

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/WZ/2024/ 655

10/07/2024 Dated:-

FIRE SAFETY CERTIFICATE

Certified that the Sarjo Devi Memorial Public School Located at Kh. No. 24/1 & 24/2, Village Nilothi, New Delhi-110041, comprised of Ground + 03 Upper Floors & earlier the School building comprised of Ground + 01 Upper Floor only, was issued Fire Safety Certificate by this department Vide Letter No. F6/DFS/MS/School/2017/98 dated 20/01/2017, owned/occupied by Sarjo Devi Memorial Public School have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and Verified by the officer concerned of Fire Service on 26/06/2024 in the presence of Sh. Rajpal Shokeen (Owner) and that the premises/building is fit for occupancy class "Educational Building" Group B with effect from 10 07 2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 10. 0.7 2024. at New Delhi by.

Tel. No. 011-23414000

Copy to: -

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi - 110054.

2. The Principal, Sarjo Devi Memorial Public School, Kh. No. 24/1 & 24/2, Village Nilothi, New Delhi-110041.

Following fire safety directives must be adhered to:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in

INSPECTION REPORT

1. Name & address of the building : Sarjo Devi Memorial Public School Located at Nilothi

Extn., Village Nilothi, Nangloi, New Delhi-110041

2. Type of Occupancy : Educational

3. Type of Case : New Case/Addition of 2nd floor & 3rd floor

4. Details of previous NOC : F6/DFS/MS/School/2017/98 dated 20/01/2017 (for

Ground + 01 Upper Floor only)

5. Fire Safety directives letter No : As per NBC (Part-IV)

6. Date of inspection : 26/06/2024

7. Name of the Inspecting Officers : Aman Kumar Lathar, ADO (JWP)

8. Name and designation of officers

from the building side : Sh. Rajpal Shokeen (Owner)

9. Year of Construction : 2011 (G+01) & 2017 (2nd & 3rd floor)

10. Applicant's letter No. : email dated 11/06/2024

S. No	Minimum Standards on fire prevention and fire safety U/R 33	NBC (Part-IV) Requirements	Provided at site	Remarks MR/NMR
1	Access to building			
	Road width	06 m	Provided	MR
	Gate width	4.5 m	Provided	MR
	Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement	of Exits		
	a. Number of staircases			
	Upper Floors	02 nos.	Provided	MR
	Basements	N/A	N/A	N/A
	b. Width of staircases			
		1.5 m each	1.5 m x 2	MR
	Upper Floors	N/A	N/A	N/A
	Basements			
	c. Protection of exits	N/A	N/A	N/A
	Fire check doorPressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	02	Provided	MR
	g. Width of Corridor	1.5 m	Provided	MR
	h. Door Size	1.2 m	Provided	MR
3	Compartmentation.	,	de legen	
A S	Fire check door	N/A	N/A	N/A
	 Sealing of electrical shafts 	N/A	N/A	N/A
	Fire Rating of shaft door	N/A	N/A	N/A
	Water Curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A

4	Smoke Management System.	19-28				
		127/4	N/A			
	Basements	N/A	N/A Natural Ventilation	N/A MR		
	• Upper floors	Required	Natural Ventilation	IVIK		
5	Fire Extinguishers		MR			
	Total numbers	10 nos.	15 nos.	CDF-SHALKER		
	Types	ABC, CO ₂ type	Provided	MR		
	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	 Length of hose reel hose 	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system					
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater PanelAlternate source of power	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
88	MOEFA	N/A	N/A	N/A		
9	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System			190		
	• Basement	N/A	N/A	N/A		
	 Upper floors 	N/A	N/A	N/A		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
1	Internal Hydrants			INA		
	Size of riser/down-comer	100 mm	Provided	MR		
	 Number of hydrants per floor 	01	Provided			
	Hose Box	Required	Provided	MR MR		
2	Yard Hydrants.					
	Total number of hydrox					
	Hose Box	N/A	N/A	N/A		
3]	Pumping Arrangements	IN/A	N/A	N/A		
	Ground Level	T				
	Discharge of main Pump		Uniquesia de Constantina de Constant			
	➤ Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	 Jockey Pump out put 	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	N/A		
		N/A	N/A	V		
1	Pump House Access	27/4	-M44	N/A		
	Terrace level	N/A	N/A	N/A		
1	Discharge of pump	450 LPM	Provided			
	Head of the pump		Provided	MR		
1		40 m	Provided	MR		

_	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	10,000 lts	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
10	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System PanelBatter backup	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	r N/A	N/A	N/A		

Note: - In the reply of the earlier shortcomings issued to vide letter no. F6/DFS/MS/\$chool/2020/45 dated 21/01/2020, the school management has submitted an affidavit that school falls under non-confirming area, so the school was not approved from MCD.

Fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view substantial compliance of the minimum standards on fire prevention and fire safety requirements under the rules, grant of Fire safety Certificate is recommended under rule 35 of the Delhi Fire service Rules 2010 under the DFS Act 2007.

Accordingly, DFA is put up for approval please.

Aman Kumar Lathar ADO (JWP)

Whigh sorry

Anyour Pro Sect