

Dated: 09/07/2024

FIRE SAFETY CERTIFICATE

Certified that Sirish Public School located at B-210, Gali No.1, Rajveer Colony Extn., Delhi – 110096 comprised of ground plus three upper floors owned/ occupied by Sirish Public School, was issued Fire Safety Certificate by this department for ground plus two upper floors vide letter No F6/DFS/MS/School/2018/NDZ/2427 dated 29.10.2018. The school building was re-inspected by the officer concerned of this department on 02/07/2024 in presence of Mr. Saurabh Srivastava (Manager) of the school and found that the school building on ground plus two upper floors have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. 262 - 362 dated 17/01/2005 and the school GF+FF+SF is fit for occupancy class "Educational Building" (Group - B) for Ground+ Two Upper floors with effect from 09/07/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS Rules, 2010. Subject to conditions, printed overleaf.

Issued on 09 07 2024 at New Delhi by.

DIRECTOR

© CDELHI FIRE SERVICE

Copy to: -

- 1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi 110051.
- 2. The Principal, Sirish Public School located at B-210, Gali No.1, Rajveer Colony Extn., Delhi 110096.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

N/13

| | | | INSPEC | TION REPORT | r | | |
|----|-------------------|---|--|---|---------------------------|-------------------|--|
| | | Nar | ne & address of the building | Sirish Public School located at B-210, Gali No.1, Rajveer Colony Extn., Delhi – 110096. | | | |
| 2 | | Bui | lding is comprised of | | | | |
| | | Tyr | pe of occupancy | G + 3 (School is running on G+2 upper floor only) | | | |
| Ì | | Type of case | | Educational Building | | | |
| ; | | | ails of previous FSC | Renewal | | | |
| | | | | 29/10/2018 | | | |
| 5 | | | e safety directives letter no. | Circular Director of Education dated 17/01/2005 | | | |
| 1 | | Dat | te of inspection | 02/07/2024 | | | |
| 3 | | Naı | me of the inspecting officers | Yashwant Singh Meena ADO (L.N) | | | |
| 9 | | | me of the designation of officer me the building side | Mr. Saurabh Srivastava (Manager) | | | |
| 10 | | Ye | ar of construction | 1998 | | | |
| 11 | | Ap | plicant's letter no. | Outdoor dairy no. 3171 dated 20/06/2024 | | | |
| S | N | | Minimum standard of fire revention and fire safety U/R | Circular Requirement | Provided at site | Remarks MR/NMR | |
| 1 | | Ac | cess to Building: | | | | |
| 1 | | A | Road width | 6.0 mtrs. | 6.0 mtrs. | MR | |
| 1 | | В | Gate width | N/A | N/A | N/A | |
| 1 | | C | Width of internal road | N/A | N/A | N/A | |
| 2 | | Number, Width, Type and Arrangement of Exits: | | | | | |
| 1 | _ | A | Number of staircases | gement of Lines. | | r eyt | |
| 1 | | A | | 02 | 02 nos. | MR | |
| 1 | | | a Upper floor b Basement | 02 no. N/A | N/A | N/A | |
| 1 | | | | IVA | IVA | 17/11 | |
| 1 | | В | Width of staircases a Upper floor | 1.5 mtrs. | 0.75 mtrs. & 0.90 mtrs | MR | |
| 1 | | | b Basement | N/A | N/A | N/A | |
| ı | | C | Protection of exits | | 79 | | |
| 1 | | | a Fire check door | N/A | N/A | N/A | |
| ı | | | b Pressurization | N/A | N/A | N/A | |
| | | D | No. of continuous staircases to terrace | 01 no. | 01 no. | MR | |
| ı | | E | Width of corridor | 1.25 mtrs. | 1.25 mtrs. | MR | |
| | | F | Door size | 1.0 mtr. | 1.0 mtr. / | MR | |
| \$ | Compartmentation: | | | | | | |
| r | | A | Fire check door | NA | NA | NA | |
| l | | В | Sealing of electrical shafts | N/A | N/A | N/A | |
| | | C | Fire rating of shaft door | N/A | N/A | N/A | |
| | | D | Water curtain | N/A | N/A | N/A | |
| | | E | Fire dampers | N/A | N/A | N/A | |
| 4 | _ | 7.55 | noke Management System: | 5 | | - | |
| | | A | Basement | N/A | N/A | N/A | |
| | | 1 | | N/A | N/A | | |

Sirish Public School located at B-210, Gali No.1, Rajveer Colony Extn., Delhi – 110096.

| 5. | Fire | Extinguisher: | | 06 nos. | MR | | |
|-----------|---|-------------------------------|-----------------------|-----------------------|-------------|--|--|
| | A | Total numbers | 06 nos. | CO ₂ & ABC | MR | | |
| ı | В | Types | CO ₂ & ABC | | MR | | |
| ł | C | ISI marking | ISI Marked | Provided | / | | |
| 5 | Eint Aid Hose Reel: | | | | | | |
| | A | Total numbers of each floor | 01 no. | Provided ' | MR MR | | |
| | B | Length of hose reel hose | 30 mtr. | Provided | | | |
| | C | Nozzle diameter | 05 mm | Provided | MR | | |
| 7 | Automatic Fire Detection and Alarming System: | | | | | | |
| | A | Type of detectors | N/A | N/A | N/A | | |
| | В | Location of main panel | N/A | N/A | N/A | | |
| | C | Location of repeater panel | N/A | N/A | N/A | | |
| | D | Alternate source of power | N/A | N/A | N/A | | |
| | E | Hooters | N/A | N/A | N/A | | |
| 8 | MO | DEFA: | N/A | N/A | N/A | | |
| 9 | | blic Address System: | N/A | N/A | N/A | | |
| 10 | Automatic Sprinkler System: | | | | | | |
| | A | Basement | N/A | N/A | N/A | | |
| | В | Upper floor | N/A | N/A | N/A | | |
| | C | Sprinkler above false ceiling | N/A | N/A | N/A | | |
| 11 | C Spinisher work times | | | | | | |
| 4. | A | Size of riser/down-comer | 100 mm | Provided | MR | | |
| | B | Number of hydrants per floor | 01 no | Provided | MR | | |
| | C | Hose box | 01 no | Provided | MR | | |
| 12 | | | | | | | |
| 12 | A | Total number of hydrants | N/A | N/A | N/A | | |
| | B | Hose box | N/A | N/A | | | |
| 13 | - | | IN/A | IN/A | N/A | | |
| Cale | | | | | | | |
| 1 | - | Ground level | 27/4 | | 1 2 3 3 3 3 | | |
| | A | Discharge of main pump | N/A | N/A | N/A | | |
| | B | Head of main pump | N/A | N/A | N/A | | |
| | C | Number of main pumps | N/A | N/A | N/A | | |
| | D | Jockey pump out put | N/A | N/A | N/A | | |
| | E | Jockey pump head | N/A | N/A | N/A | | |
| | F | Standby pump out put | N/A | N/A | N/A | | |
| | G | Standby pump head | N/A | N/A | N/A | | |
| | H | stopping | N/A | N/A | N/A | | |
| | I | Pump house access | N/A | N/A | N/A | | |
| 2 | Terrace Level | | | | | | |
| | A | Discharge of pump | 450 LPM | Provided | MR | | |
| | B | Head of the pump | 40 m | Provided | MR | | |
| | C | Power supply | Required | Provided | MR | | |
| 6 | D | Auto starting of pump | Required | Provided | MR | | |

NIIE

| 1 | |
|--|---------|
| Sirish Public School located at B-210, Gali No.1, Rajveer Colony Extn., Delhi - | 110096. |
| The state of the s | ** |

| 14 | Captive Water Storage for Fire Fighting: | | | | | |
|-----|---|--------------|-----------|--------------|--|--|
| - | A Underground tank capaci | ity N/A | N/A | N/A | | |
| - 1 | B Draw-off connection | N/A | N/A | N/A | | |
| ŀ | C Fire service inlet | N/A | N/A | N/A | | |
| ŀ | D Access to tank | N/A | N/A | N/A | | |
| ŀ | E Overhead tank capacity | 5000 liters. | Provided. | MR | | |
| 15 | Exit Signage: | N/A | Provided | MR | | |
| 16 | Provision of Lifts: | | | | | |
| - | A Pressurization of lift shaf | N/A | N/A | N/A · N/A | | |
| | B Pressurization of lift lobb | | N/A | N/A | | |
| } | C Communication in lift car | | N/A | N/A | | |
| | D Firemen's grounding swit | | N/A | N/A | | |
| 1 | E Lift signage | N/A | N/A | N/A | | |
| 17 | Standby Power Supply: | N/A | N/A | N/A | | |
| 18 | Defuge Areas | | | | | |
| 10 | A Total area | N/A | N/A | N/A N/A | | |
| | B Location | N/A | N/A | IN/A | | |
| 19 | Fire Control Room: | | | | | |
| | A Detector system panel | N/A | N/A | N/A N/A | | |
| | B Flow switch panel | N/A | N/A | N/A | | |
| | C PA system panel | N/A | N/A | N/A | | |
| | D Battery backup | N/A | N/A | N/A | | |
| | E Building floor plans | N/A | N/A | N/A | | |
| 20 | Special Fire Protection system protection of special Risks, if | ms for N/A | N/A | N/A | | |

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the compliance of minimum standards of fire prevention and fire safety measures required as per Circular No. 262-362 dated 17/01/2005, under the rules the FSC issued vide letter no. F6/DFS/MS/School/2018/NDZ/2427 dated 29/10/2018, renewal under Rule 35 of the Delhi Fire Service Rules 2010, is recommended to be renewed.

No file is pending with me before disposal of this case.

03/7/2024

i

£

if

iz

'io

Signature of the Inspecting Officer Name Yashwant Singh Meena Designation ADO (L.N)