

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6 / DFS / MS / 2024 /School/WZ/ 682

16/07/2024 Dated

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Sr. Sec. School located at Anandwas, Shakurpur, Delhi-110034 comprised of Ground and First floor was issued FSC by this department vide letter No F6 /DFS/MS/School/WZ/2021/209 dated 11.03.2021. The premises was re-inspected by the officer concerned of this department on 10.07.2024 in the presence of Smt. Pramila Joshi (H.O.S.), and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from 16.10.71.2024 for a period of three years, subject to compliance of the conditions mentioned below:

Issued on16.07.12.24 at New Delhi by

Director

Ph. 011-23414000

Copy to:-

1. The Director, Education, Government of NCT of Delhi. Old Sect. Delhi-110054

2. The Principal, Govt. Girls Sr. Sec. School located at Anandwas Shakurpur, Delhi-110034.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized

construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

WWW.dfs.Delhigovt.nic.in 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

9. Electrical Panel and electric meter under the staircase must be removed within a period of three months from the date of issuance of the Fire Safety Certificate. Failing to do so the Fire Safety Certificate will be null and void.

INSPECTION REPORT Govt. Girls Sr. Sec. School located at Anandwas, Shakurpur, Delhi-34.

Educational

Ground plus first floor

1. Name & address of the building:
2. Type of Occupancy
3. Building Comprised of:
4. Type of Case
5. Details of Previous NOC:
6. Fire Safety directives letter No:
7. Date of inspection Renewal F6/DFS/MS/School/WZ/2021/209 dated 11/03/2021 DOE circular No. 3298-3398 dated 01/03/2011

10/07/2024 7. Date of inspection

8. Name of Inspecting Officer9. Name and designation of officers R.K.Sinha, ADO (BW)

Smt. Pramila Joshi (H.O.S.) From the building side

S. No.	Minimum Stand		DOE	Provided at site	Remarks MR/NMR		
1.	Access to building	ire safety U/R 33	Requirement		MINIMIN		
	Road wid		6 m	Provided	MR		
	Gate wid	NAME OF TAXABLE PARTY.	4.5 m	Directly Accessible	MR		
	Width of		NA	NA	NA		
2.	Number, Width Type & Arrangement of Exits						
	a. Number of sta	rcases					
	 Upper F 	oors	02	Provided	MR		
	Basemer	nts	NA	NA	NA		
	b. Width of stairs	ases		Swe170.0/22	U shille-side stab		
	 Upper F 	loor	1.50 m each	1.41 m & 1.44 m	MR(old case)		
	Basemer		NA	NA	NA		
	c. Protection of e	xits	F1036265	5.05.8	4.34.4		
	Fire che	k door	NA	NA	NA		
	Pressuri		NA	NA	NA NA		
	d. No. of contin		NA	NA	NA NA		
	e. Width of Cor	ridor	1.5 m	Provided	MR		
	f. Door Size	-	1 m	Provided	MR		
3.	Compartmentat	ion					
	Fire chec	k door	NA	NA	NA		
	Sealing of	f electrical shafts	NA	NA			
		ng of shaft door	NA		NA		
	Water Cu		NA NA	NA NA	NA		
	Fire Dam		NA ·	NA NA	NA		
1.	Smoke Manager		2322	NA .	NA		
-							
				NA	NA		
	Upper flo	ors	Required	Naturally Ventilated	MR		
5.	Fire Extinguishe						
	Total nur	nbers	05 Nos.	Provided	MR		
	 Types 		ABC/ CO2 Type	Provided	MR		
	IS marki		Required	Provided	MR		
6.	First-Aid Hose l	Reels	1		1711		
		nbers on each floor	NA	NA	NA NA		
		f hose reel hose	NA	NA	NA		
	Nozzle d	ameter	NA	NA	NA		
7.	Automatic fire detection and alarming system						
/		etectors	NA	NA	NA		
	Location	of Main Panel	NA	NA			
		of Repeater Panel	NA	NA NA	NA		
	Alternate	source of power	NA	NA NA	NA		
				INA	NA		
		Location	NA				

		N-2	NTA.	Jetechar Flow Sw			
	MOEFA	NA	NA NA	7			
	Public Address System	NA	NA	.,			
0.	Automatic Sprinkler System						
_			NA	NA			
	Basement	NA	NA NA	NA			
	Ground Floor	NA	NA NA	NA			
	Sprinkler above false ceiling	NA	IVA	_			
11.	Internal Hydrants						
	Size of riser/down-comer	NA	NÁ	NA			
	Number of hydrants per floor	NA	NA	NA			
	Hose Box	NA	NA	NA			
12.	Yard Hydrants						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA NA	NA NA	NA			
13.	Pumping Arrangements	NA	IVA				
11.50 N	1 umping Arrangements						
	Ground Level						
	Discharge of main Pump	NA	NA	NA			
	➤ Head of Main pump	NA	NA	NA			
	> Number of main pumps	NA	NA	NA			
	> Jockey Pump out put	NA	NA	NA			
	> Jockey pump head	NA	NA	NA			
	> Standby Pump out put	NA	NA	NA			
	➤ Standby Pump Head	NA	NA	NA			
	➤ Auto Starting/Manual Stopping	NA	NA	NA			
è	> Pump House Access	NA	NA	NA			
	Terrace level						
	➢ Discharge of pump	NA	NA	NA			
	➤ Head of the pump	ŇA	NA	NA NA			
	➢ Power Supply	NA	NA	NA			
- CONTRACT	➤ Auto Starting of pump	NA	NA	NA			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	NA	NA	NA			
	➤ Draw-off connection	NA	NA	NA			
	> Fire service inlet	NA	NA	NA			
	➤ Access to tank	NA	NA :	NA			
	Overhead Tank capacity	NA	NA	NA			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.						
	Pressurization of Lift Shaft	NA	NA	NA			
	Pressurization of Lift lobby	NA	' NA	NA			
	Communication In lift Car	NA	NA	NA NA			
	Fireman's Grounding Switch	NA	NA	NA			
	Lift Signage	NA	NA				
17.	Standby power supply	NA	NA NA	NA NA			
18.	Refuge Area.						
	> Total Area > Location	NA NA	NA NA	NA			
	Location	INV	NA	NA			

			7.
	NA	NA	NA
System Panel	NA	NA	NA
Switch Panel	NA NA	NA	NA
PA System Panel	NA NA	NA	NA
Battery backup		NA	NA
Building Floor Plans	NA		NA
Special Fire Protection System for Protection of special Risks, if any:	NA	NA	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: Electric meter and electrical panel installed under the staircase has to be removed to a

De Cho low

Keeping in view of deemed compliance of the minimum standards of fire prevention and safer place fire safety measures as required under DOE circular no. 3298-3398 dated 01/03/2011, it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DFS/M\$/School/WZ/2021/209 dated 11/03/2021.

> Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.