

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6 / DFS / MS / 2024 /WZ/EH 223

FIRE SAFETY CERTIFICATE

Dated 15/07/2024

Certified that M/s AT MOSPHERE Restaurant located at Shop No. 201 to 206, 2nd Floor, PP City Centre, Plot No. 3, Road No. 44, Pitampura, Delhi-110034 is running at Second Floor in a building comprised of (Two Basements, Ground plus Seven Upper Floors) have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 08.07.2024 in the presence of Sh. Pushpender Singh and found that the building/ premises is fit for occupancy "Assembly" (Group D) Eating House with effect from 15 07 2074 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on ... 1.5. 1.9.7.1.2.2.4... at New Delhi by

Director Ph-011-23414000

Copy to:-

- The Owner/ Occupier, M/s AT MOSPHERE Restaurant located at Shop No. 201 to 206, 2nd Floor, PP City Centre, Plot No. 3, Road No. 44, Pitampura, Delhi-110034.
- 2. MHA Portal ID No. 2024070110183.

Conditions for the validity of Fire Safety Certificate:

1. Fire Safety Certificate is valid for Second Floor only.

2. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

3. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

5. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

6. This certificate cannot be treated in any case for regularizations of unauthorized construction.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA portal (https://www.delehlhlic.gov.in) along with a copy of this Certificate, six months prior to its expiry".

8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.Delhigovt.nic.in

9. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT 1. Name & address of the building :

M/s AT MOSPHERE Restaurant located at Shop No. 201 to 206,

2nd Floor, PP City Centre, Plot No. 3, Road No. 44, Pitampura,

Delhi- 110034.

2. Type of Occupancy Assembly 3. Type of Case
4. Details of Previous NOC
5. Fire Safety directives letter No New Case Nil

NBC Part- IV/ UBBL

08/07/2024

6. Date of inspection :
7. Name of Inspecting Officer :
8. Name and designation of officers R.K.Sinha, ADO (BW)

From the building side Sh. Pushpender Singh • 9. Year of Construction : 2019 as per MHA portal

: MHA Portal ID No. 2024070110183 dated 01/07/2024 10. Applicant's letter No.

6/D	FS/MS/WZ/2 Minimum Sta	D22/433 dated 29/09/ andards on fire	NBC Part IV/	Provided at site	Remarks MR/NMR			
lo.		d fire safety U/R 33	UBBL	E6/DES/MS/W7/202				
•	Access to building [Shopping Mall issued FSC vide letter no. F6/DFS/MS/WZ/2022/433 Dated 29/09/2022.]							
	. DI		12 m	Provided	MR			
	Road Gate	width	4.5 m	On Road	MR			
			6 m	Provided	MR			
	Width of internal road 6 m Provided Number, Width, Type & Arrangement of Exits [Provided and maintained by mall management]							
2.	Number, wittin, Type & Atlangement of Exits							
	a. Number of	staircases						
		r Floors	GF to Terrace- 02, GF to 4th Floor- 01, GF to FF- 01	Provided	MR			
	Base	ments	02 + 02 Ramps	Provided	MR			
	b. Width of st		K					
		r Floor	GF to Terrace- 1.5 m each GF to 4 th Floor- 2.5 m GF to FF- 1.5 m	Provided(old case)	MR(Old case)			
	Base	ments	1.5 m for staircase & 3 m for ramp	Provided (old case)	MR(Old case)			
	c. Protection	of exits		N N				
		check door	NA	Provided	NA			
		urization	NA	Provided	NA			
	19.10.003	tinuous staircases to	NA	Provided	NA			
	e. Width of	Corridor	1.5 m	Provided	MR			
	f. Door Size		1.5 m	Provided	MR			
			[Provided and maintained	hy Moll Monogement				
3.	Compartmen							
	Fire c	heck door	NA	Provided	NA			
	Sealing	g of electrical shafts	NA	Provided	NA			
		ating of shaft door	NA	Provided	NA			
		Curtain	NA '	Provided	NA			
		Dampers	NA	Provided	NA			
4.	Smoke Management System [Provided and Maintained by Mall Management]							
	Baser	nents	NA	Provided	NA			
	T	r floor	Required	Provided	MR			
5.	Fire Extingu	ishers						
	Total	numbers	04	06	MR			
	 Type 	3	ABC/Co2 Type	Provided	MR			
	• IS ma		Required	Provided	MR			
	First-Aid Ho		[Provided & Maintained					
		numbers on each floor	01	Provided (02)	MR			
	• Leng	h of hose reel hose	30 m	Provided	MR			
	Delin							

		N-3		7		
	9		rovided & Maintained by Mal	l Managemen		
7.	Automatic fire detection and alarmi	ng system [Pi	Provided & Maintained	MR		
	Type of detectors	Required	Provided at GF	MR		
	Location of Main Panel	Required	ALL AND DEVELOPMENT OF THE PROPERTY OF THE PRO	MR		
	Location of Repeater Panel	Required	Provided	MR		
	Alternate source of power	Required	Provided	NA		
	Alternate source of power	NA	Provided	14.		
	 Hooters' Location 	SW 1	Provided	MR		
8.	MOEFA	Required	NA	NA		
9.	Public Address System	NA		ntl		
10.	Automatic Sprinkler System		Inintained by Mall Manageme Provided	NA NA		
	Basement	NA Provinced	Provided	MR		
	Upper Floors	Required	Provided	MR		
	 Sprinkler above false ceiling 	Required		4		
11.	Internal Hydrants	[Provided & N	Maintained by Mall Manageme	MR		
	Size of riser/down-comer	150 mm	Provided	MR		
	 Number of hydrants per floor 	01	Provided (02)	MR		
	Hose Box	01	Provided(02)	IVIK		
12.	Yard Hydrants			MR		
	Total number of hydrants	Required	Provided	N. C. C. C.		
	Hose Box	Required	Provided	MR		
13.	Pumping Arrangements	[Provided & M	aintained by Mall Managemer	tj		
	Ground Level			NIA		
	Discharge of main Pump	NA	2850 lpm	NA NA		
	➤ Head of Main pump	NA	80 m	NA		
		NA	02	NA		
	> Number of main pumps	NA	2 × 180 lpm	NA NA		
	> Jockey Pump out put	NA NA	80 m			
	> Jockey pump head	NA NA	2850 lpm	NA		
	> Standby Pump out put	NA NA	80 m	NA		
	Standby Pump HeadAuto Starting/Manual	NA	Provided	NA		
	➤ Auto Starting/Manual Stopping	1,7.1		(#°		
		NA	Provided	NA		
	> Power Supply					
	Terrace level	[Provided & m	aintained by Mall Manageme	itj		
	pe of the second of the A	NA	NA	NA		
-	> Discharge of pump	NA NA	NA	NA		
	➤ Head of the pump					
H	➤ Power Supply	NA	NA	NA		
-	> Auto Starting of pump	NA	NA	NA		
	Captive Water Storage for firefighting [Provided & Maintained by Mall Management]					
	Underground tank capacity	NA	Provided (200,000 ltrs)	NA		
-	> Draw-off connection	NA	Provided	NA		
		NA	Provided	NA		
_	➤ Fire service inlet	NA NA	Provided	NA		
L	> Access to tank	20,000 ltrs	Provided	MR		
	Overhead Tank capacity	Required	Provided	MR		
1	Exit Signage.	Required	7101100			
			aintained by Mall Managemen	t]		
	Provision of Lifts.	[Provided & Ma	aintained by Man Managemen			
	- Section Control Control	•	Provided	NA		
	Pressurization of Lift Shaft	NA	Provided	NA		
	Pressurization of Lift Shaft Pressurization of Lift lobby	NA NA	Provided Provided in basement floor	NA NA		
	Pressurization of Lift Shaft	NA NA NA	Provided Provided in basement floor Provided	NA NA NA		
	Pressurization of Lift Shaft Pressurization of Lift lobby	NA NA NA	Provided Provided in basement floor Provided Provided	NA NA NA		
	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch 	NA NA NA	Provided Provided in basement floor Provided Provided Provided Provided	NA NA NA NA		
. I	Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch	NA NA NA	Provided Provided in basement floor Provided Provided	NA NA NA		
S	Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage standby power supply	NA NA NA NA	Provided Provided in basement floor Provided Provided Provided Provided	NA NA NA NA		
S	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	NA NA NA NA	Provided Provided in basement floor Provided Provided Provided Provided	NA NA NA NA		

Tana	N-4					
	Location	NA	6th Floor	NA.		
16.	Fire Control Room	Control Room [Provided & Maintained by Mall Management]				
1	Detector System Panel	NA	Provided	NA		
1	Flow Switch Panel	NA	Provided	NA		
1	PA System Panel	NA	Provided	NA		
	Battery backup	NA	Provided	NA		
	Bui ding Floor Plans	NA	Provided	NA		
20.	Special Fire Protection System for Protection of special Risks, if any:	Co2 flooding for HT & LT Panel	Provided	MR		

The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection.

Keeping in view of satisfactory compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

> Signature of Inspecting Officer Name: Rajeev Kumar Sinha

Designation: ADO/B.W.

Delfolor

Being new case reinspect & put its according

to postde ty mall and mall his