

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTER: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/School/WZ/2024/ 186

Dated:- 18 07 2024

FIRE SAFETY CERTIFICATE

Certified that the James Convent School, Located at F-34/2 & 3 Satsang Road, Nihal Vihar, Nangloi, Delhi-110041, comprised of Ground + 01 Upper Floors only owned/occupied by the James Convent School, was issued Fire Safety Certificate by this department Vide Letter No. F6/DFS/MS/School/2021/WZ/361 dated 06/05/2021. The said premises was re-inspected by the officer concerned of this department on 03/07/2024 in the presence of Ms. Sangita Chamola and found that the premises/building have deemed complied with the fire prevention and fire safety requirements in accordance D.O.E. Cr. No. 262-362 dated 17/01/2005 and that the premises/building is fit for occupancy class "Educational Building" Group B with effect from 18/07/2024 for a period of three years, subject to compliance of the conditions, printed below.

Issued on .. 18 07 2024. at New Delhi by.

Director Tel No. 011-23414000

Copy to: -

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi - 110054.

2. The Principal, James Convent School, F-34/2 & 3 Satsang Road, Nihal Vihar, Nangloi, Delhi-110041.

Following fire safety directives must be adhered to:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.

5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.

6. All comments / directions of licensing Department shall always be permitted and followed.

7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name and address of the building: James Convent School, located at F-43/2 & 3

Satsang Road, Nihal Vihar, Nangloi, Delhi-

110041.

2. Type of Occupancy

: Educational, (G + 01 Upper Floors)

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/School/2021/WZ/361 Dated 06/05/2021

5. Fire Safety directives Letter No. : D.O.E Circular no.262-362 dated 17/01/2005

6. Date of inspection

: 03/07/2024

7. Name of the Inspecting Officer

: Aman Kumar Lathar, ADO (JWP)

8. Name and designation of Officer

from the building side

: Ms. Sangita Chamola

9. Year of Construction

: 2001

10. Applicant's letter No.

: email dated 24/06/2024

S No	Minimum standards on fire prevention and fire safety U/R 33	D.O.E. Circular No 262-362 Dated 17/01/2005/ as per dated 06/05/2021	site	MR/NMF
1.	Access of building	· · · · · · · · · · · · · · · · · · ·	Provided	MR
	 Road width 	Accessible	Provided	MR
	Gate widthWidth of internal road	Accessible NA	NA	NA
2	Number, width, Type & Arrangem	nents of exits		
2.	a. Number of staircases		1 1 1 1 1	MR
	 Upper floors Basements Width of staircases Upper floors 	02 nos.	03 nos.	
		NA	NA	NA
		1.5 m each 1	.65 m x 1, 1.56 n & 1.42 m x 1	
		NA	NA	NA
	Basements Savita			
	c. Protection of exits	NA	NA	NA
	Fire check door	NA NA	NA	NA
	Pressurization No of continuous	01	Provided	MR
	staircase to terrace	1.5 m	Provided	MR
	e. Width Of Corridor	1.0 m	Provided	MR
	f. Door Size	1.0 111	NA	
3.	Compartmentation	NA	NA	NA
	 Fire check door Sealing of electrical shafts 	NA	NA	NA
		NA	NA	NA
	• Fire Rating of shaft door	NA NA	NA	NA
	Water Curtain Democre	NA NA	NA	NA
	• Fire Dampers Smoke managements System			NA NA
4.		NA	NA	NA NA
	BasementsUpper floors	NA	NA	INA

				×
	Fire Exting 1.1			MR
	Fire Extinguishers	00	10 nos.	MR
	• Total numbers	08 nos. ABC & CO ₂	Provided	MR
	• Types	ISI marked	Provided	
	• ISI marking	ISI marked		MR
-	First – Aid Hose Reels	01	Provided	MR
	 Total numbers on each floor 	30 m	Provided	MR
-	 Length of hose reel hose 	05 mm	Provided	A A A S
	 Nozzle diameter 		73 TE 1	I NA
	Automatic fire detection and alarmin	g system	NA	NA NA
	 Type of detectors 	NA NA	NA	NA NA
	 Location of Main Panel 	NA NA	NA .	NA NA
	 Location of Repeater Panel 	NA	NA	
	 Alternate source of power 	NA	NA	NA
	Hooters' Location	NA	NA	NA
	MOEFA	NA	NA NA	NA
).	Public Address System	NA	NA NA	Pi.
0.	Automatic Sprinkler System	100	T NA	NA
-	Basements	NA	NA NA	NA
	Upper Floor	NA	NA NA	NA
		NA	NA	
1	Sprinkler above false ceiling Internal Hydrants:			MR
1.	Internal Hydrants:	100 mm	Provided	
	Size of riser/down-comer		NA	NA NA
	Number of hydrants per floor	NA	NA	NA
	Hose Box			
12.	Yard Hydrants	NA	NA	NA
	 Total number of hydrants 	NA	NA	NA
	Hose Box	TAZ.		
13.	Pumping Arrangements:			
	Ground Level	NA	NA	NA
	 Discharge of main pump 		NA NA	NA
	Head of main pump	NA NA	NA NA	NA
	Number of main pumps	NA NA	NA NA	NA
	Jockey pump out put	NA	NA NA	NA
	Jockey pump head	NA	NA NA	NA
	> Standby Pump out put	NA		NA
	> Standby Pump Head	NA	NA NA	
	> Auto Staring/Manual	NA	NA I	NA
	stopping	274		
	> Pump House Access	NA	NA	NA
	Terrace level			
	> Discharge of pump	450 lpm	Provided	MR
	> Head of the pump	40 m	Provided	MR
	> Power supply	Required	Provided	MR
	> Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	 Under ground tank capacity 	NA NA	NA	NA
	Draw off connection	NA	NA	NA
	> Fire service inlet	NA	NA	NA
	Access to tank	NA	NA	NA
	 Overhead Tank capacity 	2,500 ltrs.	Provided	MR
15	Exit Signage	Required	Provided	
16.	Provision of Lifts	4 2	1	MR
. γ.	> Pressurization of Lift Shaft	No. 200		
	Pressurization of lift lobby	NA NA	NA NA	NA
	➤ Communication in lift Car	NA	NA	NA
	Fireman's Grounding Switch	n NA	NA	NA
	➤ Lift Signage	NA NA	NA NA	NA
	policy and the state of the sta	INA	NA	NA
17.	Standby power supply	NA	NA	NA

NA	NA	NA		
NA	NA	NA		
Fire control room				
NA	EU-12 U	NA		
NA	NA	NA		
NA	NA	NA		
	NA	NA		
	NA	NA		
NA	NA	NA		
	NA NA NA NA NA NA NA	NA		

Fire protection systems provided in the building were checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety, requirements as per D.O.E. Circular no. 3298-3398 dated 01.03.2011, letter vide issued Certificate Fire Safety renewal of F6/DFS/MS/School/2021/WZ/361 Dated 06/05/2021 is recommended.

Accordingly DFA is prepared for approval & signature please.

DOGO(WZ)

ADO (JWP)

FT. Letter is added for your signature pol.