

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/School/2024/WZ/684

Dated: 18 07 2024

FIRE SÁFETY CERTIFICATE

Certified that the Parkash Bharti Public School St. Block, Prem Nagar-II, Durga, Mandir Road Near Kirari, Delhi-110086, comprised of Ground + Two upper floor has already been issued FSC by this department vide letter No. F.6/DFS/MS/School/2021/WZ/678 dated 31.08.2021. The premises was re-inspected by the officer concerned of this department on 05.07.2024 in the presence of Mr. Sandeep Kumar (Chairman) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 18.10712024 at New Delhi by

Ph; 011-23414000

ol c

Copy to :-

- 1. The Principal, Parkash Bharti Public School St. Block, Prem Nagar-II, Durga, Mandir Road Near Kirari, Delhi-110086.
- 2. The director of Education, Old Secretariat, Delhi.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner/ occupier shall submit a declaration every year in Form 'K'[sub rule (2) of Rule 38] provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction (Clause 2.9.2 of UBBL-2016) or Alteration

(Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of Rule 37] along with a copy of this Certificate, six months prior to its expiry."

		INSPEC	TION REPORT				
1. Name	& address of the building			1 1 0 2 1 =			
		Parkash Bharti Public School St. Block, Prem Nagar-II, Durga Mandir Road Near Kirari, Delhi-110086.					
2. Type	of Occupancy	Educational					
3. Type	ls of Previous NOC	Renewal (Ground+ 02 upper floors)					
	Safety directives letter No	F.6/DFS/MS/School/2021/WZ/678 dated 31.08.2021. NBC Part-IV					
	7)		05.07.2024.				
0 17 111			Ajay Kumar Sharma (ADO Rohini)				
	the building side	Mr. San	deep Kumar (Chai	rman)			
9. Year	of Construction	2005, 2011 & 2015.					
10. Appl	0 20 00 00 00 00		.2615 dated 07.06.2024.				
	imum Standards on fire prev	NBC	Provided at site	Remarks			
	fire safety U/R 33		Requirement		MR/NMR		
I. Acc	ess to building						
	Road width		Accessible	Accessible	MR		
	Gate width		Accessible	Accessible	MR		
1	Width of internal road		-NA-	-NA-	·-NA-		
2. Nur	A THE PROPERTY OF THE OWNER OF THE PROPERTY OF	rement of	740 April 10				
1.000	Number, Width, Type & Arrangement of Exits a. Number of staircases						
a. 1	The Control of the Co		03nos.	03nos.	MR		
	Upper Floors		-NA-	-NA-	-NA-		
	Basements		-INA-	1771			
b. V	b. Width of staircases		1.5m	1.89, 1.59 & 1.20m	MR(Old cas		
	Upper Floor				-NA-		
	Basements		-NA-	-NA-	-NA-		
c.	c. Protection of exits			7 274	N/A		
	Fire check door		-NA-	-NA-	-NA-		
	Pressurization		-NA-	-NA-	-NA-		
d. I	d. No. of continuous staircases to terrace		-NA-	-NA-	-NA-		
e. Y	e. Width of Corridor		-NA-	-NA-	-NA-		
f. 1	f. Door Size		-NA-	-NA-	-NA-		
3. Co	mpartmentation						
	Fire check door		-NA-	-NA-	-NA-		
	Sealing of electrical shafts		-NA-	-NA-	-NA-		
	Fire Rating of shaft door		-NA-	-NA-	-NA-		
	Water Curtain		-NA-	-NA-	-NA-		
	Fire Dampers		-NA-	-NA-	-NA-		
4. Sm	oke Management System		- 4				
7. 511	a) Basements		-NA-	-NA-	-NA-		
	b) Upper floors		-NA-	-NA-	-NA-		
E 177							
5. Fir	Fire Extinguishers • Total numbers		12nos.	14nos.	MR		
			ABC/CO2	ABC-14nos.	MR		
	• Types		ISI marked	Yes	MR		
	IS marking	_		1			
6. Fir	First-Aid Hose Reels		03nos.	Provided	MR		
	Total numbers on each floor		30mm	Provided	MR		
	 Length of hose reel hose 		John	E # 70 - # 70	-		

CAN F

		20	Provided	MR		
\top	Length of hose reel hose	30mm	Provided	MR		
H	Nozzle diameter	5m				
+	Automatic fire detection and alarming system	n	-NA-	-NA-		
	a) Type of detectors	-1421	-NA-	-NA-		
ŀ	b) Location of Main Panel	-NA-	-NA-	-NA-		
1	c) Location of Repeater Panel	-NA-	-NA-	-NA-		
_	d) Alternate source of power	-NA-	-NA-	-NA-		
ŀ	e) Hooters' Location	-NA-	-NA-	-NA-		
3.	MOEFA	-NA-	-NA-	-NA-		
).	Public Address System	-NA-		*		
0.	Automatic Sprinkler System	-NA-	-NA-	-NA-		
	Basement	-NA-	-NA-	-NA-		
	Ground & Upper Floors		-NA-	-NA-		
	Sprinkler above false ceiling	-NA-	111.			
11.	Internal Hydrants	774	-NA-	-NA-		
	Size of riser/down-comer	-NA-	-NA-	-NA-		
	Number of hydrants per floor	-NA-	-NA-	-NA-		
	Hose Box	-NA-	-IVA-	150765		
12.	Yard Hydrants		-NA-	-NA-		
	Total number of hydrants	-NA-	-NA-	-NA-		
	Hose Box	-NA-	-IVA-			
13.	Pumping Arrangements	NY 1	-NA-	-NA-		
	Ground Level	-NA-	-NA-	-NA-		
	> Discharge of main Pump	-NA-	-NA-	-NA-		
	> Head of Main pump	-NA-	-NA-	-NA-		
	> Number of main pumps	-NA-	-NA-	-NA-		
	> Jockey Pump out put	-NA-	-NA-	-NA-		
	Jockey pump headStandby Pump out put	-NA-	-NA-	-NA-		
	> Standby Pump Head	-NA-	-NA-	-NA-		
	> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-		
	> Pump House Access	-NA-	-NA-	-NA-		
	Terrace level	-11/1-	101			
	- Table 200 (2010)	450lpm	450lpm	MR		
14.	Discharge of pumpHead of the pump	430ipin 40m	40m	MR		
	> Power Supply	Required	Provided	MR		
			Provided	MR		
	and the second s					
17		NT A	-NA-	-NA-		
	Underground tank capacity	-NA-	W 1999	2 2 2		
	> Draw-off connection	-NA-	-NA-	-NA-		
	> Fire service inlet	-NA-	-NA-	-NA-		
	> Access to tank	-NA-	-NA-	-NA-		
	Overhead Tank capacity	-NA-	-NA-	-NA-		
15		10,000ltr	10,000ltr	MR		
16	. Provision of Lifts.	*	20070777	1744		
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-		
	Pressurization of Lift lobby	-NA-	-NA-			
	Communication In lift Car		90.000	-NA		
-	• Communication in lift Car	-NA-	-NA-	-N.		
	TVI S	V./				

Shy to

MA	•	Lift Signage	-NA-	-NA-	-NA-
Va	Standy	lby power supply	-NA-		
18.	Defende Area		-INA-	-NA-	-NA-
10.	A	Total Area	1		190
	>	Location	-NA-	-NA-	-NA-
19.			-NA-	-NA-	-NA-
	•	Detector System Panel	NIA [
	•	Flow Switch Panel	-NA-	-NA-	-NA
	•	PA System Panel	-NA-	-NA-	-NA
	-		-NA-	-NA-	-NA-
	==2	Battery backup	-NA-	-NA-	-NA-
	•	Building Floor Plans	-NA-	-NA-	-NA
20.	Specia Protect	Fire Protection System for tion of special Risks, if any:	-NA-	-NA-	-NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/School/2021/WZ/678 dated 31.08.2021 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

Signature of the Inspecting Officer
Name Ajay Kumar Sharma

Ajay Kumar Sharma Designation ADO(Rohini)

La lake

10/2

Preeter Mys

Any fotus

G-T letter to put up for and signature please.

Discely Holly

for kind penual

hy 15/7/24