GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2024/School/WZ/699

Dated: 23/07/2024

FIRE SAFETY CERTIFICATE

Certified that the N. K. Bagrodia Public School (Nursery School building) located at Plot No. 2, Sector-25, Rohini, Delhi-110085 comprised of ground and 01 upper floors owned/ occupied by the N.K. Bagrodia Public School was issued fire safety certificate vide this office letter no. F.6/DFS/MS/2021/School/WZ/473 dated 13.07.2021. The premises was re-inspected by the officer and observed that the school have deemed complied with the fire prevention and safety requirements in accordance with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and verified by the officer concerned of Fire Service on 10.07.2021 in the presence of Mrs. Kavita Sareen (In-charge) and that the building/premises is fit for occupancy Group B Educational for ground and first floor only with effect from 23107/2024 for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 23/07/2024. at New Delhi

(Aful Garg)^V DIRECTOR Ph; 011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 54.

2. The Principal, N.K. Bagrodia Public School, Plot No. 2 Sector-25, Rohini, Delhi-110085.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

-	V	_	

-

	7.7	INSPEC	TION REPORT				
	Name & address of the building	N.K. Ba	agrodia Public Scho	ool, Plot No. 2 Sector-25	, Rohini, Delh		
2.	Type of Occupancy	Educati					
	Type of Case	Renewa	(Ground + 01 upp	per floor)			
	Details of Previous NOC	F.6/DF	DFS/MS/2021/School/WZ/473 dated 13.07.2021				
	Fire Safety directives letter No	Directo	r of Education Cir.	dated 01.03.2011.			
	Date of inspection	10.07.2	024	024			
	Name of Inspecting Officer		ay Kumar Sharma (ADO Rohini)				
	Name and designation of officers From the building side	Mrs. Ka	avita Sareen (In-cha	arge)			
	Year of Construction	2003					
	Applicant's letter No.		.3071 dated 18.06.2	2024. Provided at site	Remarks		
S.	Minimum Standards on fire pre-	vention	Cir. of Director	Provided at site	MR/NMR		
oV	and fire safety U/R 33	1	of Education				
	Access to building			Accessible	MR		
	 Road width 	-	Accessible	A STANSON MEDICAL CO.	MR		
	Gate width		Accessible	Accessible	-NA-		
	Width of internal road		-NA-	-NA-	-IAIA		
	Number, Width, Type & Arrang	ement of	Exits				
	a. Number of staircases				MR		
	Upper Floors		02nos.	02nos.			
	Basements		-NA-	-NA-	-NA-		
	b. Width of staircases			14			
			1.5m	1.5m each	MR		
	Upper Floor	_	-NA-	-NA-	-NA-		
	Basements	يلسب	-11/4-				
		c. Protection of exits		-NA-	-NA-		
	Fire check door		-NA-	-NA-	-NA-		
	Pressurization		-NA-	***************************************	-NA-		
	d. No. of continuous staircases to terrace		-NA-	-NA-	-NA-		
	e. Width of Corridor		-NA-	-NA-			
	f. Door Size		-NA-	-NA-	-NA-		
3.	Compartmentation		12				
	a) Fire check door		-NA-	-NA-	-NA-		
	b) Sealing of electrical shafts			-NA-	-NA-		
	c) Fire Rating of shaft door		-NA-	-NA-	-NA-		
	d) Water Curtain		-NA-	-NA-	-NA-		
	e) Fire Dampers		-NA-	-NA-	-NA-		
1.	Smoke Management System						
••	a) Basements		-NA-	-NA-	-NA-		
	b) Upper floors		12 a/c per hour	Natural ventilated	MR		
			1				
5.	Fire Extinguishers		05nos.	06nos.	MR		
	a) Total numbers		ABC/CO2	ABC-06nos.	MR		
	b) Types		ISI marked	Yes			
	c) IS marking		151 marked	I CS	MR		
	First-Aid Hose Reels		01nos.	Daniel 1	3.00		
	a) Total numbers on each floor		200000000	Provided	MR		
	b) Length of hose reel hose		30mm	Provided	MR		
	c) Nozzle diameter		5m	Provided	MR		
1.	Automatic fire detection and al	arming sy	stem	-6			
	a) Type of detectors		-NA-	-NA-	-NA-		
	b) Location of Main Panel		-NA-	-NA-	-NA-		
	0) 2004		ny k				

N		ی
---	--	---

		N-13		1		
		-NA-	-NA-	-NA		
	c) Location of Repeater Panel		-NA-	-NA		
-	d) Alternate source of power	V 440 143 445	-NA-	-NA		
-	e) Hooters' Location			-NA		
, h		2000 a	7/35	-NA		
3. N	Public Address System	-NA-	-NA-	-1474		
). F	Automotic Sprinkler System			-NA-		
0. A	Automatic Springer	-NA-		139000000000		
-	a) Basement	-NA-	UEAS -	-NA-		
_	b) Ground & Upper Floors c) Sprinkler above false ceiling l. Internal Hydrants a) Size of riser/down-comer b) Number of hydrants per floor c) Hose Box l. Yard Hydrants a) Total number of hydrants b) Hose Box l. Pumping Arrangements • Ground Level > Discharge of main Pump > Head of Main pump > Number of main pumps > Number of main pumps > Jockey Pump out put > Jockey Pump out put > Standby Pump out put -NA- -N	-NA-				
11. I	Internal Hydrants	-NA-	-NA-	-NA-		
	a) Size of riser/down-conter	-NA-	-NA-	-NA-		
		-NA-	-NA-	-NA-		
12.	Yard Hydrants	-NA-	-NA-	-NA-		
		17517267857		-NA-		
		-11/1				
13. l		_N/A_	-NA-	-NA-		
		NMMAGA		-NA-		
		1,2010000		-NA-		
		MN 22X SEC		-NA-		
		25 VA VA C	NY 1940, 1440, C	-NA-		
		125/45	- Carlotte	-NA-		
	N SEAS OF		100 April 100 Ap	-NA-		
			Date:0.5	-NA-		
	Standby Pump Head		Never -	-NA-		
		10/9/102		-NA-		
	20 (Table 2000)	-NA-	-IVA-	1177		
		4501mm	450lpm	MR		
		West Keeting		MR		
			AMAZOROS	-NA-		
13. 1			FI STON	MR		
		Required	Tiovided	1/11		
14.	New World Control Cont	NA	NA	-NA-		
			X7. 07. 84			
	> Draw-off connection	33.0963.03	174.72	-NA-		
	➤ Fire service inlet	-NA-	44,000	-NA-		
	C) Location of Repeater Panel	-NA-	-NA-			
-		10,000ltr	MR			
15.	ACTION OF THE PARTY OF THE PART	Required	Provided	MR		
	a) Pressurization of Lift Shaft	-NA-	-NA-	-NA-		
	Section (Control of the Control of t	-NA-	-NA-	-NA-		
	c) Communication In lift Car	-NA-	-NA-	-NA-		
	d) Fireman's Grounding Switch	-NA-	-NA-	-NA-		
	e) Lift Signage	-NA-	-NA-	-NA-		
17.	Standby power supply	NA-	-NA-	-NA-		
18.						
	a) Total Area	-NA-	-NA-	-NA-		
	The state of the s	-NA-	-NA-	-NA-		
19.				_		
	a) Detector System Panel	NA	-NA-	-NA-		

-NA-	-NA-	-NA-
AT ARTON D	-NA-	-NA-
GUADINA.	-NA-	-NA-
-NA-	-NA-	-NA-
-NA-	-NA-	-NA-
		-NANA- -NANA- -NANA-

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures required stipulated in Director of Education Circular, the FSC issued vide letter no. F.6/DFS/MS/2021/School/WZ/473 dated 13.07.2021 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

D.B Mukherjee DO (NW)

Fi letter is fout up for kind peursal and signature bleare.