



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110 001

No. F.6/DFS/MS/EH/2024/SZ 22

Dated: 1.9./0.7-/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Pret A Manger (A unit of Reliance Brands Limited) located at Shop No. G-05, Ground Floor, Worldmark-1, Asset No. 11, Hospitality District Aerocity, IGI Airport, New Delhi-110037, building comprised of B1 (with mezzanine) + B2 + B3 + G + 6 Upper Floors only, owned/occupied by Reliance Brands Limited have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 06/07/2024 in the presence of Sh. Akhil Mishra (Restt. Manager) and that the premises is fit for occupancy class "Group D" (Restaurant) with effect from the issue of this certificate up to 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service Rules. 2010.

Issued on 19/07/2024 at New Delhi

DEL'HI FIRE SERVICE

Copy to: -

The Joint Commissioner of Police (Lic), First Floor, Police Station Defence Colony, New Delhi-110049 (W.r.t. Online MHA ID No. 2024062309827 dated 23/06/2024)

Sh. Karan Jagmohan Sachdeva of M/s Pret A Menger (A unit of Reliance Brands Limited), Shop No. G-05, Ground Floor, Worldmark-1, Asset No. 11, Hospitality District Aerocity, IGI Airport, New Delhi-110037

Conditions for the validity of fire safety certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment's and

method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the firefighting equipment's shall be maintained in perfect working condition all the time as seen at the time of inspection and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc.

may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate in form J, six months prior to its expiry.

you	Name & Address of the Building	ION REPORT M/s Pret A Manger (A unit of Reliance Brands Ltd), Shop No. G-05, Gd. Floor, Worldmark-1, Asset No. 11, Hospitality District Aerocity, IGI Airport, New Delhi-110037			
2	Type of Occupancy Group-D, "Assembly" (Restaurant)				
1	Building Comprised of	B1 (with mezzanine)+B2+B3+G+6 upper floors			
A	Type of Case	New		Ti nti	
8	Details of Previous NOC	NII F.6/DFS/MS/BP/2011/527 dated 22/03/2011 & F.6/DFS/MS/BP/2013/193 dated 10/01/2013			
6	Fire Safety Directives Letter No				
7	Date of Inspection	06/07/2024			
8	Name of the Inspecting Officers	ADO (SJ)			
9	Name & Designation of Officers from the building side	Sh. Akhil Mishra (Restt. Manager)			
0	Year of construction	2014			
1	Applicant letter No. /Online MHA	ID No. 2024062309827 dated 23/06/2024			
S. 10.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL/NBC-2016 Requirement	Provided at Site	Remark MR/NM	
10.	Access to Building/FSC to Bldg.	F.6/DFS/MS/Mix	ed/2024/SZ/HTL/12 I)t. 12/03/24	
_	Road width	Restt. within WN	A-1 As above	MR	
	Gate width	Restt. within WN	⊿-1 As above	MR	
	Width of internal road	Restt. within WN	√-1 As above	MR	
2	Number, width, type & arrangemen	of exits.			
4	a) Number of Staircase	Provided and	Maintained by Bldg.	Mgmt.	
		NA	Restt. at GF only	NA	
	Upper floors.Basement floor.	NA	N/A	NA	
		Provided and	Maintained by Bldg.	Mgmt.	
	b) Width of Staircase	NA NA	Restt. at GF only	NA	
	> Upper floors	NA NA	NA	NA	
1	> Basement floor	NA Duralded and	Maintained by Bldg.	Mgmt.	
	c) Protection of exits		NA NA	NA	
	➤ Fire check door	NA NA	NA NA	NA	
	> Pressurization	NA		100000	
	d) No. of continuous staircase to terrace		Maintained by Bldg. NA	NA	
	e) Width of corridor	NA	37.41-31.55	MR	
	f) Door size	1.5m x 2 Nos	2m & 1.60m		
3	Compartmentation.		Maintained by Bldg. NA	NA	
Outstand !	Fire check door.	NA NA	NA	NA	
	 Sealing of electrical shafts. 	NA NA	NA NA	NA	
	 Fire rating of shaft door. 	NA NA	NA NA	NA	
	Water curtain	NA		NA	
	Fire dampers.	NA	NA	A C227-3 - 24	
1	Smoke Management system.	Provided and	Maintained by Bldg.	N/A	
4.	Basement	30 ACPH	N/A	N/A	
	Upper floor	12 ACPH	N/A	14/24	
5.	Fire Extinguishers.	AL LANGE	Of New	MR	
	Total numbers	Required	06 Nos	MR	
	Types	ABC/CO ₂ /WCO ₂	ABC & CO ₂	MR	
		Required	Provided	233.5.55	
-	ISI Marking Proceedings	Provided and	Maintained by Bldg.	Mgmt.	
6.	First Aid Hose Reels. Total numbers on each floor.	One near Restt.	Provided	IVII	
	Length of hose-reel hose.	30m	Provided	MR	
	e Length of nose-reel flose.	5mm	Provided	MR	

N-37

7	Automatic fire detection & alarmin	g system.		
	Type of detectors	NA	Smoke & Heat	N
	Location of Main Panel	NA	Ground floor	N
	Location of Repeater Panel	NA	N/A	N
	Alternate source of power	NA	Provided	N
	Hooter's location	NA	Near entry/exit	N
8	MOEFA		Provided	M
9	Public Address System	Required	211201 COLORES	N.
10		NA D : 1 1	NA	- A V
10	Automatic Sprinkler System	The state of the s	d Maintained by Bldg	g. Mgm
	Basement	NA	NA	
	Upper floors.	NA	NA -	N.
	Sprinkler above false ceiling	NA	NA	N/
11	Internal Hydrants.	Provided and Maintained by Bldg. Mgmt		
	Size of Riser/Down-comer	100mm	Provided	M
	Number of Hydrant per floor	One near EH	Provided	MI
12	Hose box. Verd Harden	One near EH	Provided	MI
12	Yard Hydrants.		Maintained by Bldg	
	Total number of hydrants.Hose box.	NA	As above	NA
13	Pumping arrangements.	NA	As above	- NA
	Ground Level	Provided and	Maintained by Bldg.	Mamt
	Discharge of main pump.	2280 LPM	2280 LPM	MR
	> Head of main pump.	105m	105m	MR
	➤ Number of main pumps.	Two	Two	MR
	➤ Jockey Pump output.	2 x 180 LPM	2 x 180 LPM	MR
	> Jockey Pump head.	105m	105m	MR
	Standby Pump output.	2280 LPM	2280 LPM	MR
	Standby Pump head.Auto Starting/Manual Stopping.	105m	105m	MR
	> Pump house access.	Required	Provided	MR
	Terrace Level	Required	Provided	MR
22	> Discharge of pump.	Provided and	Maintained by Bldg.	
50	> Head of pump.	450 LPM	900 LPM	MR
	> Power supply.	40m	40m	MR
	➤ Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	Required	Provided	MR
14			Maintained by Bldg.	
	 Underground tank capacity. Draw-off connection. 	1,50,000 Ltrs	Provided	MR
15	> Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
		Required	Provided	MR
	Overhead tank capacity. Exit Signage.	20,000 Ltrs	Provided	MR
16	Provision of Lifts.	Required	Provided	MR
	Pressurization of lift shaft.	NA Provided and N	Maintained by Bldg. N	
	Pressurization of lift lobby.	NA NA	NA	NA
	Communication in lift car.	NA NA	NA	NA
	• Fireman's switch.	NA NA	NA	NA
	Lift signage.	The second secon	NA	NA
17	Standby Power Supply	NA NA	NA	NA
18	Refuge Area	Required	Provided	MR
	Total area	Provided and Maintained by Bldg. Mgmt.		
	C. Lat 7 (44) C. (2000)	NA	NA	NA
	• Location	NA	NA	NA

M

2

19	Fire Control Room.	rol Room. Provided and Maintained by Bld		. Mgmt.
1/	Detector system panel.	NA	Provided	NA
	Flow switch panel.	NA	Provided	NA
	PA system panel.	NA	Provided	NA
	Battery backup.	NA	Provided	NA
	Building floor plan.	NA	Provided	NA
20	Special Fire Protection System for the Protection of special Risk, if any.	Provided and Maintained by Bldg. Mgmt.		

The fire protection systems provided in the premises were checked, tested at random and found functional at the of inspection. The shortcomings communicated by this department vide letter No. F6/DFS/MS/EH/SZ/2023/HTL/31 dated 31/10/2023 found complied.

Keeping in view of the substantial compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety dertificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Santosh Kumar

Designation: ADO (SJ) (ha) The dry of nestaurant is same there is no change Hence clarify with dry

The readth of the exit havebeen widen and stegraph of same are auterhed verenith or kind person please resulmitted fr