GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI <u>HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001</u>



No F 6 / DFS / MS / 2024 /Bnqt/WZ/ 36

Dated: 19 07 2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Green Lounge North Banquet (A Unit of Nagpal Hospitality Pvt. Ltd.) located at Ground and First floor, C-93, Wazirpur Industrial Area, New Delhi-110052 in a building comprised of Basement, Ground, Mezzanine plus one upper floor was issued FSC by this department vide letter No F6/DFS/MS/WZ/2021/296 dated 07.07.2021. The premise was re-inspected by the officer concerned of this department on 12.07.2024 in the presence of Sh. Jagdish Nagpal and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "Assembly (Group D)" (for Ground & First floor except Basement) with effect from 19107 2024 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 19.10.7.120.2.4.. at New Delhi, by

Delhi Fire Service

Copy to: -

- 1. M/s Green Lounge North Banquet (A Unit of Nagpal Hospitality Pvt. Ltd.), C-93, Wazirpur Industrial Area, New Delhi-110052.
- MHA Portal, ID No. 2024062710016.

Conditions for the validity of Fire Safety Certificate:

This FSC is valid for Ground & First Floor only.

- 2. All the fire safety arrangement provided there-in shall be maintained in good working
- 3. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation with regard to the construction etc shall be verified by the concerned
- 6. This certificate cannot be treated in any case for regularizations of unauthorized
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA portal (https://www.delehlhlic.gov.in) along with a copy of this Certificate, six months
- 8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

1. Name & address of the building : INSPECTION REPORT

Green Lounge North Banquet (A Unit of Nagpal Hospitality Pvt. Ltd.)

Located at C-93, Wazirpur Industrial Area, Delhi-110052.

 Type of Occupancy
 Building Comprised of : Assembly (Banquet Hall)

4. Type of Case : Basement, Ground, Mezzanine plus 01 upper floor.

5. Details of Previous NOC Renewal

F6/DFS/MS/WZ/2021/296 Dated- 07/07/2021 6. Fire Safety directives letter No :

F6/DFS/MS/BP/2014/13 Dated- 17/01/2014 (For Industry) occupancy

Changes into assembly.

7. Date of inspection 12/07/2024

8. Name of Inspecting Officer R.K.Sinha, ADO (BW) 9. Name and designation of officers

From the building side Sh. Jagdish Nagpal

10. Year of Construction 2003 as per MHA portal.

11. Applicant's letter No. MHA Application ID No. 2024062710016 dated 27/06/2024

S. No.	Minimum Star	r floor, ndards on fire d fire safety U/R 33	BBL/ Inspection rep	port Provided at site	Remarks MR/NMR	
1.	Access to build	ling	uated 20/00/2021			
	Road v		12 m	Provided	MR	
	Gate w		5 m	On Road	MR	
		of internal road	NA	NA	NA	
2.		th, Type & Arrangeme	ent of Exits			
	a. Number of s	taircases			1 10	
	Upper	Floors	02	03	MR	
	Basen	nents	NA	02	NA	
	b. Width of sta		_			
	Upper		2 m each	2 m, 2.05 m & 1.82- 1.92 m	MR	
	Basen		NA	1.42 m & 1.32 m One stair found blocked	NA	
	c. Protection of	f exits				
	** * **	heck door	Required	Provided	MR	
		rization	NA	NA	NA	
		inuous staircases to	02	Provided	MR	
	e. Width of Co	orridor	NA	NA	NA	
	f. Door Size		2 × 2 m	GF- 2 × 2.45 m, 1.86 m & F.F 2 × 2 m	MR	
3.	Compartmentation					
<i>-</i> .		eck door	Required	Provided	MR	
			NA NA	NA	NA	
		of electrical shafts				
		ting of shaft door	NA NA	NA NA	NA NA	
	• Water (NA NA	NA NA	NA NA	
	Fire Da		NA	NA NA	NA	
4.	Smoke Management System Basement used by cenesale as store					
	Baseme	ents	NA	Provided	NA	
	Upper f	loors	Required	Provided	MR	
5.	Fire Extinguish	hers				
	Total ni	umbers	15	Provided	MR	
	Types		ABC/Co2 Type	Provided	MR	
	IS mark	ing	Required	Provided	MR	
6.	First-Aid Hose					
		umbers on each floor	01	Provided	MR	
		of hose reel hose	30 m	Provided	MR	
		diameter	5 mm	Provided	MR	
7.	Automatic fire detection and alarming system					
	Type of	detectors	Smoke/ Heat	Provided		
		The Control of	MANAGEMENT PROPERTY.	11071000	MR	

N-21

_				MR		
	Location of Repeater Panel	Required	Provided	MR		
	 Alternate source of power 	Required	Provided			
		Appropriate		MR		
_	Hooters' Location	locations	Provided	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided			
10		Required	Provided	MR		
	Basement	Required	Provided	MR		
	Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling					
11						
	Size of riser/down-comer	100 mm	Provided Provided	MR MR		
	 Number of hydrants per floor 	1	Provided	MR		
100	Hose Box	1	Flovided			
12		1	Provided	MR		
	Total number of hydrants	4	Provided	MR		
-	Hose Box					
13.						
	Ground Level Discharge of main Pump	2290 Inm	Provided	MR		
	➤ Discharge of main Pump	2280 lpm 60 m	Provided	MR		
	➤ Head of Main pump	OO III				
	> Number of main pumps	01	Provided	MR		
	> Jockey Pump out put	180 lpm	Provided	MR		
	> Jockey pump head	60 m	Provided	MR		
	> Standby Pump out put	2280 lpm	Provided	MR		
	➤ Standby Pump Head	60 m	Provided	MR		
	> Auto Starting/Manual	Required	Provided	MR		
\$3	Stopping					
	> Pump House Access	Required	Provided	MR		
	Terrace level					
	➤ Discharge of pump	900 lpm	Provided	MR		
		40 m	Provided	MR		
	➤ Head of the pump					
	> Power Supply	Required	Provided	MR		
	➤ Auto Starting of pump	Required	Provided	MR		
4.	Captive Water Storage for fire fighting					
	Underground tank capacity	50,000 ltrs	Provided	MR		
	> Draw-off connection	Required	Provided	MR		
	> Fire service inlet	Required	Provided	MR		
	> Access to tank	Required	Provided	MR		
		10,000 ltrs	Provided	MR		
5.	Overhead Tank capacity Exit Signage.	Required	Provided	MR		
	5 5	Acquired	1 loyided	IVIK		
6.	Provision of Lifts.	3, • 1				
	Pressurization of Lift Shaft	NA	NA	NA		
	 Pressurization of Lift lobby 	NA	NA	NA		
	 Communication In lift Car 	NA	NA	NA -		
	Fireman's Grounding Switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
	Standby power supply	Required	Provided	MR		
3.	Refuge Area.					
1	➤ Total Area	NA	NA	NA		
,	> Location	NA	NA	NA NA		
19.	Fire Control Room		S 15-2	11/1		
4	Detector System Panel	NA D	NA			
The state of the s	The second second	- NA N	INA	NA		

7	ow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	. NA
		NA	NA	NA
	Battery backup	NA	NA	NA
	Building Floor Plans	NA NA	NA	NA
20.	Special Fire Protection System for Protection of special Risks, if any:	INA.		

Note: Mezzanine floor is located in between Ground floor and First floor and is segregated from both floors.

The fire protection systems provided in the building were tested, checked and found functional at

the time of inspection.

ed

led

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the fire safety certificate issued vide letter number F6/DFS/MS/WZ/2021/296 dated 07/07/2021 under Rule 37 of The Delhi Fire Service Rules, 2010.

> Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

msleer