GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI

HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2024/ School/WZ/ 72|

Dated:

25/07/2024

FIRE SAFETY CERTIFICATE

Certified that the Rukmini Devi Bal Vatika (Junior Wing) located at GD- Block, Pitampura, Delhi-110034 comprised of Basement + Ground +Three upper floors was issued FSC by this department vide letter No F6/DFS/MS/School/WZ/2021/585 dated 05.08.2021. The premises was re-inspected by the officer concerned of this department on 15.07.2024 in the presence of Smt. Anjali Kotnala (Principal), and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements under rule 33 of the Delhi Fire Service Rule, 2010 and that the building/ premise is fit for occupancy Group B Educational with effect from ...25. a.7. 2a.2.4. for a period of three years, in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on ... 25 07/2024.... at New Delhi, by

Director Ph. 011-23414000

per

Copy to:-

1. The Director, Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

2. The Principal, Rukmini Devi Bal Vatika (Junior Wing) located at GD- Block, Pitampura, Delhi-110034.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>
- 8. The basement shall be used as per BBL.

INSPECTION REPORT Name & address of the building: INSPECTION REPORT
Rukmini Devi Bal Vatika (Junior Wing) located at GD- Block, Pitampura,

2. Type of Occupancy Delhi-110034. 3. Building Comprised of : Educational : Basement + Ground + 3 upper floors

4. Type of Case : F6/DFS/MS/School/WZ/2021/585 Dated- 05/08/2021

5. Details of Previous NOC : F6/DF5/NAC.
6. Fire Safety directives letter No : NBC Part-IV 15/07/2024 7. Date of inspection

R.K.Sinha, ADO (BW) 8. Name of Inspecting Officer

9. Name and designation of officers

Smt. Anjali Kotnala (Principal) From the building side

	10. Year of Construction 11. Applicant's letter No.	: 2008 as per N-10 : Form J dated 18/06/20	Provided at site	Remarks				
S. No.	Minimum Standards on fire	NBC Part-IV	tion	MR/NMR				
1.	Access to building	Topose	Provided	MR				
1.	Road width	6 m	Directly Accessible	MR				
	Gate width	4.5 m	NA NA	NA				
	. Width of internal road	NA	177					
2.	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases		02	MR				
	Upper Floors	02	03	MR				
	Basements	02	- 03					
	b. Width of staircases		1.42 m & 0.90 m	MR(old case)				
	Upper Floor	1.50 m each	1.45 m & 0.76 m	MR(old case)				
Y.	Basements	1.50 m each	1.45 m & 0.76 m					
	c. Protection of exits	g)g		NA				
		NA	NA	NA NA				
		NA	NA	, NA				
	d. No. of continuous staircases to terrace	. 01	Provided	MR				
	vy M. Camidor	1.5 m	Provided	MR				
	f. Door Size	1 m	Provided	MR				
	Compartmentation NA							
3.	77.5	NA NA	NA	NA				
	Fire check door	NA NA	NA	NA				
	Sealing of electrical shafts		NA	NA				
	 Fire Rating of shaft door 	NA NA	NA NA	NA				
	Water Curtain	NA	NA NA	NA				
	Fire Dampers	NA	NA NA	102				
	Smoke Management System							
	Basements	Required	Exhaust Fan Provided	MR				
	Upper floors	Required	Naturally Ventilated	Provided				
	Fire Extinguishers	0031	25) [) (D				
	Total numbers	08 Nos.	25 Nos.	MR				
	Types	ABC/ Co2 Type	Provided	MR				
	IS marking	Required	Provided	MR				
-	First-Aid Hose Reels	01	D					
-	Total numbers on each floor		Provided	MR				
}	Length of hose reel hose	30 m	Provided	MR				
=	Nozzle diameter	5 mm	Provided	MR				
	Automatic fire detection and alarming system							
	 Type of detectors 	NA	NA	NA				
	 Location of Main Panel 	NA	NA	NA NA				
-	 Location of Repeater Panel 	NA	NA NA					
-	 Alternate source of power 	NA NA	NA NA	NA				

N-25

	Hooters' Location	NA	NA	NA
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	F 1 0 0	1100.000	
	Basement	Required	Provided	MR
	Upper Floor	ŇA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants			
	Size of riser/down-comer	100 mm	Provided) (D
	Number of hydrants per floor	01	02	MR
	Hose Box	01	Provided	MR MR
12.	Yard Hydrants		Flovided	MIK
	Total number of hydrants	NA	Provided	NA
	Hose Box	NA	NA	A-2011 (A-2011)
3.	Pumping Arrangements		IVA	NA
+	Ground Level	NA	NTA I	-
	➤ Discharge of main Pump		NA	NA
		NA NA	· NA	NA
	➤ Head of Main pump		NA	NA
	Number of main pumps	NA.	NA	NA
	> Jockey Pump out put	NA	NA ·	NA
	> Jockey pump head	NA	NA	NA
	> Standby Pump out put	NA	NA	NA
	Standby Pump Head Auto Starting/Manual	NA	NÁ	NA
	➤ Auto Starting/Manual Stopping	NA	NA	. NA
	> Pump House Access	NA	NA	NA
	Terrace level			
	➢ Discharge of pump	450 lpm & 180 lpm	Provided	MR
4	➤ Head of the pump	40 m	Provided	MR
	➤ Power Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting	3	Tiovided	MK
	Underground tank capacity ,	NA	NA	NA
	> Draw-off connection	NA	NA	NA
	➤ Fire service inlet	NA	NA	NA
×	➤ Access to tank	NA	NA	NA
	Overhead Tank capacity	15,000 ltrs	Provided	MR
5.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.			
	Pressurization of Lift Shaft	. NA	NA I	NA NA
	Pressurization of Lift lobby	NA .	NA	NA NA
	Communication In lift Car	Required	Provided	MR
	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
7.	Standby power supply	Required	Provided	MR
8.	Refuge Area.			
			<u> </u>	
	➤ Total Area ➤ Location	NA	NA	NA
- 1		NA -	NA	NA

Detector System Panel	NA		
Flow Switch Panel		NA	NA
PA System Panel	NA	NA	NA
	NA	NA	NA
Battery backup	NA	The state of the s	
Building Floor Plans		NA	NA
	NA	NA	NA
Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: Electrical panel and electric meter are not under the staircase.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, it is recommended to renew the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/WZ/2021/585 dated 05/08/2021 under Rule 37 of the Delhi Fire Service Rules, 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha

Designation: ADO/B.W.

Ductor

d/2 / 18/2

Dêneter

Anysi

in 16 1 feet - from & sy

()

restor(0/h)

m

Sear Salland