

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/EH/2024/SZ/ 232

Dated: 22/07/2024

# **FIRE SAFETY CERTIFICATE**

Certified that the M/s The Barbeque Company (a unit of Savour Hospitality), running at ground and first floor only of a building comprised of ground plus three upper floors, located at HL-1 & 2, GF, FF, Anand Vihar, Jail Road, New Delhi-110064, owned/occupied by M/s The Barbeque Company (a unit of Savour Hospitality) was issued FSC by this department vide letter F6/DFS/MS/EH/2021/SZ/188 dated 16.08.2021. The Restaurant building was reinspected by the officers concerned of this department on 10.07.2024 in the presence of Sh. Vikas Kumar (Manager) and found that building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Ground floor & First floor Only) is fit for occupancy class Group-D "Assembly Building" (Restaurant) w.e.f. 22 07/221 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 22 07 2024 at New Delhi.

Atul Carg)
Director
Delhi Fire Service

### Online application Id 2024060508807 dated 18.06.2024

# Following fire safety directives must be adhered to: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. Basement shall be used as per the building bye laws.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

#### INSPECTION REPORT

1. Name & address of the building: M/s The Barbeque Company (a unit of Savour Hospitality), HL-1 & 2,

GF, FF, Anand Vihar, Jail Road, New Delhi.

Type of Occupancy

: Group D (Assembly Building)

3. Building Composition

Restaurant running at ground & first floor only of a building

comprised of ground plus three upper floors.

4. Type of Case

: Renewal

5. Details of Previous NOC

F6/DFS/MS/EH/2021/SZ/188 dated 16.08.2021

6. Fire Safety directives letter No :

N/A

7. Date of inspection

: 10.07.2024

8. Name of Inspecting Officers

A.D.O. R.K. Yadav

9. Name and designation of officers

. . .

From the building side

Sh. Vikas Kumar (Manager)
Before 2008

10. Year of Construction

ID No. 2024060508807 dated 18.06.2024

S. No.		um Standards on fire prevention and fire U/R 33	Requirement	Provided at site	Remarks MR/NMR			
l.	Access	to building		la l	L'and reli			
	•	Road width Gate width Width of internal road	09 mtrs 4.5 mtrs N/A	Provided Directly accessible from road N/A	MR MR N/A			
2.	Numb	er, Width, Type & Arrangement of Exits						
	a. Nur	nber of staircases						
	•	Upper Floors	Two	Provided	MR			
	•	Basements	N/A	N/A	N/A			
	b. Wid	th of staircases Upper Floor	Old case	1.28 & 1.08 m	MR, being old case			
		Basements	N/A	N/A	N/A			
	c. Pro	tection of exits Fire check door		The same of the				
		Pressurization	N/A	N/A	N/A			
	•	Flessurization	N/A	N/A	N/A			
	d No	of continuous staircases to						
	The State of the S	тасе	N/A	N/A	N/A			
	e. Wi	dth of Corridor	N/A	1.08 m	N/A			
	( D	C:	SWEET:	2.0 m & 1.0 n				
	f. Do	oor Size	Two Exits	2.0 m & 1.0 m	II WIK			
3.	Comp	artmentation						
-		Fire check door	N/A	N/A	N/A			
		Sealing of electrical shafts	N/A	N/A	N/A			
	•	Fire Rating of shaft door	N/A	N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System							
	•	Basements	N/A	N/A	N/A			
		Upper floors	Required	Provided	MR			
5.	Fire Extinguishers							
		Total symphose	06 No.'s	Provid	led MR			
	•	Total numbers Types	ABC/CO₂	Provid	led MR			
		I S marking	ISI marked	ISI mar	ked MR			
			151 Illaikeu					

N	22
	(

	. 14			-			
6.	First-Aid Hose Reels	One	Provided	MR			
	Total numbers on each floor	30 m	Provided	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	5 mm	Provided	MR			
	Nozzle diameter	, J.III.	1100.000				
7.	Automatic fire detection and alarming system						
	Type of detectors	N/A	Provided	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	Provided	N/A			
	Hooters' Location	N/A	At exit Provided	N/A MR			
8.	MOEFA	Required		N/A			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System						
	Basement	N/A	N/A	N/A MR			
	Ground Floor	N/A	Provided				
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants	(Old Case)	1 MD				
	Size of riser/down-comer	N/A	Provided Provided	MR MR			
	Number of hydrants	N/A N/A	Provided	MR			
	Hose Box	IVA	Tiovided				
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A N/A			
	Hose Box	N/A	N/A	IVA			
13.	Pumping Arrangements		المساطع الما				
	Ground Level		27/4	NI/A			
	> Discharge of main Pump	N/A	N/A	N/A			
	> Head of Main pump	N/A	N/A	N/A			
	<ul><li>Number of main pumps</li><li>Jockey Pump out put</li></ul>	N/A	N/A	N/A			
	<ul><li>Jockey Pump out put</li><li>Jockey pump head</li></ul>	N/A	N/A	N/A			
	Jockey pump nead	N/A	N/A	N/A			
	➤ Standby Pump out put	N/A	N/A	N/A			
	> Standby Pump Head	N/A	N/A	N/A			
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
	Terrace level     Discharge of nump	450 LPM & 180 LF	M   450 LPM & 180 L	PM MR			
	<ul><li>Discharge of pump</li><li>Head of the pump</li></ul>	30 mtrs.	Provided	MR			
	> Power Supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
4.	Captive Water Storage for fire fighting		Cala Maria				
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
_	Overhead Tank capacity  P. 4.63	5000 ltrs	Provided	MR			
5.	Exit Signage.	Required	Provided	MR			
6.	Provision of Lifts.						
	Pressurization of Lift labby	N/A	N/A	N/A			
	Pressurization of Lift lobby     Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
		N/A	N/A	N/A			

1	Standby power supply		Required	Provided	MR	
18.	Refuge Area.					
	A	Total Area	N/A	N/A	N/A	
	>	Location	N/A	N/A	N/A	
19.	Fire Control Room					
		N/A	N/A	N/A		
	•	Detector System Panel	N/A	N/A	N/A	
		Flow Switch Panel	N/A	N/A	N/A	
		PA System Panel	N/A	N/A	N/A	
		Battery backup Building Floor Plans	N/A	N/A	N/A	
:0.	Special	Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/EH/2021/SZ/188 dated 16.08.2021, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting

Name: - R.K. Yadav Designation: - ADO (JKP)

DO (South West)