

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No. F6/DFS/MS/2024/GH 307

Dated: 29/07/2024

FIRE SAFETY CERTIFICATE

Certified that the building of M/S Hotel Ananda Located at 1st, 2nd & 3rd floors Plot No.8/41, WEA. Abdul Aziz Road, Karol Bagh, New Delhi, in a building comprised of basement, ground plus three upper floors using basement as (storage), ground floor (lobby, shops & reception), first, second & third floor (10 guest rooms each floor) (Total=30 guest rooms) and 01 staff room on terrace (now sealed/closed) was issued FSC vide Letter No F6/DFS/MS/GH/SZ/2021/226, dated 19/07/2021. The premises was re inspected by the officer concerned of this department on 22/07/2024 in the presence of Sh. Naresh (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" (guest house) at first, second & third floor (10 guest rooms each floor) (Total=30 guest rooms) with effect from 29 of 2029 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 29.07.2024.. at New Delhi by.

Director Delhi Fire Service

Copy to:

- 1. The Joint. Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi.
- 2. The Manager, M/S Hotel Ananda Located at 1st,2nd & 3rd floors Plot No.8/41, WEA Abdul Aziz Road, Karol Bagh, New Delhi.

Following fire safety directives must be adhered to:-

1. 4th floor shall not be used for any purpose as undertaking given by owner.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. Basement strictly shall be kept vacant as seen during inspection.

- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

Name & address of the building: M/S Hotel Ananda Located at 1st,2nd & 3rd floors Plot No.8/41, WEA Abdul Aziz Road, Karol Bagh, New Delhi.

2. Type of Occupancy

:Lodging or rooming "A-1"

3. Type of Case : Renewal (Running at 1st,2nd & 3rd floors in a building comprised of Basement, G+3 UFs & staff room on terrace

4. Details of previous NOC: F6/DFS/MS/GH/SZ/2021/226, dated 19/07/2021

5. Fire Safety directives Letter No.: Nil

6. Date of inspection

:22/07/2024

7. Name of the Inspecting Officer: ADO (DWK)

8. Name and designation of Officer

from the building side

: Sh. Naressh (Manager)

9. Year of Construction

: Before 2008

10. Applicant's letter No.

: 2024070210264, dated 02/07/2024

S No	Minimum standards on fire prevention and fire safety U/R 33					the state of the s		I company to the	Remarks MR/NMR	
1.	Access of building							1		
	Road width	61	mtr .5 Direc		Provided Direct accessible from road			MR		
	 Gate width 	4.5						road	MR	
	 Width of internal road 	N.	۸·	NA					NA	
2.	Number, width, Type & Arrang	gem	ents of e	exits					1	
	a. Number of staircases									
	 Upper floors 	01	d case	01		- N		(Being	old case)	
	Basements	Old case		(01		MR (Being old case) MR (Being old case)		d cose)	
	 b. Width of staircases 							ornig of	u case)	
	 Upper floors 	0	ld case	1.25	m		MR	Raina	ld assa)	
	Basements				Trine (De		Dellig (eing old case) (Being old case)		
	c. Protection of exits	112 111 111				77111	IVII	(Deing	g old case	
	 Fire check door 	N	NA NA		NT A					
	 Pressurization 		NA NA		NA				NA	
	d. No of continuous		01		NA				NA	
	staircase to terrace	OI.			01				MR	
	e. Width Of Corridor	10	Old case		11.50					
	f. Door Size					1.52 m		N		
		Old case			0.80 m		MR(Being old case		d case)	
3.	Compartmentation									
	 Fire check door 	N	NA.		NA					
	 Sealing of electrical 	R	equired						NA	
	shafts					Sealed			· MR	
	 Fire Rating of shaft door 	NA				N	NA		NA	
1	Water Curtain	NA NA								
	Fire Dampers					NA			NA	
	-	1,				N	A		NA	



N/38

_	Smoke managements System Basements 30 a/c p		10	per hour Provide			led			
					al ventilation			MR MR		
	•	Upper floors	12 a	c per	nour	Natura	1 Venui	ation		
	Fire Ex	ctinguishers					Provid	ad .		MR
- 1	•	Total numbers		15 N		-				MR
	•	Types			C & CO ₂		CO ₂ &			
		IS marking		Requ	uired		Provid	ed		MR
).	First -	Aid Hose Reels	4					vided	-	MR
	•	Total numbers on each floor				or 01				MR
		Length of hose red			30 m	YACA		rided		MR
	•	Nozzle diameter			5 MN		Prov	rided		IVIIC
7.	Auton	natic fire detection	and ala	armin	g system		In	الموادية		MR
•	•	Type of detectors			CO dete	ectors		ovided	1.7	MR
		Location of Main Panel			Require	Provided			NA	
1		Location of Repea		nel	NA		NA	4001	FTTA	MR
		Alternate source of	of pow	er	Require	d	DG se	t 125 I	CVA	NA NA
	•	Hooters' Location	1		NA	N	IA	11.1		MR
8.	MOE				Require	d	Prov			MR
<u>8.</u> 9.		Address System			Required	d	Prov	ided		1,122
10.	Autor	natic Sprinkler Syst	em	Ĭ .	12 /2		Dear	ided		MR
10.	•	Rasements R			ired	V.	Provided NA			NA
		Upper Floor		NA			NA NA			NA
		Sprinkler above fa	alse	NA			1471			
		ceiling								
11.	Intern	nal Hydrants:		NA	NA			NA		
	•	Size of riser/down	ı- com	er			NA			NA
	•	Number of hydrau	nts per	floor	NA NA		NA			NA
	•	Hose Box	-		1421					
12.	Yard	Hydrants	1	to.	NA.		NA			NA
	•	Total number of hydrants			147					
	•	Hose Box			NA		NA			NA
12	Domes	oing Arrangements:								
13.	Pump	~ 1T -1							4 1	
		Discharge of main pump			NA	NA			NA	
	D	Head of main pun			NA		NA			NA
	>	Number of main pumps Jockey pump out put Jockey pump head Standby Pump out put			NA		NA NA NA			NA
100	A				NA					NA
	>				NA					NA
34	>				NA	NA			NA	
	A				٧A		NA			NA
	>	Auto Staring/Man stopping	ual	1	NA .		NA			NA
	>	Pump House Acce	ess	1	NA .		NA			NA
		Terrace level								4 14 1
		Vie Sichardes Coorden Store, F			150 lpm	Prov	ided	MR	-	
	6266				40 mtrs Pro		rovided MR rovided MR			
	A									
	> Auto starting of pump		_			ovided MR				
					=	120.17	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW			



m

N/39

4. C	Captive water Storage for fire fi	ightin	g:							
	capacity	NA	A A		NA	NA NA				
	Draw off connection	NA			NA					
	Fire service inlet	NA			Provided	NA				
	Access to tank	NA			NA	NA				
	Overhead Tank capacity		case		6000 ltr	MR				
15	Exit Signage Rec				Provided	MR				
16.	Provision of Lifts				TTOVIACU	11110				
	Pressurization of Lift Sl	naft	NA		NA	NA				
	Pressurization of lift lob	by	NA		NA	NA				
	Communication in lift (Car	Required		Provided	MR				
	Fireman's Grounding Switch	*	Required		Provided	MR				
	Lift Signage		Required		Provided	MR				
	17. Standby power supply		Required		Provided	MR				
18.	Refuge Area					Š.				
1	➤ Total area		NA NA		NA	NA				
	> Location				NA	NA				
19.										
	 Detector system panel Flow Switch Panel PA System Panel Battery backup 				NA	NA				
					NA	NA				
					NA	NA				
			Required		Provided	MR				
	➤ Building Floor Plans	NA			NA	NA				
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA		NA	.e.	NA				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/SZ/2021/226, dated 9/07/2021 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended. If approved the FSC may be issued.

Signature of the Inspecting Officer

Name: Sh. Udaivir Singh Designation: ADO (DWK)

CFO(\$2)

Director My

ublocated