



No. 6/DFS/MS/Cinema/NDZ/2024 / 499

Dated: 30/07/2024

**FIRE SAFETY CERTIFICATE**

Certified that the M/s Moon Shine Entertainment Limited (Miraj Cinema) hall running on 3<sup>rd</sup> & 4<sup>th</sup> floor (Audi – 04, Audi no. 05 & Audi no. 06, (Miraj Cinema) located at Trilok Puri, Delhi - 110091, building comprised of three basement, ground plus four upper floors, owned/occupied M/s Moon Shine Entertainment Limited, have complied with the Fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 20/07/2024 in the presence of Mr. Vikas Tyagi (Manager) and found that the building/premises is fit for occupancy class “Assembly Building” (Group – D) with effect from 30/07/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010, printed below.

Issued on 30/07/2024 at New Delhi by.

(ATUL GARG)  
DIRECTOR

d/c DELHI FIRE SERVICE

**Copy to:-**

1. The Ex. Engineer (Bldg.), MCD, 419, F.I.E. Udyog Sadan, Patparganj, Delhi – 110092
2. The Manager, Moon Shine Entertainment Limited (Chand Cinema) located at Trilok Puri, Delhi - 110091.
3. The Deputy Health Officer, Shahdara South Zone, Shahdara, Delhi.
4. The Electrical Inspector, Govt. of NCT of Delhi, D- Block, 5 Sham Nath marg, Delhi.

**Conditions for the validity of Fire Safety Certificate:**

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).

**INSPECTION REPORT**

1	Name & address of the building	Moon Shine Entertainment Limited for (Audi - 04, Audi no. 05 & Audi no. 06, (Miraj Cinema) located at Trilok Puri, Delhi - 110091.		
2	Building is comprised of	03 Basement, Ground + 04 upper floors only. (Cinema Hall on 2 <sup>nd</sup> , 3 <sup>rd</sup> & 4 <sup>th</sup> floor)		
3	Type of occupancy	<b>Assembly Building</b> (Cinema Hall)		
4	Type of case	New Case		
5	Details of previous FSC	Nil (FSC also issued to the building vide letter No. F6/DFS/MS/Cinema/NDZ/2024/242 dated 19/04/2024.)		
6	Fire safety directives letter no.	F6/DFS/MS/BP/2019/113 dated 15.03.2019		
7	Date of inspection	20.07.2024		
8	Name of the inspecting officers	Yashwant Singh Meena ADO (L.N)		
9	Name of the designation of officer from the building side	Mr. Vikas Tyagi (Manager)		
10	Year of construction	2020		
11	Applicant's letter no.	Outdoor Diary no. 4205 dated 15/07/2024		
S.No	<b>Minimum standard of fire prevention and fire safety U/R 33</b>	<b>Requirement</b>	<b>Provided at site</b>	<b>Remarks MR/NMR</b>
1	<b>Access to Building:</b>			
	A	Road width	30 mtrs.	30mtrs. MR
	B	Gate width	6.0mtrs.	6.0mtrs. MR
	C	Width of internal road	9.0mtrs.	9.0mtrs. MR
2	<b>Number, Width, Type and Arrangement of Exits:</b>			
	A	Number of staircases		
		a	Upper floor	04 nos. 04 nos. MR
		b	Basement	03 nos. 03 nos. + 01 no. ramp MR
	B	Width of staircases		
		a	Upper floor	2.0 mtrs. 2.0 mtrs. MR
		b	Basement	2.0 mtrs. 2.0 mtrs. (Ramp 7.30 mtrs.) MR
	C	Protection of exits		
		a	Fire check door	Required Provided MR
		b	Pressurization	Required Provided MR
	D	No. of continuous staircases to terrace	02 nos.	04 nos. MR
	E	Width of corridor	Required	Provided MR
	F	Door size	2.0 mtrs. & 1.50 mtrs.	Provided MR
3	<b>Compartmentation:</b>			
	A	Fire check door	Required	Provided MR
	B	Sealing of electrical shafts	Required	Sealed MR
	C	Fire rating of shaft door (02 hrs)	Required	Provided MR
	D	Water curtain	Required	Provided MR
	E	Fire dampers	Required	Provided MR
4	<b>Smoke Management System:</b>			
	A	Basement	30 a/c per hrs	Provided MR
	B	Upper floor	12 a/c per hrs	Provided MR

Miraj Cinema located at Trilok Puri, Delhi - 110091.

2/16

<b>5.</b>	<b>Fire Extinguisher:</b>			
A	Total numbers	40 nos.	Provided /	MR
B	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR
C	ISI marking	ISI Marked	ISI Marked	MR
<b>6</b>	<b>First-Aid-Hose Reel:</b>			
A	Total numbers of	Required one no. in each Audi.	Provided /	MR
B	Length of hose reel hose	30 mtrs.	Provided	MR
C	Nozzle diameter	05 mm	Provided	MR
<b>7</b>	<b>Automatic Fire Detection and Alarming System:</b>			
A	Type of detectors	Smoke & Heat	Provided /	MR
B	Location of main panel	Ground floor entry gate no. 01	Provided	MR
C	Location of repeater panel	In main building control room	Provided	MR
D	Alternate source of power	Batter & DG Set	Provided	MR
E	Hooters location	Staircase	Provided /	MR
<b>8</b>	<b>MOEFA:</b>	Required	Provided /	MR
<b>9</b>	<b>Public Address System:</b>	Required	Provided /	MR
<b>10</b>	<b>Automatic Sprinkler System:</b>			
A	Basement	Required	Provided /	MR
B	Upper floor	Required	Provided /	MR
C	Sprinkler above false ceiling	Required	Provided /	MR
<b>11</b>	<b>Internal Hydrants:</b>			
A	Size of riser/down-comer	150mm	Provided	MR
B	No. of hydrants per floor	Required one no. in each Audi.	Provided	MR
C	Hose box	Required	Provided	MR
<b>12</b>	<b>Yard Hydrants:</b>			
A	Total number of hydrants	05 nos.	05 nos.	MR
B	Hose box	05 nos.	05 nos.	MR
<b>13</b>	<b>Pumping Arrangements:</b>			
<b>1</b>	<b>Ground level</b>			
A	Discharge of main pump	2850 LPM	2850 LPM /	MR
B	Head of main pump	120 M	120 M /	MR
C	Number of main pumps	02 nos.	02 nos.	MR
D	Jockey pump out put	180 LPM	180 LPM /	MR
E	Jockey pump head	120 M	120 M /	MR
F	Standby pump out put	2850 LPM	2850 LPM /	MR
G	Standby pump head	120 M	120 M /	MR
H	Water Curtain Pump	900 LPM	900 LPM	MR
I	Auto starting /manual stopping	Auto	Provided	MR
J	Pump house access	Required	Provided	MR
<b>2</b>	<b>Terrace Level</b>			
A	Discharge of pump	N/A	N/A	N/A
B	Head of the pump	N/A	N/A	N/A
C	Power supply	N/A	N/A	N/A
D	Auto starting of pump	N/A	N/A	N/A

W


W

14 Captive Water Storage for Fire Fighting:		Common with Mall Building		
A	Underground tank capacity	2,00,000 Liters	2,00,000 Liters	✓ N/A
B	Draw-off connection	Required	Provided	MR
C	Fire service inlet	Required	Provided	MR
D	Access to tank	Required	Provided	✓ MR
E	Overhead tank capacity	20,000 liters	20,000 liters.	MR
15	Exit Signage:	Required	Provided	MR
16 Provision of Lifts:				
A	Pressurization of lift shaft	Required	Provided	MR
B	Pressurization of lift lobby	Required	Provided	MR
C	Communication in lift car	Required	Provided	MR
D	Firemen's grounding switch	Required	Provided	MR
E	Lift signage	Required	Provided	MR
17	Standby Power Supply:	Required	Provided	MR
18 Refuge Area:				
A	Total area	N/A	N/A	N/A
B	Location	N/A	N/A	N/A
19 Fire Control Room: Common with Mall Building/Repeater panel in cinema bldg.				
A	Detector system panel	Required	Provided	MR
B	Flow switch panel	Required	Provided	MR
C	PA system panel	Required	Provided	MR
D	Battery backup	Required	Provided	MR
E	Building floor plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	Required	Provided	MR

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The earlier shortcomings issued vide letter no. F6/DFS/MS/Cinema/NDZ/2024/401 dated 15.07.2024 by this department have been rectified by the management.

Keeping in view of the substantial compliance of the minimum standards of fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

No file is pending with me before disposal of this case.

  
 Signature of the Inspecting Officer  
 Name Yashwant Singh Meena  
 Designation ADO (L.N)

DY. CFO/NDZ

*L.V.P*  
*22/07*

C.F/O.

*Please speak*

*24/7/2024*

DY CFO (NDZ)

Sir,

- spoken with CFO.

- Joint inspection has already been carried out by DyFO(NDZ) & ADO(LN) on 05/07/24.

- This inspection was carried out by ADO(LN) to verify the shortcomings rectification.