

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001 ८९५ राजादी व अमृत महोत्सव

No.F6/DFS/MS/Hostel/SZ/2024/ 40

Dated: 02 08 2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Old Girls Hostel Building at Rajkumari Amrit Kaur College of Nursing, Joship Broz Tito Marg, Lajpat Nagar-IV, New Delhi, comprised of Ground + 06 upper floors owned & occupied by Rajkumari Amrit Kaur College of Nursing have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by a team of officers concerned of Delhi Fire Service on 25.07.2024 in the presence of Mr. Varun and found that the building/premises (Ground + 06 upper floors) is fit for occupancy of Group-A "Residential Building (Hostel Building)" with effect from .22.22.4...... for a period of five years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on....02 08 2024 .. at New Delhi by

ul Garg) Director

Delhi Fire Service

Copy to:-

- 1. The Executive Engineer (Building), South DMC, 9th floor, Dr. SPM Civic Centre, JLN Marg, New Delhi.
- 2. The Owner/Occupier/Manager, M/s Old Girls Hostel Building at Rajkumari Amrit Kaur College of Nursing, Joship Broz Tito Marg, Lajpat Nagar-IV, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Department and approval shall be obtained thereto before occupancy of the same.

| 1 | | e & address of the building | Amrit Kaur C | Hostel Building at ollege of Nursing, ipat Nagar-IV, Nev | Joship Broz | |
|-------------|---|--|---|--|-------------------|--|
| 2 | Build | ding is comprised of | ASSESSMENT OF THE PARTY OF THE | dential (Hostel build | ding) | |
| 3 | | e of occupancy | | dential (Hoster build | uilig) | |
| 4 | Туре | of case | New case | | | |
| 5 | Deta | ils of previous FSC | Nil | | | |
| | Fire | safety direction letter no. | BBL-1983 & N | IBC-2016 | | |
| 6 | | of inspection | 25.07.2024 | | | |
| 7 8 | Nam | e of the inspecting officers | Manoj Kumar Sharma, DO (SD) & Rajesh Kumar Shukla, ADO (M. Road) | | | |
| 9 | Name of the designation of officer From the building side 1074 | | | | | |
| | From | of construction | 1974 | | | |
| 10 | | | Outdoor diary no. 3384 dated 25.06.2024 | | | |
| 11 S. No | 36:- | imum standard of Fire vention and Fire Safety U/R 33 | Requirements as per BBL1983 | Provide at site | Remarks MR/NMR | |
| | | | | The Property of the last of th | 1 MD | |
| 1 | | ess to Building Road width | 6.0 m | 6.0 m | MR NA | |
| | A B | Gate width | NA | NA | 722 22 40 | |
| | | wild afinternal roads | Required | 6.0 m | MR | |
| | C Width of internal roads Required 6.0 iii Number, Width, Type & Arrangement of Exits | | | | | |
| 2 | A | No. of staircase: | 191 | | MR | |
| | A | 77 0-00 | 02 nos. | Provided | NA | |
| | σ | a) Upper floor b) Basements | NA | NA | 1177 | |
| | | Width of the staircase: | 19 nterior | 143 & 120 cms | MR (old | |
| | В | a) Upper floors | 125 & 75 | 143 & 120 cms | building) | |
| | -75-1 | a) -FF | cms | NA | NA | |
| | PP ! | b) Basements | NA | 1177 | | |
| | C | Protection of Exits | TATA | NA | NA | |
| | | a) Fire check door | NA NA | NA | NA | |
| | - 54 | b) Pressurization | 01 no. | 02 nos. | MR | |
| | D | No. of continuous staircase to terrace: | | Provided | MR | |
| | E | Width of the corridor | 100 cms 1.0 mtrs | 1.0 mtrs (final | MR · | |
| | F | Door size | 1.0 mus | exits) | | |
| 3 | Cor | npartmentation: | NA | NA | NA | |
| | A | Fire Check doors Sealing of horizontal & vertical | Required | Provided | MR | |
| | | opening | NA | NA | NA | |
| | C | Fire rating of shaft Doors | NA NA | NA | NA NA | |
| | D | Water curtain | NA NA | NA | NA | |
| | F | Fire dampers | INA | Thought Inc. | NA | |
| 4 | Sm | oke management System: | NA | NA | NA NA | |
| | A | Basements | NA | Natural | | |
| | В | Upper floors | 1970 | day in | MR | |
| 5 | Fire | e extinguishers | 36 nos. | 36 nos. | | |
| | A | Total numbers | CO ₂ , ABC | CO ₂ , ABC | MR | |
| | В | Types | ISI marked | Provided | MR | |
| | C | ISI marking | 151 marked | | Du | |

| | ha las | N/15 | | | | | |
|-------|---|-----------------------|---|----------|--|--|--|
| T ==: | Land Land | | | | | | |
| | rst Aid Hose Reel | | | MD | | | |
| A | Total no. at each floor | 02 nos. | 02 nos. | MR | | | |
| B | Length of hose reel | 30 mtrs | 30 mtrs | MR | | | |
| C | Nozzle diameter | 5 mm | 5 mm | MR | | | |
| Αι | tomatic Fire Detection and Alarm Sy | | | | | | |
| A | Type of detectors | NA | NA | NA | | | |
| ·B | Location of main Panel | NA | NA | NA | | | |
| C | Location of repeater panel | NA | NA | NA | | | |
| D | Alternate power source | NA | NA | NA | | | |
| E | Hooter's location | NA | NA | NA | | | |
| M | OEFA | Required | Provided with talk back system | MR | | | |
| Pu | blic Address System | NA | Provided | NA | | | |
| Aı | tomatic Sprinkler System | | * | | | | |
| A | Basement | NA | NA | NA | | | |
| В | Upper floor | NA | NA | NA | | | |
| C | Sprinklers above false ceiling | NA | NA | NA | | | |
| In | | | | | | | |
| A | Size of the riser/down comer | 100 mm | 150 mm | MR | | | |
| В | No. of hydrants per floor | 02 nos. | 02 nos. | MR | | | |
| C | | 02 nos. | 02 nos. | MR | | | |
| Y | ard Hydrants | | | 7 | | | |
| A | Total no. of hydrants | NA | NA | NA | | | |
| В | Hose box | NA | NA | NA | | | |
| Pı | imping arrangements | | | | | | |
| A | Ground Level | | The same of the | | | | |
| | a) Discharge & head of main pump | NA | NA | NA | | | |
| 1 | b) Number of main pump | NA | NA | NA | | | |
| 1 | c) Discharge & head of jockey | NA | NA | NA | | | |
| | pump | 80. | | 1121 | | | |
| | d) Discharge & head of Standby pump | NA . | NA | NA | | | |
| | e) Auto starting/ manual stopping | NA | NA | NA | | | |
| В | Terrace Level | 5785 | | IAM | | | |
| 1 | a) Discharge of terrace pump | 900 LPM | Provided (2nos.) | MR | | | |
| 1 | b) Head of terrace pump | 40 mtrs | Provided (2nos.) | MR | | | |
| | c) Alternate power supply | Required | Provided | MR | | | |
| | d) Auto starting of pump | Required | Provided | MR | | | |
| Ca | aptive Water Storage for Fire Fighting | | TTOVICEU | IVIK | | | |
| A | Underground tank capacity | NA | NA | NIA | | | |
| В | Draw off connection | NA | NA NA | NA NA | | | |
| C | Fire Service Inlet | NA | NA NA | NA NA | | | |
| E | Access to tank | NA | NA NA | | | | |
| D | Overhead tank capacity | 25,000 Ltrs | Provided | NA | | | |
| - | it Signage | Required | Provided | MR | | | |
| | ovision of lift | - sequired | TTOVIGEG | MR | | | |
| A | Pressurization of lift shaft | NA | NA | NIA | | | |
| B | Pressurization of lift lobby | NA NA | NA NA | NA | | | |
| C | Communication in lift car | Required | Provided | NA | | | |
| D | Fireman switch | NA | NA NA | MR | | | |
| - | Mark Salver Co. Salver | | 7. M. | NA | | | |
| - | | | | MR MR | | | |
| | Lift signage | v assumente ann steam | v advocator de stat | | | | |

M/s Old Building (Hostel Block) at RAK College of Nursing, Joship Broj Tito Marg, Lajpat Nagar-IV, New Delhi.





| 18 | Refuge Area | | | | | | |
|----|---|--|----|-------|----------|--|--|
| | A | location | NA | NA | INA | | |
| | В | Total area | NA | | NA NA | | |
| 19 | Fire Control Room | | | | | | |
| | A | Fire Detection System panel | NA | NA | N/A | | |
| | В | Flow switch panel | NA | NA | NA NA | | |
| | C | P A system panel | NA | NA | NA | | |
| | D | Battery backup | NA | NA NA | NA NA | | |
| | E | Building floor plan | NA | NA NA | NA NA | | |
| 20 | Special Fire Protection for special risk if any | | | | | | |
| | A | Special Fire Protection system for Protection of Special Risk, if any: | NA | | NA | | |

LEGENDS-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the Rules, it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Manoj Kumar Sharma Designation DO (SD) Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

Director My A

(1) in four up for eignatures pla

Mrk