

### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/2024/School/ 737

Dated: 31/07/2024

#### FIRE SAFETY CERTIFICATE

Certified that the Dhanpatmal Virmani Senior Secondary School located at Roop Nagar, Delhi-110007 comprised of Ground & 02 upper floors only owned/ occupied by Dhanpatmal Virmani Senior Secondary School was issued Fire Safety Certificated vide this office letter no. F6/DFS/MS/2007/1679 dated 22.06.2007. The premise was re-inspected by the officer concerned of this department on 20.07.2024 in the presence of Sh. Pradeep Mann (Teacher) and found that the said premises have deemed complied with the fire prevention and fire safety requirements of circular issued by Director of Education vide letter no 262-362 dated 17.01.2005 and the building/ premise is fit for occupancy class "Group B Educational" with effect from ...31. .07. .2024 for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 31 07 2024. at New Delhi

Director 011-23414000

#### Copy to: -

1. The Director of Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Principal, Dhanpatmal Virmani Senior Secondary School located at Roop Nagar, Delhi-110007.

# Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Delhi Fire Service Rules 2010. The form http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

## INSPECTION REPORT

1. Name & address of the building

Type of Occupancy

3. Composition of building

4. Type of Case

5. Details of previous NOC

6. Fire Safety directives letter No

7. Date of inspection 8. Name of the Inspecting Officers

9. Name and designation of officers

from the building side

10. Year of Construction

11. Applicant's letter No.

: Dhanpatmal Virmani Sr. Sec. School at Roop Nagar, Delhi-110007.

: Educational

: ADO (RN)

: 1963

: Ground plus 02 upper floors only

: Renewal

: F6/DFS/MS/2007/1679 Dated: 22.06.2007

: Director of education circular dated 17.01.2005

: 20.07.2024

: Sh. Pradeep Mann (Teacher)

: Online e-mail dated: 04.07.2024

		um Standards on fire prevention and fire safety U/R 33	Director. Of Educa Circular dated: 17.01 Requirements		Remarks MR/NMR		
		building	06	06m	MR		
		Road width	06m				
	• 1	Gate width	4.5m	05m	MR		
	•	Width of internal road	NA .	NA	NA		
2	Number, Width, Type & Arrangement of Exits						
	a. Numb	er of staircases					
	•	Upper Floors	02	03	MR		
	•	Basements	NA	NA	NA		
	b. Width	of staircases					
	•	Upper Floors	c	n, 1.25m GF to FF & 1.25 onnected with adjoining building GF to Terrace	m MR (being old case		
		Basements	NA	NA NA	NA		
	082000000000000000000000000000000000000	tion of exits					
	•	Fire check door	NA	NA	NA		
	•	Pressurization	NA	NA	NA		
	1990012142212121212	f continuous staircases to terrace	01	01	MR		
	e. Width	of Corridor	NA	NA	NA		
	f. Door	Size	1m	1.10m	MR		
3	Compai	tmentation.	***				
	•	Fire check door	NA	NA	NA		
		Sealing of electrical shafts	NA	NA	NA		
		Fire Rating of shaft door	NA	NA	NA		
	•	Water Curtain	NA	NA	NA		
	•	Fire Dampers	NA	NA	NA		
4	Smoke	Management System.			Tan .		
	•	Basements	NA	NA	NA		
	•	Upper floors	Required	Natural Ventilation	MR		
5	Fire	Extinguishers					
	•	Total numbers	12nos	22nos	MR		
	•	Туреѕ	ABC/Co2	ABC-12/Co2-10	MR		
	•	ISI marking	Yes	Yes	MR		

	THE AMERICAN POLICE TO THE PROPERTY OF THE PRO				
6	First-Aid Hose Reels.			1	
	Total numbers on each floor	01	Provided	MR	
	Length of hose reel hose	30m	Provided	N.S.	
	Nozzle diameter	5mm	Provided	MR	
_	Automatic fire detection and alarming system		-		
	A 1 1 100000	NA	NA NA	NA	
	Type of detectors     Location of Main Panel	NA	NA	NA	
	* of Demoster Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
	1 Hootels Becaute.	NA NA	NA NA	NA	
}	MOEFA	NA NA	NA NA	NA NA	
¥	Public Address System.	101		SANAR SANAR	
0	Automatic Sprinkler System.		NA NA	NA	
	Basement	NA		NA NA	
	Upper Floor	NA .	NA	PARK	
	Sprinkler above false ceiling	NA	NA	NA	
1	Internal Hydrants		0		
	Size of riser/down-comer	01	Provided	MR	
	Number of hydrants per floor	30m	30m	MR	
	Hose Box	5mm	5mm	MR	
2	Yard Hydrants.			•	
2	Total number of hydrants	NA	. NA	NA	
	Hose Box	NA	NA	NA	
13	Pumping Arrangements.				
	Ground Level			•	
	> Discharge of main Pump	N/A	N/A	N/A	
	> Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	➤ Standby Pump out put	N/A	N/A	N/A	
	> Standby Pump Head	CONTRACT.	N/A	N/A	
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N/A		N/A	
		N/A	N/A	N/A	
	Terrace level	1	A STATE OF THE STA	MR	
	➢ Discharge of pump	450 LPM	Provided	MR	
	➤ Head of the pump	40m	40m	975	
	> Power Supply	Required	Provided	MR	
_	> Auto Starting of pump	Required	Provided	MR	
4	Captive Water Storage for fire fighting.		54		
	Underground tank capacity	NA	NA	NA	
	> Draw-off connection	NA	NA	NA	
	➢ Fire service inlet	NA	NA	NA	
	> Access to tank	13/4	4344	193553	

	• (	verhead Tank capacity	5,000 LTR	Provided	MR
;	Exit Sign		Required	Provided	MR
6	Provision		N/A	N/A	N/A
	•	ressurization of Lift Shaft	15-40/20-03	N/A	N/A
		Pressurization of Lift lobby	N/A	N/A	WAXA-1780
			N/A	N/A	N/A
		Communication In lift Car	N/A	14 Table 14	N/A
	•	Fireman's Grounding Switch	N/A	N/A	IVA
		Lift Signage		N/A	N/A
		Lift Signage	N/A		N/A
17	Standby	power supply	N/A	N/A	1
1.7	Standby	power sepp.			
18	Refuge	Area.		N/A	N/A
	<b>A</b>	Total Area	N/A	160	N/A
	8	Location	N/A	N/A	
	>			li estate	
19	Fire Co	ntrol Room	N/A	N/A	N/A
		Detector System Panel	180-000-00-	N/A	N/A
		Flow Switch Panel	N/A	INCA	
	.   1		N/A	N/A	N/A
	1	PA System Panel	SECULIAR SEC	N/A	N/A
		Batter backup	N/A	N/A	~
		<b>Building Floor Plans</b>	N/A	N/A	N/A
		1380		N/A	N/A
20	Special	Fire Protection Systems for on of special Risks, if any:	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/School/2022/726 dated 01.12.2022.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular issued vide letter of even no. F6/DFS/MS/2007/1679 dated 22.06.2007 renewal under rule 35(6) of the Delhi Fire Service Rules, 2010 is recommended.

Signature of the Inspecting Officer Name:- C.L. Meena

Designation:- Asst. Div. Officer (RN)

DO (NW)
24/04/1024

tel 1/m

Anyth

conf. .. P.T.O.