

No.F.6/DFS/MS/School/2024/SZ/ 728

Dated: 29/07/2024

FIRE SAFETY CERTIFICATE

Certified that the Education Point Convent School, Plot No.-3 & 4, Vikas Nagar, Som Bazar Road, New Delhi-110059, comprised of ground floor plus three upper floors, owned/occupied by Education Point Convent School was issued FSC by this department vide letter no. F.6/DFS/MS/School/2021/SZ/539 dated 27.07.2021. The School building was reinspected by the officer concerned of this department on 17.07.2024 in the presence of Sh. Vivek Tyagi (Admin.) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Educational" w.e.f. 29 07 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 29 07 2024 at New Delhi.

Delhi Fire Service

Copy to:-

1. The Chairman, Education Point Convent School, Plot No.-3 & 4, Vikas Nagar, Som Bazar Road, New Delhi-110059.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

Following fire safety directives must be adhered to: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

MID

INSPECTION REPORT

1. Name & address of the building: Education Point Convent School, Plot No.-3 & 4, Vikas Nagar, Som

Bazar Road, New Delhi-110059

2. Type of Occupancy : Educational

3. Building Comprised of : Ground plus three upper floors.

4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/School/2021/SZ/539 dated 27.07.2021

6. Fire Safety directives letter No : N/A

7. Date of inspection : 17.07.2024

8. Name of inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Vivek Tyagi (Admin.)

10. Year of Construction : 2010-11 (GF & FF) & 2016 (SF) & 2017 (TF)

11. Applicant's letter No. : Online email Id epcschool.3@yahoo.com dated 28.06.2024

S. No.		um Standards on fire prevention and ety U/R 33	NBC requirements	Provided at site	Remarks MR/NMR	
1.	Access to building					
		Road width Gate width Width of internal road	Accessible 06 mtrs 4.5 mtrs N/A	06 mtrs 5.65 & 5.3 mtrs N/A	M/R M/R N/A	
2.	Number, Width, Type & Arrangement of Exits					
	a. Num	ber of staircases Upper Floors Basements	02 No.'s N/A	03 No.'s N/A	M/R N/A	
	b. Widt	h of staircases Upper Floor Basements	150 each N/A	150 m each N/A	M/R N/A	
		ction of exits Fire check door Pressurization	N/A N/A	N/A N/A	N/A N/A	
	d. No. o	of continuous staircases to	Required 1.50 m	Provided 2.45m	MR M/R	
		h of Corridor Size	1.00 m	1.03 m & 1.2 m at TF (double door)	M/R	
3	Compar	tmentation				
		ire check door ealing of electrical shafts	N/A N/A	N/A N/A	N/A N/A	
= ^	• I	ire Rating of shaft door	N/A	N/A	N/A	
-		Vater Curtain lire Dampers	N/A N/A	N/A N/A	N/A N/A	
4.		Ianagement System asements	N/A	N/A	N/A	
	• [Jpper floors	Required	Natural ventilation provided	M/R	
5.	Fire Ext	nguishers				
	251	otal numbers	11 no's	Provided	MR	
		ypes 5 marking	ABC/CO ₂ type ISI marked	Provided Provided	MR MR	

MIB

	Total numbers on each floor	01 no.	Denvided		
	Length of hose reel hose	30 mtrs	Provided Provided	MR	
	Nozzle diameter	5 mm	Provided	MR MR	
	Automatic fire detection and alarming system				
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A	444	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A N/A	
	Hooters' Location	N/A	N/A	N/A	
8.	MOEFA	N/A	N/A	N/A	
9.	Public Address System	N/A	N/A	N/A	
10.	Automatic Sprinkler System		1 8177		
	Basement	N/A	N/A	N/A	
	• Ground Floor	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants			= = = = = = = = = = = = = = = = = = =	
	Size of riser/down-comer	100 MM	100 MM	MD	
	Number of hydrants per floor	1 No.	1 No.	MR MR	
	Hose Box	1 No.	1 No.	MR	
12.	Yard Hydrants		Roman Cappins	Actes A	
	Total number of hydrants	N/A	N/A	NT/A	
	Hose Box	N/A	N/A	N/A N/A	
13.	Pumping Arrangements				
	Ground Level		49 444 4	bar	
	Discharge of main Pump	27/2	[40]		
	➤ Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	➤ Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	➤ Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A N/A	
		N/A	N/A	5.555 %-7.55	
	> Pump House Access	N/A	N/A	N/A	
	Terrace level Dial		IVA	N/A	
	Discharge of pump	450 LPM	Provided	and resident	
	- read of the pump	30 mtrs	Provided	MR	
	1 ower Supply	Required	Provided	MR	
	state starting of pump	Required	Provided	MR MR	
4.	Captive Water Storage for fire fighting		- 10 Page	IVIK	
	Underground tank capacity				
	Draw-off connection	N/A	N/A	NI/A	
	Fire service inlet	N/A	N/A	N/A	
- 1	> Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	N/A	N/A	N/A	
	Tunk capacity	10000 ltrs	Provided	N/A	
	Exit Signage.			MR	
		Required	Provided	MR	
	Provision of Lifts.				

1/1

N	10
1	

,	Pressurization of Lift Shaft	N/A	N/A	N/A		
	 Hressurization of Lift lobby Communication In lift Car Hireman's Grounding Switch Lift Signage 	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
17.	Standby power supply	- 6. 4	Uni			
18.	Refuge Area.	VA V	N/A	N/A		
10.	> Total Area > Location	N/A N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel Flow Switch Panel PA System Panel	N/A	N/A	N/A		
		N/A	N/A			
		N/A	N/A	N/A		
	and the state of t	N/A	N/A	N/A		
	Battery backup Building Floor Plans	N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC was issued vide letter no. F.6/DFS/MS/School/2021/SZ/539 dated 27.07.2021, renewal under the under rule 35 of the Delhi Fire Service Rules 2010 it is recommended.

Signature of Inspecting Office Lory

Name: - R.K. Yadav

Designation: - ADO (JKP)

DO (South West)

23 7 200

Dinecter

mykin