

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6 DFS/MS/School/2024/SZ/753

Dated: 02/08 / 2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Good Samaritan School, Basti Vikas Kendra, Sanjay Camp, Dakshinpuri, New Delhi 110062 comprised of Ground floor owner/occupied by M/s Good Samaritan School, have complied with the fire prevention and fire safety requirements in with Directorate of Education Circular No F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education, Govt. of NCT of Delhi and verified by officer concern of this department on 22/07/2024 in the presence of Ms. Tulsi (Admin) and that the premises is fit for occupancy class "Educational, Group-B" (School) with effect from 02/08/2024 for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Pelhi Fire Service Rules, 2010.

Issued on <u>02/08</u>,2024 at New Delhi by

Copy to: -

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi -54.

2. M/s Good Samaritan School, Basti Vikas Kendra, Dakshinpuri, New Delhi 110062.

Conditions for the validity of Fire Safety Certificate:-

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. This certificate cannot be treated as regularization of unauthorized construction, if any.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



9	INSPI	ECTION REPORT					
1	Name & Address of the Building	M/s Good Samaritan School, Basti Vikas Kendra, Sanja Camp, Dakshinpuri, New Delhi 110062.					
2	Type of Occupancy	Educational, Group-B					
3	Building Comprised of	Ground floor only					
4	Type of Case	New Case					
, 5	Details of Previous NOC	Nil mat soil &					
6	Fire Safety Directives Letter No	DOE Circular dated 01/03/2011					
7	Date of Inspection	22-07-2024	Foreign at the U.S. of				
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)					
9	Name & Designation of Officers from the building side	Ms. Tushi (Admin)					
10	Year of construction	1992					
11	Applicant letter No.	/2024	1 5				
S. No	and Fire Safety U/R 33	UBBL/NBC requirements	Provided at Site	Remarks MR/NMR			
1	Access to Building.	50	sicontil spice. If	1 1/0			
1	Road width	06 mtr	Provided	MR -NA-			
	Gate width	-NA-	-NA-				
	Width of internal road	-NA-	-NA-	-NA-			
2	Number, width, type & arrangement of exits.	4.65	A Philippinal Competition				
	a) Number of Staircase		been forming for a				
	> Upper floors.	-NA-	-NA-	-NA-			
	> Basement floor.	-NA-	-NA-	-NA-			
	b) Width of Staircase		THE TOP OF				
	▶ Upper floors	-NA-	-NA-	-NA-			
	> Basement floor	-NA-	-NA-	-NA-			
	c) Protection of exits	Alter M. The	DATES IN THE B				
	> Fire check door	-NA-	-NA-	-NA-			
	> Pressurization	-NA-	-NA-	-NA-			
		-NA-	-NA-	-NA-			
	d) No. of continuous staircase to terrace e) Width of corridor	(Park 19 2 cm)	-NA-	-NA-			
	[] [] [] [] [] [] [] [] [] []	-NA-	ALEXALI CARCILITATES	No. of			
	f) Door size	1.0 mtr	Provided	MR			
3	Compartmentation.	* Pressortane of lift shall. * Pressortane of lift labby.					
-	Fire check door.	A MARKA	-NA-	-NA-			
	Sealing of electrical shafts.		-NA-	-NA-			
	Fire rating of shaft door.	-NA-	-NA-	-NA-			
	Water curtain	-NA-	-NA-	-NA-			
	Fire dampers.	-NA-	-NA-	-NA-			
4.	Smoke Management system.	71	mu istoT •				
	Basement	-NA-	-NA-	-NA-			
	Upper floors	-NA-	-NA-	-NA-			
5.	Fire Extinguishers.	financiano	men retend .				
	Total numbers	Required	06 Nos	MR			
	Types	ABC type	ABC Type	MR			
	ISI Marking	ISI mark	Provided	MR			
5.	First Aid Hose Reels.	mija n	out and the form				
	Total numbers on each floor.	-NA-	-NA-	-NA-			
	Length of hose-reel hose.	-NA-	Arran -NA-	-NA-			
	Nozzle Diameter	-NA-	-NA-	-NA-			
,	Automatic fire detection & alarming system.			*14.5			
-	Type of detectors	-NA-	-NA-	NIA			
- 1	Location of Main Panel	-NA-	-NA-	-NA-			
-	Location of Repeater Panel	-NA-	-NA-	-NA-			
		-NA-	-NA-	-NA-			
		-IN/A-	-A 14 A	-NA-			
	Alternate source of power						
	Alternate source of power Hooter's location	-NA-	-NA-	-NA-			
_	Alternate source of power						



	Basement	-NA-	-NA-	-NA-
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.	2000000	y 1	-11/4
	Size of Riser/Down-comer	-NA-	-NA-	-NA-
	Number of Hydrant per floor	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	
12.	Yard Hydrants.	11/ 11/	-IVA-	-NA
	Total number of hydrants.	-NA-	NIA	1
	Hose box.	-NA-	-NA-	-NA
13.	Pumping arrangements.	-14A-	-NA-	-NA
10.	Ground Level		9 00	
		374		
	Be or many.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	> Jockey Pump output.	-NA-	-NA-	-NA-
	> Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	> Pump house access.	-NA-	-NA-	-NA-
	Terrace Level		746 - Wasy	.,,,
	➢ Discharge of pump	-NA-	-NA-	-NA-
	➤ Head of pump.	-NA-	-NA-	-NA-
	Power supply.	-NA-	-NA-	-NA-
Y	Auto starting of pump.	-NA-	-NA-	-NA-
14.	Captive water storage for fire fighting.	. 14.5		-NA-
	Underground tank capacity.	NA	-NA-	-NA-
1963	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	> Access to tank.	-NA-	-NA-	
	Overhead tank capacity.	-NA-	-NA-	-NA-
15.	Exit Signage.	Required	Provided	-NA-
16.	Provision of Lifts.	AMILIA	Flovided	MR
	Pressurization of lift shaft.	-NA-	NIA	377
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-		-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
			-NA-	-NA-
17.	Lift signage. Standby Parent Survey.	-NA-	-NA-	-NA-
	Standby Power Supply	-NA-	-NA-	-NA-
18.	Refuge Area		Entertail Land	
	Total area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
19.	Fire Control Room.		400 FMR +	
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA
	Battery backup. Building Grant	-NA-	-NA-	-NA
20.	Building floor plan. Special Fire P. A. C.	-NA-	-NA-	-NA
20,	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA



The fire protection system provided in the building were randomly checked and found

functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

DO (South

F.-1. fetter is spritisp