

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/School/2024/SZ

29/07/2024 Dated:

FIRE SAFETY CERTIFICATE

Certified that the Gyan Bharti Convent School at Plot No. 16-17, Arjun Park, Najafgarh, New Delhi-110043, building comprised of ground plus two upper floors but school running at ground and first floor only, owned/occupied by Gyan Bharti Convent School was issued FSC for Ground plus one upper floor by this department vide letter no. F.6/DFS/MS/School/2018/SZ/2544 dated 26.11.2018. The school was re-inspected by the officer concerned of this department on 15.07.2024 in the presence of Sh. Vikash (Manager) and found that Gyan Bharti Convent School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (Ground plus and first floor only) is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

Issued on 29/07/2024 at New Delhi.

Director

Delhi Fire Service

Copy to:-

1. The Manager, Gyan Bharti Convent School, Plot No. 16-17, Arjun Park, Najafgarh,

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

Following fire safety directives must be adhered to: -

1. All the fire safety arrangements provided therein shall be maintained in good working

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning

6. The certificate may not be treated in any case for the regularization of the unauthorized

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

INSPECTION REPORT

1. Name & address of the building :

Gyan Bharti Convent School, Plot No. 16-17, Arjun Park, Najafgarh,

New Delhi-110043.

2. Type of Occupancy

Educational 3. Building Comprised of

4. Type of Case

Ground plus two upper floors but school running at ground and first floor only

Renewal

5. Details of Previous NOC

F.6/DFS/MS/School/2018/SZ/2544 dated 26.11.2018 (For GF & FF Only)

6. Fire Safety directives letter No :

N/A

7. Date of inspection

15.07.2024

8. Name of Inspecting Officer

From the building side

A.D.O. R.K. Yadav

9. Name and designation of officers

Sh. Vikas (Manager)

10. Year of Construction

2006(GF) 2011 (FF) & 2017 (SF)

11. Applicant's letter No.

: Nil, dated 21.06.2024

S. No.		Standards on fire prevention afety U/R 33	Requirements as per FSC dt. 26.11.2018	Provided at site	Remarks MR/NMR
1.	Access to	building		14.70	and the
-	• G	ead width te width idth of internal road	Accessible 06 mtrs 4.5 mtrs N/A	04 to 06 mtrs Directly accessible from road N/A	M/R being old cas M/R N/A
2.	Number,	Width, Type & Arrangement of			0 1 2
	a Number	of staircases			1470
_	THE RESERVE OF THE PARTY OF THE	pper Floors	02 No.'s	02 No.'s	M/R
-		sements	N/A	N/A	N/A
		oper Floor	150 cms/additional staircase of 75 cms if less than 150 cms	120 & 120 cms	M/R
	• Ba	sements	N/A	N/A	N/A
	c. Protection	n of exits		7	21/4
		e check door	N/A	N/A	N/A
		essurization	N/A	N/A	N/A
- 1	J. No offe	ontinuous staircases to	N/A	N/A	N/A
	terrace	AW	N/A	N/A	N/A
		f Corridor	100 cms	88 cms	M/R, being old case
	Compartme			Part and I	
• _	Comparime	entation	37/4	N/A	N/A
		check door	N/A	N/A	N/A
	• Seal	ing of electrical shafts	N/A	N/A	N/A
		Rating of shaft door	N/A	32/11/11	N/A
		er Curtain	N/A	N/A	N/A
		Dampers	N/A	N/A	1414
	Smoke Man	agement System	N/A	N/A	N/A
	Base	ements		Natural ventilation	M/R
	• Upp	er floors	Required	provided	433,500,000
	Fire Extingu	uishers	-7		M/R
		l numbers	04 no's	Provided	M/R
	 Type 	S	ABC/CO ₂ type ISI marked	Provided Provided	M/R
	• IS m	arking	151 marked	Provided	and Arman

1 N70

j.	First-Aid Hose Reels			
	Total numbers on each floor	N/A	N/A	
	Length of hose reel hose	N/A	N/A	N/A
	Nozzle diameter	N/A	N/A	N/A
7.	Automatic fire detection and alarming sy	/stem	N/A	N/A
		N/A	le fight to	
	Type of detectors Location of Main Panel		N/A	N/A
	Location of Main Panel Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A
	MUCESAN PRIMAN - PERFECTIONEMENT	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	BLACK NA BA	Male	
	Basement	N/A	N/A	
	Ground Floor	N/A	N/A N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants		IVA	N/A
	Size of riser/down-comer			
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants	N/A	N/A	N/A
	As the Springer of the			Transfer and the same of the s
	Total number of hydrants	N/A	Pht Control 1	elayer p
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	A	N/A	N/A
	Ground Level		- January	14W A
	Discharge of main Pump	WILL BETTER		J # 1
	riead of Main pump	N/A	N/A	H II
	Number of main number	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A		N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual	N/A	N/A	N/A
	Stopping	N/A	N/A	N/A
	> Pump House Access		N/A	N/A
	Terrace level	N/A		
	Discharge of pump		N/A	N/A
	Head of the pump	N/A	JP R HE S	2.314.3
	Power Supply	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A
		N/A	N/A N/A	N/A
	Captive Water Storage for fire fighting		.va	N/A
	Underground tank capacity		GSALIZ II. CALLINA	
	Draw-off connection	N/A	N/A	
1	Fire service inlet	N/A	N/A N/A	N/A
	➤ Access to tank	N/A		N/A
	Overhead Tank capacity	N/A	N/A	N/A
	Exit Signage.	N/A	N/A	N/A
-	XII Nignage		N/A	
F	Salt Signage.	N/A	N/A	N/A

	Provision of Lifts.		No Lift			
5	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
Ý	Standby power supply	N/A	N/A	N/A		
8.	Refuge Area.					
	\ m 114	N/A	N/A	N/A		
	Total AreaLocation	N/A	N/A	N/A		
9.	Fire Control Room					
		NI/A	N/A	N/A		
	Detector System Panel	N/A N/A	N/A	N/A		
	Flow Switch Panel	N/A N/A	N/A	N/A		
	PA System Panel	N/A N/A	N/A	N/A		
	Battery backupBuilding Floor Plans	N/A N/A	N/A	N/A		
).	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2018/SZ/2544 dated 26.11.2018, renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note: - As per undertaking given by the Principal (placed at C-27) School is running at ground floor and first floor only in a building comprised of ground plus two upper floors. Second floor is not use for school purpose and students' strength is less than 45 in each class room.

Signature of Inspecting Of

Name: - R.K. Yadav

Designation: - ADO (JKP)

DO (South West)

Mug-

Dineter

W/ 19/19/19

M