

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6 DFS/MS/School/2024/SZ/750

Dated: 02/08/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Paul George Global School located at Alaknanda, New Delhi 110017 comprised of Basement, Ground plus Four upper floors owner/occupied by St. George Education Society (Regd.) was granted Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2021/SZ/223 dated 12-03-2021. The said premise was re-inspected by officer concerned of this department on 23/07/2024 in presence of Mr. Raja (Admin) of the school and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and the building is fit for occupancy class "Educational Building Group - B" with effect from <u>62/08/</u> 2024 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on <u>\$2/\$8.</u> 2024 at New Delhi by

DELHI FIRE SER

Copy to: -

1. The Principal, Paul George Global School, located at Alaknanda, New Delhi -17

2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-54.

Conditions for the validity of Fire Safety Certificate:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

2. All the staff members must know the correct method of operation of firefighting

system.


3. This certificate cannot be treated as regularization of unauthorized construction, if

4. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."





1	Name & Address of the Building Paul George Global School, Alaknanda New				
0	dain me	Delhi-110019			
2	Type of Occupancy	Educational, Group-B (School)			
3	Building Comprised of	Ground + 04 upper floors.			
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/School/2021/SZ/223 dated 12-03-2021			
6	Fire Safety Directives Letter No	F6/DFS/MS/BP/2013/257 dated 29/08/2013			
7	Date of Inspection	23/07/2024			
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Raja (Admin)			
10	Year of construction	2015			
11	Applicant letter No.	Outdoor diary no 4232 dated 16/07/2024			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirements	Provided at Site	Remarks MR/NMR	
1	Access to Building.		and the same	1	
	Road width	9 mtr	Provided	MR	
	Gate width	5 mtr	Provided	MR	
	Width of internal road	6 mtr	Provided	MR	
2	Number, width, type & arrangement of e	xits.	Tue Tripped I		
904	a) Number of Staircase	20.60.00			
	> Upper floors.	Required	06 Nos	MR	
311	Basement floor.	Required	05 Nos	MR	
10.1	b) Width of Staircase	- Thoughton	Approximation of the second		
307	> Upper floors	1.50 mtr each	1.6 m x 2 & 2 m x 4	MR	
	> Basement floor	1.50 mtr each	1.6 m x 2 & 2 m x 3	MR	
		1.50 mu cach	1.0 111 X Z & Z 111 X 3	MIK	
	c) Protection of exits > Fire check door	D	17/31 5025:44.3 7	1 10	
SEE		Required	Provided	MR	
2017	> Pressurization	-NA-	-NA-	-NA-	
	d) No. of continuous staircase to terrace	Required	06 Nos	MR	
914	e) Width of corridor	1.5 mtr	2.84 m & 1.76 m	MR	
•	f) Door size	lm -	Provided	MR	
3	Compartmentation.				
	Fire check door.	Required	Provided	MR	
	Sealing of electrical shafts.	Required	Provided	MR	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
844	Water curtain	-NA-	-NA-	-NA-	
EFN/	• Fire dampers.	Required	Provided	MR	
4	Smoke Management system.		10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MIK	
HEZ	Basement	30 ACPH	Exhaust fan provide	1 100	
	Upper floors	12 ACPH	DECEMBER 15 - 2 9 (190)	24.	
5	Fire Extinguishers.	/ ICI II	-NA-	-NA-	
W	Total numbers	一	DESCRIPTION OF MARKET STREET	55	
Al-I	Types	70-	60 Nos	MR	
	ISI Marking	ISI marked	CO2 & ABC	MR	
6			Provided		
U	First Aid Hose Reels.		1.101,000	MR	
	Total numbers on each floor.		05 No et = 1.0		
	 Length of hose-reel hose. 	Hoss	05 No at each floor	MR	
154	Nozzle Diameter	Hose-reel	30m	MR	
7	Automatic fire detection & alarming system.		5mm	MR	
MILL	Type of detectors		A CONTRACTOR OF THE PARTY OF TH	IVIK	
	- JPS OF UCICCIONS	Required	Smoke type		





	Location of Main Panel Location of Main Panel	Required Control room		M
	Location of Repeater Panel	-NA-	Basement	MR
	Alternate source of nower	Required	Provided	-NA-
	Hooter's location MOEFA	Required		MR
	Public A d d	Required	Provided	MR
	Public Address System	Required	Every floors	MR
	Automatic Sprinkler System	required	Provided	MR
- 1	Basement	Paguinal	2 y di pelasik	
-	Upper floors	Required -NA-	Provided	MR
1	Sprinkler above false ceiling Internal Handard Properties		-NA-	-NA-
		-NA-	-NA-	-NA-
	Size of Riser/Down-comer	100	A THE RESERVE A	
	Number of Hydrant per floor	100 mm	Provided	MR
12	Tiose box	05	Provided	MR
12	Yard Hydrants.	05	Provided	MR
	Total number of hydrants	mineralistical stated the	Afternation of the parties of the	278.27
10	TOSE DOY	-NA-	-NA-	-NA-
13	Pumping arrangements.	-NA-	-NA-	-NA-
	Ground Level		NEW TINES	TVA
	Discharge of main number		CONTRACT OF	
	nead of main nume	2280 LPM	Provided	MR
	Number of main number	80 m	Provided	MR
	JOCKEV Pump output	01	Provided	MR
	Jockey Pump head	180 LPM	Provided	MR
	Standby Pump output	40 m	Provided	MR
	Standby Pump head	2280 LPM	Provided	MR
7.65	Auto Starting/Manual Stanning	80 m	Provided	MR
	➤ Pump house access.	Required	Provided	MR
NA.	Terrace Level	Required	Provided	MR
	Discharge of pump.	000 7 77 7	والمراجعة المراجعة	MIK
215	Head of pump	900 LPM	Provided	MR
718	➤ Power supply.	35 m	Provided	MR
4.4	Auto starting of nump	Required	Provided	MR
14	Captive water storage for fire fighting	Required	Provided	MR
31.8	Underground tank capacity	50,000 ltrs	3276 H 102 1	
41/	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
10	Overhead tank capacity.	25,000 Ltr	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	UIU	2.squired	Provided	MR
10	Pressurization of lift shaft.	Required	D-mid t	
	 Pressurization of lift lobby. 	Required	Provided	MR
	 Communication in lift car. 	Required	Provided	MR
	 Fireman's switch. 	Required	Provided Provided	MR
17.0	Lift signage.	Required		MR
17	Tower Supply	Required	Provided	MR
18	Refuge Area	roduien	Provided	MR
Stall.	Total area	-NA-	the sales and the	
1.3	Location		-NA-	-NA
19		-NA-	-NA-	-NA
	Detector system panel.			
	Flow switch panel.	Required	Provided	MR
10.34	a tow switch panel.	Required	Provided	11





20	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA
	 Building floor plan. 	Required	Provided	MR
	PA system panel. Battery backup.	Required	Provided	MR
		Required	Provided	MR

The fire protection system provided in the building / premises were test checked at random and found functional at the time of inspection.

Receping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/School/2021/SZ/223 dated 12-03-2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HO)

approved, F.T. Lettre in portup fore synature Pl , Mh