

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No.F.6/DFS/MS/Institutional/2024/SZ/504

Dated: 05/08/2024

FIRE SAFETY CERTIFICATE

Certified that Nursing Home located at Plot No B-2/5, Safdarjung Enclave, New Stilt, Ground plus Two upper floors Delhi-110029 comprised of Basement, owner/occupied by Unit of Nouvel Neptune Hospital LLP was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/Institutional/2021/SZ/454 dated 20/09/2021. The premise was re-inspected by officers concerned of this department on 23/07/2024 in the presence of Dr. Dileep Makhija and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class Group-C Institutional (Hospital) with effect from 05/08/2024 for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 05/08/2024 at New Delhi by

FIRE SER

Copy to: -

1. M/s Nouvel Neptune Hospital LLP, at Plot No B-2/5, Safdarjung Enclave, New Delhi-

2. The Executive Engineer (Bldg) Delhi Municipal Corporation, Green Park, New Delhi 110016.

Conditions for the validity of Fire Safety Certificate: -

1. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

2. All the staff members must know the correct method of operation of fire fighting

3. The basement shall be used strictly as per the provision of Building Bye Laws.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."





2		TON DEBORE			
	INSPECTION REPORT				
6 41 84	Name & Address of the Building	Nursing Home, The Neptune Hospital at Plot No B-2/ Safdarjung Enclave, New Delhi-110029			
2	Type of Occupancy	Institutional building, "Group-C" (Hospital)			
3	Building Comprised of	Basement, Stilt, Ground + 02 upper floors			
4	Type of Case	Renewal (57/454 4-4-4 20/00/200			
5	Details of Previous NOC	F6/DFS/MS/Institutional/2021/SZ/454 dated 20/09/202			
6	Fire Safety Directives Letter No	F6/DFS/MS/2021/BP/1691 dated 26.08.2021			
7	Date of Inspection	23/07/2024			
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers from the building side	Dr. Dileep Makhija			
10	Year of construction	2020			
11	Applicant letter No.	Outdoor diary no	4451 dated 23-07-2024	Remarks	
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL-2016 requirements	Provided at Site	MR/NMI	
,1	Access to Building.		45.70	MR	
	Road width	9 mtr	45.72 m	-NA-	
	Gate width	-NA-	-NA-	-NA-	
	Width of internal road	-NA-	-NA-	-IN/A-	
2	Number, width, type & arrangement of exits.		BOTH CHARLES		
	a) Number of Staircase	No. 64 De	Production in a section of	MR	
	> Upper floors.	02 Nos	02 Nos	MR	
	> Basement floor.	02 Nos	02 Nos	MIK	
	b) Width of Staircase	MICHAEL STATE OF THE STATE OF T	1 0 . 0.1.50 mtm	MR	
	➤ Upper floors	2 mtr & 1.5 mtr	2 mtr & 1.50 mtr	MR	
	➤ Basement floor	1.5 m each	1.5 m each	1724	
	c) Protection of exits	Gramme, Garat	Provided	MR	
1	> Fire check door	Required	5031	-NA-	
1	> Pressurization	-NA-	-NA-	MR	
	d) No. of continuous staircase to terrace	Required	Provided 01	-NA-	
l'a	e) Width of corridor	-NA-	-NA-	MR	
	f) Door size	1.25 m 1.5 m & 2 m	Provided	IVIX	
3	Compartmentation.) (D	
-	Fire check door.	Required	Provided	MR	
	Sealing of electrical shafts.	Required	Provided	MR MR	
	Fire rating of shaft door.	Required	Provided	-NA-	
	Water curtain	-NA-	-NA-		
-	Fire dampers.	-NA-	-NA-	-NA-	
4.	Smoke Management system.		rient landentile versi		
	Basement	30 ACPH	Exhaust fan provided	MR	
	Upper floors	12 ACPH	Natural ventilation	MR	
5.	Fire Extinguishers.				
-	Total numbers	25 Nos	25 Nos	MR	
	Types	ABC/Co2	ABC & Co2	MR	
	ISI Marking	ISI marked	Provided	MR	
6.	First Aid Hose Reels.		Sugreme Livi.		
7	Total numbers on each floor.	01 Nos at each	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	
_		Jimii	Date A Land		
7	Automatic fire detection & alarming system. • Type of detectors	Required	Smoke type	MR	

				35
	 (3013) PT 	Required	Ground floor	MR
4"	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	Required	Provided	MR
	Alternate source of power Hooter's location	Required	All Areas	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	-NA-	-NA-	-NA-
10.	Automatic Sprinkler System	-81	North Republication of the Control o	PS.
	Basement	Required	Provided	MR
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.		Carrier du salari que a	V -
	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	01 Nos	Provided	MR
no 575 - 1	Hose box.	01 Nos	Provided	MR
12.	Yard Hydrants.		To at a Midney area halfs	design of
, - i	 Total number of hydrants. 	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.		Instrumental and the second) Iv
	Ground Level	To 1847 1	N 1 N1 1 1	
	Discharge of main pump.	1620 LPM	1620 LPM	MR
7	Head of main pump.	70 mtr	70 mtr	MR
1	Number of main pumps.	01	emiliario OI estima	MR
	➤ Jockey Pump output.	180 LPM	180 LPM	MR
	> Jockey Pump head.	70 mtr	70 mtr	MR
	Standby Pump output.	1620 LPM	1620 LPM	MR
	Standby Pump head.	70 mtr	high 1670 mtr rostly in	MR
	 Auto Starting/Manual Stopping. Pump house access. 	Required	Provided	MR
_		Required	Provided	MR
	Terrace Level	ACCUSED TO HER	removed the Live Vil	
5-	Discharge of pump.	-NA-	900 LPM	-NA-
	 Head of pump. Power supply. 	-NA-	40 m	-NA-
	> Auto starting of pump.	-NA-	Provided	-NA-
14. (-NA-	Provided	-NA-
14.	Underground tank capacity.	75 000 T +-	and the Salar an	
	Draw-off connection.	75,000 Ltr	Provided	MR
	Fire Service Inlet.	Required Required	Provided	MR
-	> Access to tank.	Required	Provided	MR
	Overhead tank capacity.	10,000 Ltr	Provided Provided	MR
15. E	Exit Signage.	Required	Provided	MR
	rovision of Lifts.		Tiovided	MR_
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	- Land Allendaria
	 Communication in lift car. 	-NA-	-NA-	-NA-
	 Fireman's switch. 	-NA-	-NA-	-NA-
	 Lift signage. 	-NA-	Den e	-NA-
17. S	tandby Power Supply	1,070,014	-NA-	-NA-
	lefuge Area	Required	Provided (DG Set)	MR
	Total area	-NA-	Obst. Prints (N. 19)	
الله الم	• Location		-NA-	-NA-
9. F	ire Control Room.	-NA-	-NA-	-NA-
A.	Detector system panel.	27.6	Work of the second	
	zototor system panel.	-NA-	-NA-	-NA-

V





_	PA system panel. Battery backup. Building floor plan.	-NA- -NA-	-NA- -NA-	-NA-
		-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 377 dated 04/07/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Institutional/2021/SZ/454 dated 20/09/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Moroved, f.t. fettel il ne, synature Pl 1