

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

**NEW DELHI- 110001** 

No.F.6/DFS/MS/EH/2024/SZ/ 242

#### FIRE SAFETY CERTIFICATE

Certified that the **Trinandrews A unit of Tera Hotels**, located at Shop No. B-1/637, GF, Janakpuri, New Delhi- 110058, running at ground floor of a building comprised of basement, ground plus three upper floors, owned/occupied by **Trinandrews A unit of Tera Hotels**. The restaurant/eating house building was inspected by the officer concerned of this department on dated 22.07.2024 in the presence of Sh. Ramandeep Singh (Owner) and found that the restaurant building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class "D" "Assembly Building" (**for ground floor only**) w.e.f. the date of issue of this certificate for a peri0od of **three** years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on <u>25/07/2024</u> at New Delhi.

(ATVIL GÅRG) DIRECTOR DELHI FIRE SERVICE

## Online application Id 2024071911268 dated 19.07.2024

### Following fire safety directives must be adhered to:-

- 1. This NOC is valid only for ground floor.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 6. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, six months prior to its expiry.

NY

# INSPECTION REPORT

1. Arme & address of the building: Trinandrews A unit of Tera Hotels, located at Shop No. B-1/637, GF, Janakpuri, New Delhi- 110058,

2. Type of Occupancy : Assembly (Restaurant)

3. Building Composition : Said restaurant is running at ground floor only in a building comprised of basement (Parking), ground floor (restaurant), 1<sup>st</sup>, 2<sup>nd</sup>

& 3<sup>rd</sup> floor (other property use for office)

4. Type of Case : New Case

5. Details of previous NOC : N/A6. Fire Safety directives letter No : N/A

7. Date of inspection : 22.07.2024

8. Name of the Inspecting Officers: R.K. Yadav, ADO (JKP)

9. Name and designation of officers

from the building side : Sh. Ramandeep Singh (Manager)

9. Year of Construction : 2023

10. Applicant's letter No. : Online Application Id 2024071911268 dated 19.07.2024

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per NBC/BBL	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	06 mts	Provided	MR		
	Gate width	4.5 mts Di	rectly accessible from the road	MR		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases		· · · · · · · · · · · · · · · · · · ·	147		
	Upper Floors	N/A	03	N/A		
	Basements	N/A	N/A	N/A		
	b. Width of staircases		e santonal m			
	Upper Floors	N/A	1.50, 1.25 & 1.18 mts	N/A		
	Basements	N/A	N/A	N/A		
	c. Protection of exits	- 1 - 1 AM	and the second of			
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	N/A	N/A	N/A		
	g. Width of Corridor	N/A	N/A	N/A		
	h. Door Size	1.5 mts each	1.50, 1.60 & 1.60 m	MR		
3	Compartmentation.	1-11-				
	Fire check door	N/A	N/A	N/A		
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basements	30 a/c per hour	N/A	N/A		
	Upper floors (Restaurant-GF)	12 a/c per hour	Provided	MR		
5	Fire Extinguishers					
	<ul><li>Total numbers</li><li>Types</li><li>IS marking</li></ul>	06 CO <sub>2</sub> , ABC type ISI marked	Provided	MR		
			Provided	MR		
			Provided	MR		

h

-	First-Aid Hose Reels.		Provided		
		01	Provided	1	
	Total numbers on G. floor (Rest.)	30 m	Provided	MR	
	<ul> <li>Length of hose reel nose</li> </ul>	5 mm	1101.00		
	Liometer	evstem.		MR	
7	Nozzie diantee  Automatic fire detection and alarming	Heat/Smoke	Provided	N/A	
	Type of detectors	N/A	N/A	N/A	
	<ul> <li>Location of Main Panel</li> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> <li>Hooters' Location</li> </ul>		N/A	7.1	
		N/A	Provided	MR	
		Required	N/A	N/A	
		N/A Required	Provided	MR	
8	MOEFA		N/A	N/A	
9	Public Address System.	N/A	4-1-1-1	TI NIA	
10	Automatic Sprinkler System.	77	N/A	N/A	
	Basement	N/A	Provided	MR	
	Entire Restaurant	Required	N/A	N/A	
	Sprinkler above false ceiling	N/A	IVIX	14	
	Internal Hydrants	1 1 3 4	100	MR	
11	Size of riser/down-comer	100 mm	100 mm	MR	
	Number of hydrants per floor	01	01	MR	
	Hose Box	01	01	-12	
10	Yard Hydrants.	NI/A	N/A		
12	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	14/1	
12	Pumping Arrangements.	A:		-	
13	Ground Level	· =	57/4	N/A	
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	The second second	
	Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A	N/A	
	> Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual stopping	N/A	N/A	N/A	
	Pump House Access	N/A	N/A	N/A	
	Terrace level		450 I DM	MR	
	Discharge of pump	450 LPM	450 LPM Provided		
	> Head of the pump	40 mts	Provided	MR	
	Power Supply	Required	Provided	MR MR	
	Auto Starting of pump	Required	Tiovided	IVIK	
14	Captive Water Storage for fire fighting.				
	Underground tank capacity	N/A	N/A	N/A	
-	Draw-off connection	N/A	N/A	N/A	
	<ul> <li>Fire service inlet</li> <li>Access to tank</li> </ul>	N/A N/A	N/A	N/A	
	Access to tank     Overhead Tank capacity	20,000 lts	N/A Provided	N/A	
				MR	
15	Exit Signage.	Required	Provided	MR	





		NA					
_	sion of Lifts.	N/A	N/A	N/A			
MR	Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage	N/A	N/A	N/A			
		N/A	N/A	N/A			
1		N/A	N/A	N/A			
		N/A	N/A	N/A			
		Required	Provided	MR			
17	Standby power supp-y						
18	Refuge Area.	N/A	N/A	N/A			
	> Total Area > Location	N/A	N/A	N/A			
19	Fire Control Room						
17	D. Anster System Panel	N/A	N/A	N/A			
	DI Guitale Danel	N/A	N/A	N/A			
	D. C Donal	N/A	N/A	N/A			
	457	N/A	N/A	N/A			
	Battery backup     Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Note:- The total covered area of restaurant as per MHA CAF portal is 175 Sq mtr., so sitting capacity comes (175/1.8 = 97) 97 persons.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rule 2010 if agreed.

Accordingly, reply letter is put up for approval & signature please.

Signature of the inspecting officer Name- R.K. Yadav

Designation- ADO (JKP)

CFO (S2) 111

23 H 201

Dinectar/1/

409 DX