

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Dated: 25 07/2024

No. F.6/DFS/MS/EH/2024/SZ/240

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Uncle By Miss Pinto located at 1st & 2nd floor, Plot No 24, Community Centre, Vasant Vihar, Delhi 110057 in the building comprised of Basement, Ground, Mezz. Plus 02 upper floor owner/occupied by Unit of Hungry N Thirsty Foods Pvt Ltd was issued FSC by this department vide letter no F6/DFS/MS/SZ/2013/501 dated 01/07/2013 for the Name of M/s Kylin Restaurant. The restaurant premise was re-inspected by the officers concerned of this department on 15/07/2024 in the presence of Mr. Kapil Kumar and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class- D " Assembly Building" (Restaurant at 1st & 2nd floor) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on25/0.7.../2024 at New Delhi by.

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic/Branch), First floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2024070610550 dated 06/07/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of 2.8 of

UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

The Basement is closed and not in use.

MIS

	INSPECTIO	ON REPORT		महोत्सव			
1	Name & Address of the Building	M/s Uncle By Miss Pinto (Unit of Hungry I Thirsty Foods Pvt Ltd) Plot No 24, 1 st & 2 nd floor Community Centre, Vasant Vihar, Delhi 110057					
2	Type of Occupancy	Community Centr	st a and Elass	п 110037			
3	Building Comprised of	(Restaurant at 1	* & 2 Floor)	nner floor			
4	Type of Case	Basement, Ground, Mezz. Plus 02 upper floor					
5	Details of Previous NOC	Renewal / Nam	e Change /2013/501 dated 01/	07/2013 fo			
Sing	Details of Fievious NOC	the Name of M/	s Kylin Restaurant	07/2013 10			
6	Fire Safety Directives Letter No	Circular dated 0		177			
7	Date of Inspection	15/07/2024	The late of the la				
8	Name of the Inspecting Officers	DO (South) & A	DO (BCP)	,			
9	Name & Designation of Officers	Mr. Kapil Kumar					
	from the building side	gress (I breast) (II)					
10	Year of construction	1997 more name 1 result for Signal					
11	Applicant letter No.	MHA Portal ID 2024070610550 dated 06/07/2024					
S.	Minimum standards on Fire Prevention	Circular dated	Provided at Site	Remarks			
No.		04/04/2005	1 lovided at Site	MR/NMI			
1	and Fire Safety U/R 33	04/04/2003	A A A				
A Auri	Access to Building. Road width	4.5 mtr	Provided	MR			
	Gate width	N/A	N/A	N/A			
	Width of internal road	N/A N/A	N/A	N/A			
2	The state of the s		man attached				
ענק 2	Number, width, type & arrangement of exits.						
	Number of Staircase	0137	02 No	Old case			
	Upper floors.	01 No		N/A			
Arel	Basement floor.	N/A	N/A	IVA			
	Width of Staircase	1.30 m & 01 fire	1.30 m & spiral	MR			
	Upper floors	escape	sc spiral	(old case			
7.0	Basement floor	N/A	N/A	N/A			
	Protection of exits		Refer hatemal				
(75.7	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
2014	No. of continuous staircase to terrace	NA	01 No	NA			
2174	Width of corridor	N/A	N/A	N/A			
18		N/A	N/A	N/A			
3	Compartmentation.	grander i 1120	ROSE TO ME SOURCE				
	Hire check door.	N/A	N/A	N/A			
- 1	Sealing of electrical shafts.	N/A	N/A	N/A			
-37	Fire rating of shaft door.	N/A	N/A	N/A			
Alk	Water curtain	N/A	N/A	N/A			
35	Fire dampers.	N/A	N/A	N/A			
4	Smoke Management system.		Althous .	11/17			
	Basement	12 ACPH	N/A	N/A			
- A 104	Upper floors	12 ACPH	Exhaust fan	MR			
5	Fire Extinguishers.	and He	Anneust Idii	IVIIC			
	Total numbers	06 Nos	13 Nos	MR			
100	Types	ABC/CO ₂	ABC & CO ₂				
yty	I\$I Marking	ISI marked	Provided	MR			
6	First Aid Hose Reels.	101 markeu	Flovided	MR			
	Total numbers on each floor.	One at each	Provided	MR			
	Length of hose-reel hose.	30m	Provided	MR			
	Nozzle Diameter	5mm	Provided				
7	Automatic fire detection & alarming sys	stem	TIOVIDED	MR			
7	Type of detectors	N/A	N/A	N/A			
77			INIM	- 1 A 1 / A			

	A CONTRACTOR OF THE PROPERTY O			1
197 g	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
A ac	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			IVIIC
	Basement	N/A	N/A	N/A
	Ground floor & upper floor	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.		-12-21	1 2 0 4 2
	Size of Riser/Down-comer	100 mm	Provided	MR
S. The	Number of Hydrant per floor	One	Provided	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.	अभियोगा जात	TERM THE RES	
	Total number of hydrants.	N/A	N/A	N/A
12	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.		11,000	
	Ground Level		7	
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head. Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
i i bii	Pump house access.	N/A	N/A	N/A
A.2	8.71	N/A	N/A	N/A
	Terrace Level	_	diam're.	R
	Discharge of pump.	450 & 225 LPM	Provided	MR
1.0	Head of pump.	35m	Provided	MR
- 177	Power supply. Auto starting of pump.	Required	Provided	
	Auto starting of pump.	Required	ALEX CONTRACTOR	MR
14	Captive water storage for fire fighting.	Required	Provided	MR
	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A N/A
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	20,000 Ltrs	20,000 ltr	1 1 1 2 2 2 3
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	- Languista	TIOVICE	MR
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area		عود السيالي	. 19
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	
19	Fire Control Room.	750		N/A
17	Detector system panel.	N/A	NT/A	
	Flow switch panel.	N/A	N/A N/A	N/A
			1307.43	N/A



1		12		I NI/A
	PA system panel.	N/A	N/A	N/A N/A
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A ecked and found

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 271 dated 04/07/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/SZ/2013/501 dated 01/07/2013 for the Name of M/s Kylin Restaurant, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Denecta As approved, F=1. 1-etter in putup to you synature PI (12/3/2024)

upleaded 26/2/24