## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.F6/DFS/MS/School/SZ/2024/77-

Dated:

### FIRE SAFETY CERTIFICATE

Certified that the Hakikat Rai Sarvodaya Kanya Vidyalaya, Shiv Park, Khanpur, New Delhi-62 (School ID no. 1923062), comprised of three blocks:- A block - Ground + 3 upper floors, B block - Ground + 1 upper floor (Old), C block - Ground + 1 upper floor (Old), was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/School/2021/SZ/86 dated 02.02.2021. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 02.08.2024 in the presence of Mrs. Purnima Kaushal (HOS) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises/building comprised of three blocks:- [A block - Ground + 3 upper floors, B block - Ground + 1 upper floor (Old), C block - Ground + 1 upper floor (Old)] is period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on...o.7/08/2014...at New Delhi by.

Director

Delhi Fire Service

#### Copy to:-.

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

2. The Principal, Hakikat Rai Sarvodaya Kanya Vidyalaya, Shiv Park, Khanpur, New Delhi-62

# Conditions for the validity of Fire Safety Certificate:-

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

	_	INSP	ECTION REPORT	THE RESERVE OF THE PARTY OF THE	
1		- address of the building:	Hakikat Rai Sarvo	daya Kanya Vidyala hi-62 (School ID no.	aya, Shiv Par
2	Bu	ilding is comprised of	Comprised of three	<u>m-02 (School ID no.</u> blocks:-	1923002).
			A block - Ground +	3 upper floors	
	1		B block - Ground +	1 upper floor (Old)	
3	Tv	ne of comm	C block - Ground +	1 upper floor (Old)	
4	Ty	pe of occupancy pe of case:	Group -B Education	al Building (School)	
5	_	tails of previous FSC:	Renewal		
6	Fir	re safety directives no.:		2021/SZ/86 dated 02.	
	1.11	c safety directives no.:	A block as per NBC/	UBBL & B & C bloc	ck as per
7	Da	te of inspection:	DOE circular dated 0	01.03.2011	
8		me of the inspecting officer:	02.08.2024		
9	Na	me and designation of the officer	ADO Rajesh Kumar Shukla (M. Road) Mrs. Purnima Kaushal (HOS)		
	fro	m the building side:	Mrs. Purnima Kausha	al (HOS)	
10	Ye	ar of construction:	2013 & 2017		
11	Re	ference letter no.:	Outdoor diary no. 394	41 dated 00 07 2024	
S,No		nimum Standards on fire	Requirements	Provide at site	Remarks
	Pr	evention and fire safety	requirements	1 Tovide at site	MR/NMF
4	rec	quirements U/R 33			1 7
1		cess to Building			
	A	Road width	6.0 m	6.0 m	MR
	B	Gate width	NA	NA	NA
100	C	Width of internal roads	NA	NA	NA
2		mber, Width, Type & Arrangem	ent of Exits	والمراكب	
	A	No. of staircase:			
		a) Upper floor	A block- 01 no.	A block- 01 no.	MR
		A. Kr	B block- 01 no.	B block- 01 no.	
		100	C block- 02 nos.	C block- 02 nos.	
	В	b) Basements Width of the staircase:	NA	NA	NA
	D	a) Upper floor	1 steinesse of 1 5		1.00
		a) Opportion	1 staircase of 1.5 mtrs or if main staircase	A block- 1.70 mtrs B block -1.50 mtrs	MR
		T A INCOME TO THE REAL PROPERTY OF THE PARTY	width is < 1.5 mtrs an	C block- 1.80 mtrs	100
	- 2	er i distribuito di peri	additional staircase of	& 1.60 mtrs	
		And I won't made A ' 1884 at	0.75 mtrrs width is required	White and the same	
		b) Basements	NA	NA	NA
	C	Protection of exits	10.00	IVA	INA
		a) Fire check door	NA ·	NA	INTA
		b) Pressurization	NA	NA	NA
	D	No. of continuous staircase to	1 no. each block	Provided	NA
		terrace:	I no. caen block	riovided	MR
	F	Width of the corridor	NA	NA	27.4
	E	Door size	1.0 mtrs. for class	1.0 mtrs. for class	NA
			room	room	MR
3	Cor	mpartmentation:			
	A	Fire check doors	NA	NA	NA
	В	Sealing of electrical shafts	NA	NA	NA NA
	C	Fire rating of shaft doors	NA	NA	L. The Residence
	D	Water curtain	NA	NA	NA
	E	Fire dampers	NA	NA	NA
	Sme	oke Management System:		Application of the Con-	NA
	A	Upper floors	NA	NA.	20 11
	В	Basements	NA	NA NA	NA
	Fire	Extinguishers		TVA	NA
	A	Total numbers	22 mas	W .	
	B	Types	22 nos.	44 nos.	MR
ŀ		2.2	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR
	·	ISI marking	Required	Provided	MR

N	120

6	Fi	rst Aid Hose reel	NIW				
	A	Total no. at each floor	A block -1 no.	A block -1 no.	MR		
	B	Length of hose reel	30 mtrs.	30 mtrs.	MR		
	C	Nozzle diameter	5 mm	5 mm	MR		
7	Automatic Fire Detection and Alarm System (ADAS)						
	A	Type of detectors	NA NA	NA	NA		
	В	Location of main panel	NA ·	NA	NA		
	C	Location of repeater panel	NA	NA	NA		
	D	Alternate power source	NA	NA	NA		
	E	Hooter's location	NA	NA	NA		
8	1000000	OEFA	NA	NA	NA		
9	Pu	blic Address System	NA	Provided	NA		
10	Automatic Sprinkler System						
	A	Basement	NA	NA	NA		
	С	Upper floor	NA	NA	NA		
11	-	Sprinklers above false ceiling	NA	NA	NA		
11	A	ternal Hydrants					
	_	Size of the riser/down comer	NA	NA	NA		
	C	No. Of hydrants per floor Hose box	NA	NA	NA		
12	_	rd Hydrants	NA	NA	NA		
	A	Total no. of hydrants	l N/A	The last			
	B	Hose box	NA	NA	NA		
13	_	mping Arrangements	NA	NA	NA		
	A	Ground Level			1. 4		
		a) Discharge of main pump	NA	374			
		b) Head of main pump	NA NA	NA	NA		
		c) Number of main pump		NA	NA		
		d) Discharge of jockey pump	NA NA	NA	NA		
				NA	NA		
. 5		J. T. J. Santap	NA	NA	NA		
		<ul><li>f) Discharge of standby pump</li><li>g) Head of standby pump</li></ul>	NA	NA	NA		
Jan.			NA	NA	NA		
		stopping	NA	NA	NA		
	В	Terrace Level					
		a) Discharge of terrace pump	A block - 450 LPM	A block -2 nos. of 450 LPM	MR		
	T.	b) Head of terrace pump	40 m	Provided	MR		
		c) Alternate power supply	Required	Provided	MR		
	A TH	d) Auto starting of pump	Required	Provided	MR		
4	Ca	ptive Water Storage for Fire Figl		Harli Cana	10.		
1	A	Underground tank capacity	NA	NA	NA		
	B	Draw off connection	NA '	NA	NA		
	C	Fire service inlet	NA	NA	NA		
	E	Access to tank	NA	NA	NA		
	D	Overhead tank capacity	A block - 10,000 ltrs	A block -10,000 ltrs	MR		
15		it Signage	Required	Provided	MR		
16	Provision of lift						
	A	Pressurization of lift shaft	NA	NA	NA		
	В	Pressurization of lift lobby	NA	NA	NA		
	C	Communication in lift car	NA	NA	NA		
	D	Fireman switch	NA	NA	NA		
	E	Lift signage	NA	NA	NA		
17	Sta	ndby Power Supply	NA	NA	NA		



Hakikat Rai Sarvodaya Kanya Vidyalaya, Shiv Park, Khanpur, New Delhi-62 (School ID no. 1923062).

18	Re	fuge Area	-	15 (Senson 11) no. 15	23002).
	A	location			
	B	Total area	NA	NA	NA
19	Fi	re Control Room	NA	NA	NA NA
	A	Fire detection system panel	1		
	B	Flow switch panel	NA	NA	NA
	C	P A system panel	NA NA	NA	NA
	D	Battery backup	NA NA	NA	NA
	E	Building floor plan	NA	NA NA	NA NA
20	Sne	ecial Fire Protection for special r	NA NA	NA	NA
	~ P	cetal The Trotection for special r	isk if any		NA

## LEGENDS:-Meeting requirement (MR), Not meeting requirement (NMR), Not applicable (NA), Provided but not functional (PNF).

The fire protection systems provided in the building were tested checked and found properly functional at the time of inspection.

The shortcoming issued to the building vide letter no. F6/DFS/MS/School/SZ/2024/109 dated 11.03.2024 has been rectified by the school management.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no F6/DFS/MS/School/2021/SZ/86 dated 02.02.2021 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010

> Signature of the Inspecting Officer Name Rajesh Kumar Shukla ADO (M . Road) Designation