GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2024/SZ/ 777

Dated: 08/08/2024

FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya Co-ed. School, Pandwala Kalan, New Delhi-110043 comprised of ground plus one upper floor, owned/occupied by Govt. of NCT of Delhi was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2021/SZ/966 dated 30.11.2021. The school building was re- inspected by the officer concerned of this department on 02.08.2024 in the presence of Sh. Manoj (Teacher) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Delhi Fire Service

Copy to:-

1. The Principal, Sarvodaya Co-ed. School, Pandwala Kalan, New Delhi-110043

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

Following fire safety directives must be adhered to: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/24

INSPECTION REPORT

1. Name & address of the building

: Sarvodaya Co-ed. School, Pandwala Kalan, New Delhi-110043

2. Building is comprised of3. Type of Occupancy

Ground plus one upper floor only.

4. Type of Case

: Educational

4. Type of Case

RenewalF.6/DFS/MS/School/2021/SZ/966 dated 30.11.2021

5. Details of Previous NOC6. Fire Safety directives letter No

Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

7. Date of inspection

02.08.2024

8. Name of Inspecting Officer

: A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side

: Sh. Manoj (Teacher)

10. Year of Construction

: 1970

11. Applicant's letter No.

5.

Online email ID hospandwaa005@gmail.com dated 08.07.2024

S. No.	Minimum Star	dards on fire prevention U/R 33	Requirement as per FSC dt. 30.11.2021	r Provided at site	Remarks MR/NMI
Ι.	Access to build				
	Road w	idth	Accessible 06 m	10 m	MR
	• Gate wie		4.5 m	Directly accessible from	MR
		f internal road	N/A	road	N/A
•	1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	, Type & Arrangement of	Exits	N/A	
	a. Number of sta	ircases			
	Upper F		02 no.'s	03 no.'s	MR
	Basemer		N/A	N/A	N/A
- 1	b. Width of stairs	A CONTRACTOR OF THE CONTRACTOR			
	Upper F.	_	1.50 m	1.60, 1.58 & 1.35 m	MR
	1.		N/A	N/A	N/A
	e. Protection of e				
	Fire chec	THIN DACK	N/A	N/A	N/A
	Pressuriz		N/A	N/A	N/A
	d. No. of continu	HECKEDAMA.			C- NOV-S.
- 1	terrace	ous stancases to	N/A	N/A	N/A
6	e. Width of Corri	dor	N/A	N/A	N/A
f	Class Room D	oor Size	1.0 m 1	.20 & 1.0 m (double door)	MR
(Compartmentatio	n	×		
	Fire check	EQUALITY OF THE PARTY OF THE PA	N/A	N/A	N/A
		electrical shafts	N/A	N/A	N/A
	 Fire Rating Water Curta 	of shaft door	N/A	N/A	N/A
	Fire Dampe		N/A	N/A	N/A
			N/A	N/A	N/A
Sn	noke Managemei	nt System			
	• Basements		N/A	N/A	N/A
	 Upper floors 		Required	Natural Ventilation provided	MR
Fir	e Extinguishers				
	Total numbers		10 No's	Provided	MR
	• Types		ABC/CO ₂ type	Provided	MR
	IS marking		ISI marked	ISI marked	MR

6.	First-Aid Hose Reels			
	 Total numbers on each floor Length of hose reel hose 	N/A	N/A	, N/A
>	Nozzle diameter	N/A N/A	N/A	N/A
			N/A	N/A

	Automatic fire detection and alarming system			
•		27/4	N/A	A711
	Type of detectors	N/A N/A		N/A
	Location of Main Panel	N/A N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location		N/A	N/A
3.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants		5	
	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level		14 200	
	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	Jockey pump headStandby Pump out put	N/A	N/A	N/A
	 Standby Pump out put Standby Pump Head 	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
	7 Maio Baiting Manual Biopping	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
8	➤ Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connectionFire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
		N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.	1	1	(No Lift)
	Pressurization of Lift Shaft	N/A	NI/A	NT/A
	Pressurization of Lift lobby		N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
11	Lift Signage	N/A	N/A	N/A
111	-00-	N/A	N/A	N/A

1	1
N	4

17.	Standby	power supply	27/4	1	T	
18.	Refuge A	N-525 6	N/A	N/A	N/A	
		otal Area	N/A	N/A	T N/A	
	> I	ocation	N/A	N/A	N/A N/A	
19.	Fire Control Room					
	• D	etector System Panel	N/A	N/A	N/A	
		ow Switch Panel	N/A	N/A	N/A	
	PA System Panel Battery backup	N/A	N/A	N/A		
		uilding Floor Plans	N/A	N/A .	N/A	
•			N/A	N/A	N/A	
20.	Special Fi	re Protection System for Protection of sks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2021/SZ/966 dated 30.11.2021, renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Office Name: - R.K. Yaday

Designation: - ADO (JKP)

DO (South West)

2)

6 8 0

and of