

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI-110001**

No. F.6/DFS/MS/EH/2024/SZ/253

Dated..05/08/2024

**FIRE SAFETY CERTIFICATE**

Certified that the Eating House in the Name & Style of **M/s Adyar Ananda Bhavan Sweet India Pvt Ltd** located at **GF, FF & SF**, S-16, Green Park Street, Main Market, New Delhi 110016 in the building Comprised of Basement (storage) Ground plus Three upper floor (**Sealed with Brick Wall**) owned/Occupied by M/s Adyar Ananda Bhavan Sweet India Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 01/08/2024 on in the presence of Mr. Balaji and found that the premise is fit for occupancy **Group "D" (Assembly Building)** and **validity upto 31/03/2027** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 05/08/2024 at New Delhi by

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police, (Lic/Branch) 1<sup>st</sup> Floor, PS Defence Colony, New Delhi 110049. (Ref. MHA Portal 2024070410388 dated 04/07/2024)

**Conditions for the validity of Fire Safety Certificate: -**

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. The basement shall be used as per the provisions of UBBL 2016 /NBC Part- IV.
4. All the staff members must know the correct method of operation of fire fighting system.
5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

## INSPECTION REPORT

1	Name & address of the building	Adyar Ananda Bhavan Sweet India Pvt. Ltd. At S-16, Green Park Street, Main Market, New Delhi-110016.		
2	Type of Occupancy	(Restaurant at GF + FF+ SF only) Basement + Ground + 03 upper floors)		
3	Type of Case	New Case		
4	Details of previous FSC	N/A		
5	Fire Safety directives Letter No.	N/A		
6	Date of inspection	01.08.2024		
7	Name of the Inspecting Officer	DO (South) & ADO (BCP)		
8	Name and Designation of Officer from the building side	Mr. Balaji		
9	Year of Construction	2023		
10	Applicant's letter No./ Online Id No.	MHA Portal 2024070410388 dated 04/07/2024		
Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R 33	Requirements	Provided at Site	Remarks MR/NMR
1	<b>Access to Building</b>			
	Road Width	Required	06 mtr.	MR
	Gate Width	N/A	N/A	N/A
	Width of Internal Road	N/A	N/A	N/A
2	<b>Number, Width, Type &amp; Arrangements of exits</b>			
	<b>A Number of Staircase</b>			
	Upper Floors	02 nos.	02 nos.	MR
	Basement	02 nos.	02 nos.	MR
	<b>B Width of Staircase</b>			
	Upper Floors	1.5 m	1.5 m each	MR
	Basement	1.5 m	1.5 m each	MR
	<b>C Protection of Exits</b>			
	Fire Check door	N/A	N/A	N/A
	Pressurization	N/A	N/A	N/A
	<b>D No. of Continuous S/C to terrace</b>	02 nos.	02 nos.	MR
	<b>E Width of Corridor</b>	N/A	N/A	N/A
	<b>F Door Size</b>	1.5 mtr.	1.50 mtr each	MR
3	<b>Compartmentation</b>			
	Fire check door	Required	Provided	MR
	Sealing of electrical shafts	Required	Provided	MR
	Fire rating of shaft door	N/A	N/A	N/A
	Water curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
4	<b>Smoke Management System</b>			
	Basements	N/A	N/A	N/A
	Upper floors	12 a/c per hour	Exhaust fan	MR
5	<b>Fire Extinguishers</b>			
	Total Numbers	08 Nos.	10 Nos.	MR
	Types	ABC & CO2	ABC & CO2	MR
	ISI Marking	Required	Provided	MR

<b>6</b>	<b>First-Aid Hose Reel</b>			
	Total number 1 <sup>st</sup> floor	01 nos.	01 nos.	MR
	Length of hose reel hose	30 mtr.	30 mtr.	MR
	Nozzle diameter	05 mm	05 mm	MR
<b>7</b>	<b>Automatic Fire Detection &amp; Alarming System</b>			
	Type of detectors	Heat & Smoke	Heat & Smoke	MR
	Location of main panel	Reception	Gr. floor	MR
	Location of repeater panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	5 Hooter's Location	Required	Provided	MR
<b>8</b>	<b>MOEFA</b>	Required	Provided	MR
<b>9</b>	<b>Public Address System</b>	N/A	N/A	N/A
<b>10</b>	<b>Automatic Sprinkler System</b>			
	Basement	N/A	N/A	N/A
	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
<b>11</b>	<b>Internal Hydrants</b>			
	Size of riser/down-comer	Required	Provided	MR
	Number of hydrants per floor	01 nos.	Provided	MR
	Hose box	01 nos.	Provided	MR
<b>12</b>	<b>Yard Hydrants</b>			
	Total number of hydrants	N/A	N/A	N/A
	Hose box	N/A	N/A	N/A
<b>13</b>	<b>Pumping Arrangement</b>			
	<b>A Ground level</b>			
	Discharge of main pump	N/A	N/A	N/A
	Head of main pump	N/A	N/A	N/A
	Number of main pump	N/A	N/A	N/A
	Jockey pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Stand by pump output	N/A	N/A	N/A
	Stand by pump head	N/A	N/A	N/A
	Auto starting/Manual stopping	N/A	N/A	N/A
	<b>B Terrace level</b>			
	Discharge of pump	900 lpm	Provided	MR
	Head of pump	40m	Provided	MR
	Power supply	Required	Provided	MR
	Auto starting of pump	Required	Provided	MR
<b>14</b>	<b>Capacity of Water Storage for Fire Fighting</b>			
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Over head tank capacity	20,000 ltr	20,000 ltr	MR
<b>15</b>	<b>Exit Signage.</b>	Required	Provided	MR
<b>16</b>	<b>Provision of Lifts.</b>			
	Pressurization of lift shaft	N/A	N/A	N/A
	Pressurization of lift lobby	N/A	N/A	N/A

N/12

	Communication in lift car	N/A	N/A	N/A
	Fireman's switch	N/A	N/A	N/A
	Lift signage	N/A	N/A	N/A
17	Stand by Power Supply	Required	Provided	MR
18	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	Detector system panel	N/A	N/A	N/A
	Flow switch panel	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20	Special Fire Protection System for Protection of special Risk, if any:			N/A

Note- The third floor of building is Sealed with brick wall (Photo endorsed)

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 255 dated 24/06/2024.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

*Handwritten signature of Sh. Manoj Kumar Sharma*

Signature of the Inspection Officer  
Name: Sh. Manoj Kumar Sharma  
Design: DO (South)

*Handwritten signature of Sh. Rajesh Kumar*

Signature of the Inspecting Officer  
Name: Sh. Rajesh Kumar  
Design: ADO (BCP)

CFO/HQ

*Handwritten signature and date 28/8/2024*

Director

*Handwritten signature and date 5/10/24*

*Handwritten signature*

*Handwritten signature*

*Handwritten text: uploaded 5/8/24*