GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001 0.F6/DFS/MS/GH/NDZ/2024/ 335 Dated:..07-08../2024

No.F6/DFS/MS/GH/NDZ/2024/ 335

FIRE SAFETY CERTIFICATE

Certified that the Chanchal Continental Guest House located at 8524, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 05 Upper floors, Ground floor (Reception + 01 Office), 1st floor to 3rd floor (11 guest rooms at each floor) and 4th & 5th floor not in use as per affidavit dated 11.12.2019, total 33 guest rooms up to third floor only, owned/occupied by Chanchal. Continental Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2021/216 dated 15/07/21. Now, the premises was re-inspected by the officers concerned of this department on 29/07/24 in the presence of Manager and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1, ground floor -office & reception,1st to 3rd floor (11 guest rooms at each floor) 33 guest rooms up to third floor only, and valid up to the period of three year from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued .. 07. 08. 2.24...... New Delhi by.

Copy to:-

- 1. The Commissioner, North MCD, New Delhi: to ensure the occupancy in the building.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.
- 3. Online id no. 2024071210892 dated 12/07/24.
- 4. The Manager, Chanchal Continental Guest House at 8524, Arakashan Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid for guest house from ground to third floor only.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.

			M136					
	I Name & III	TON REPORT	130 W 31.000					
	1. Name & address of the buildi	Continental Guest House at 8524,						
	2 Type of con-	Road, Pahar Ganj, New Delhi						
	Type of occupancy:-		al, Sub Division-A-1					
		mer floors (total 33 Guest rooms)						
		Ground floor (
	floor (11 guest rooms at each floor) and 5 th floor sealed with brick wall							
	& 4th & 5th floor not in use as per affidavit dated							
	11 12 2010							
	 Type of case:- Details of previous FSC:- No.F6/DFS/MS/GH/NDZ/2021/216 dated 15/07/21. Fire safety directives No Date of inspection:- Name of the inspecting officer:- Renewal No.F6/DFS/MS/GH/NDZ/2021/216 dated 15/07/21. N/A Sh. Ravinder Singh (ADO CC) 							
	. Name & designation of officer							
	From the building side:- Manager							
	9. Year of construction:-	2001	2001					
1	0. Applicant's letter No:- Online id.2024071210892 dated 12/07/24.							
				Old Case				
S.No	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR				
1.	Access to Building			7				
1000	1) Road width	N/A	06 mtr	N/A				
	2) Gate width	N/A	N/A	N/A				
	3)Width of internal road	N/A	N/A	N/A				
2.	Number, Width Type & Ari							
۷.	A. Number of staircases	angement of Ex						
	1. Upper floors	01 Nos.	01 Nos. C	MR				
	2. Basements	N/A	N/A	N/A				
	B. Width of staircase	1						
	1. Upper floors	1.25 mtr.	1.25 mtr.	MR				
	2. Basements	N/A	N/A	N/A				
	C. Protection of exits	1,112		1.				
	1. Fire check door	Required	provided	MR				
	2. Pressurization	N/A	N/A	N/A				
	D. No. of continuous staircase to terrace	N/A	N/A	N/A				
			J					
	E. Width of corridor	N/A	N/A	N/A				
š = -	F. Door size	01 mtr.	01 mtr. /	MR				
	Compartmentation	100						
	1) Fire check door	N/A	N/A	N/A				
	2) Sealing of electrical shafts	N/A	N/A	N/A				
	3) Fire rating of shaft door	N/A	N/A	N/A				
	4) Water curtain	N/A	N/A	N/A				
	5) Fire Dampers	N/A	N/A	N/A				
6	Smoke Management System							
	1) Basements	N/A	N/A	N/A				
	2) Upper floors	12 ACPH	Natural	MR				
ii.	Fire Extinguishers			1.55				
•	1) Total numbers	16 Nos.	16 Nos.	MR				
	2) Types	ABC & CO2	ABC & CO2					
	3) ISI marking	Required		MR				
	First-Aid Hose Reel	Kequired	Provided	MR				
	1) Total number of eachfloor	01	7.					
		01	01	MR				
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR				
	3) Nozzle diameter	05 mm	05 mm	MR				

4/37

	A -to-motic Fire Detection & A	Jarming Syste	m	_ \	
7.	Automatic Fire Detection & Alarming System 1) Type of detectors CO type Required Provided			7	
	2) Location of main panel	Ground floor		MR	
	2) Location of main panel	N/A	Provided	MR	
	3) Location of repeater panel	- DELICE (CL2)	N/A	N/A	
	4) Alternate source of power	Required	Provided	MR	
	5) Hooter's Location	Ground floor	Provided	MR	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System .				
10.	1) Basement N/A		N/A	N/A	
	2) Unper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling			3-3 month 955	
••	Internal Hydrants				
11.	1) Size of riser/down-comer	100 mm	100 mm	MR	
	2) Number of hydrants per	01	01	MR	
60	floor		1-	ontenn.	
	1100r	01	01 /	MR	
100	3) Hose box	**	/	in the s	
12.	Yard Hydrants	N/A	N/A	N/A	
	1) Total number of hydrants	N/A	N/A	N/A	
	2) 11030 0011	IN/A	14/17	IVA	
13.	Pumping Arrangement	27/4	DI/A	N/A	
	1) Ground level	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A	
	pump		37/1	DI/A	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual stopping	N/A	N/A	N/A	
	2) Terrace level				
	a) Discharge of pump	225 LPM	225 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr. /	MR	
		Required	Provided	MR	
	c) Power supply	Required	Provided	MR	
212	d) Auto starting of pump Required Provided Captive Water Storage for Fire Fighting				
14.	 Under ground tank 	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
		N/A	N/A	N/A	
	b) Fire service inlet	N/A N/A	N/A	N/A	
	c) Access to tank		15,000 ltr.	MR	
	d) Over head tank	15,000 ltr.	15,000 121		
15	capacity	Required	Provided	MR	
15. 16.	Exit Signage.	Required			
10.	Provision of Lifts.		NIA	N/A	
	 a) Pressurization of lift shaft 	N/A	N/A	N/A	
	 b) Pressurization of lift lobby 	N/A	N/A		
	c) Communication in	Required	Provided	MR	
	lift car	redamen		MR	



	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2021/216 dated 15/07/21, under rule 35(6) of the Delhi Fire Service Rules 2010. Accordingly, DFA is prepared and put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: Ravinder Singh Designation: ADO (CC)

2007/24
24/260 (2002)
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24
24/27/24

sid Signotion please

Disection

up Jumbel