

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/252

Dated: 02/08/2024

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Uncafe located at Plot No S-35 A Ground Floor, Green Park Main Market, New Delhi- 110016 in the building comprised of Basement, Ground plus three upper floor owner/occupied by Unit of Risa Curates Pvt Ltd was issued FSC by this department vide letter F6/DFS/MS/EH/2021/SZ/164 dated 30/07/2021. The restaurant premise was reinspected by the officers concerned of this department on 23/07/2024 in the presence of Ms. Nidesha (Manager) and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class-D "Assembly Building" and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 02/08/2024 at New Delhi by

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic./Branch), 1st Floor, P.S. Defence Colony, New Delhi-110049. (Ref. MHA Portal ID 2024071210912 dated 12/07/2024)

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire-fighting system.
- The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

N 19

To the last	INSPECTIO	N REPORT	आज़ादी	का	
1	Name & Address of the Building	M/s Uncafe (A U No S -35 A Groun New Delhi- 1100)	nit of Risa Curates ad Floor Green Park	Pvt Ltd) Plo Main Market	
2	Type of Occupancy	Group-D Assemb	ly Building.		
3	Building Comprised of	Basement, Ground Plus three upper floor (Restaurant running at ground floor only)			
4	Type of Case	Denoviol			
5	Details of Previous NOC	F6/DFS/MS/EH/2021/SZ/164 dated 30/07/2021			
6	Fire Safety Directives Letter No	UBBL-2016 / NB	C Part-IV	12 PL	
7	Date of Inspection	23/07/2024			
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers from the building side	Ms. Nidesha			
10	Year of construction	1975	(Nept 6 1: 5:10 - 8	10/07/2024	
11	Applicant letter No.	MHA Portal ID 2024071210912 dated 12/07/2024  Provided at Site Remarks			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL/NBC Provided at Site Remarks Requirement MR/NMF			
1	Access to Building.	Startes	of 1987) in the latest of the	) AD	
-	Road width	06 mtr	09 mtr	MR	
	and the state of t	N/A	N/A	N/A	
	Gate width  Wilds of internal road	N/A	N/A	N/A	
	Width of internal road	AND THE PROPERTY OF THE STATE O	in gradent o		
2	Number, width, type & arrangement of ex	secretary of	AND THE PARTY OF T		
	a) Number of Staircase	N/A	N/A	N/A	
	> Upper floors.	N/A	N/A	N/A	
J-10	> Basement floor.		Standby Pun		
71.00	b) Width of Staircase	N/A	N/A	N/A	
All.	> Upper floors	20.002555	MA N/A	N/A	
AV	> Basement floor	mag N/A	sagoni quarit e		
AW	c) Protection of exits	27/4	toval N/A 1	N/A	
	> Fire check door	N/A	N/A	N/A	
	Pressuitzation	IV/A	One	MR	
507	d) No. of continuous staircase to terrace	Required	N/A	N/A	
	e) Width of corridor	N/A	01001 2 - 11 - 14	MR	
	n Door size	1.50 mtr x 2	1.50 mtr each	MIK	
3	Compartmentation.	duning and to		1 37/4	
7.21	Fire check door.	N/A	N/A	N/A	
MW	Sealing of electrical shafts.	N/A	N/A	N/A	
NEA	Fire rating of shaft door.	N/A	N/A	N/A	
14	water curtain	N/A	N/A	N/A	
214	• Fire dampers.	N/A	N/A	N/A	
4	Smoke Management system.		Mic Combine	31 31	
	Basement	30 ACPH	N/A	N/A	
7.7	Upper floors	12 ACPH	N/A	N/A	
5	Fire Extinguishers.	nua (fel n	· Committeening		
Lor	Total numbers	06 Nos	06 Nos	MR	
	Types	ABC/CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR	
	ISI Marking	ISI marked	Provided	MR	
6	First Aid Hose Reels.		AAD 8 - Es	7 33	
arly	Total numbers on each floor.	One	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	
	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	00000000000000	A A O FIGURE	IVII	
7	Automatic fire detection & alarming syste	m.	NOVEMBER DOM:		

	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	NA	N/A
10	Automatic Sprinkler System	A = 01	A20 circle a people of	
	Basement	N/A	N/A	N/A
	Ground floor.	N/A	Provided	N/A
11	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.  • Size of Riser/Down-comer		JESS No-DIER, SIL	
	Number of Hydrant per floor	100 mm	Provided	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.	One	Provided	MR
7.7	L RECEIPT AND A	\$ 27/4 T	of the safety a 'R	
	Total number of hydrants.     Hose box.	N/A	N/A	N/A
13	Pumping arrangements.	N/A	N/A	N/A
	Ground Level		di, ye ret i e	
	Discharge of main pump.	N/A	NI/A	3777
	Head of main pump.	N/A	N/A N/A	N/A
	Number of main pumps.	N/A N/A	N/A N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
VALUE.	Jockey Pump head.	N/A		N/A
	Standby Pump output.	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	<ul> <li>Auto Starting/Manual Stopping.</li> <li>Pump house access.</li> </ul>		N/A	N/A
	Terrace Level	N/A	N/A	N/A
4	Discharge of pump.	450 LPM	e True died vlaa	100
	> Head of numn	430 LPM	Provided	MR
	> Power supply.	TREETINGS OF THE LOCAL	Provided	MR
	> Auto starting of pump.	Required Required	Provided Provided	MR
14	Captive water storage for fire fighting.	Required	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	MR
	Underground tank capacity.	N/A	N/A	N/A
	> Draw-off connection.	N/A	N/A	N/A
	➤ Fire Service Inlet.	N/A	N/A N/A	N/A
	➤ Access to tank.	N/A	N/A N/A	N/A
	Overhead tank capacity.	20,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	of the Have	HEALT OF THE STATE	
	Pressurization of lift shaft.	N/A	N/A	N/A
μK	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
Mic	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	N/A	N/A	N/A
8	Refuge Area		Mark on half are	
1	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
9	Fire Control Room.		MANAGE TO THE ME	
-	Detector system panel.	N/A	N/A	N/A
- 9	- Detector of prom baner	N/A	N/A	N/A



	<ul> <li>Flow switch panel.</li> <li>PA system panel.</li> <li>Battery backup.</li> <li>Building floor plan.</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found

functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2021/SZ/164 dated 30/07/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ) F.T. fetter i pritup synature P1

ms cell