



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HQRS: DELHI FIRE SERVICE: CONNAUGHT PLACE, NEW DELHI

No.F.6/DFS/MS/GH/2024/SZ/331

Dated: .06/.08./2024

FIRE SAFETY CERTIFICATE

Certified that the Lodging House in the Name & Style of M/s BMK Business and Resorts Pvt Ltd located at B-2, Greater Kailash Enlave-1, New Delhi 110048, comprised of Basement (Vacant), ground plus three upper floors (Total- 27 Guest Room) Fire Safety Certificate by this department vide letter F6/DFS/MS/GH/2021/SZ/459 dated 30/09/2021. The premise was re-inspected by the officer concerned of this department on 23/07/2024 in the presence of Mr. Ali (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" and Validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

06 08 /2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

- 1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2024071611093 dated 16/07/2024 & MHA Portal ID 2024070710578 dated 07/07/2024)
- 2. The Dy. Commissioner, (Green Park Zone) Municipal Corporation of Delhi, Green Park, New Delhi 110016 with respect to basement in the building. (Email dyancsz@mcd.gov.in

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

4. All the staff members must know the correct method of operation of fire fighting system.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

NBT



	Name & Address of the Building	N REF	PORT	don't rough		
1	Traile & Fiduress of the Building	M/s BMK Guest House B-2 Greater Vailant				
	Tune of Occupancy	Enclave-1, New Delhi 110049				
2	Type of Occupancy Building Comprised of	Kesider	itial, "Grou	up-A" (Guest House)		
3	Type of Case	Residential, "Group-A" (Guest House) Basement, Ground + 03 upper floors				
5	Details of Previous NOC	Renewal				
_	His Sefet Division	F6/DFS/MS/GH/2021/SZ/459 dated 30/09/2021				
7	Pire Safety Directives Letter No	Nil Nil				
8	Date of Inspection	23/07/2024				
9	Name of the Inspecting Officers	DO (South) & ADO (BCP)				
	Name & Designation of Officers	Mr. Ali (Manager)				
	from the building side					
10	Year of construction	2006 Guest House ruining at Ground plus three upper f			ee unner floor	
11	Applicant letter No.	total 27 Guest Rooms				
S. No.	Minimum standards on Fire Prevention	MHA Portal ID 2024070710578 dated 07/07/2024				
	and Fire Safety U/R 33	Old	NOC	Provided at Site	Remarks	
1	Access to Building.	requi	rements	40400 (Cred. Det 1	MR/NMR	
	Road width		GINIAPA	The managed and a second		
	Gate width		quired	09 mtr	MR	
	Width of internal road		NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits.	-	NA-	-NA-	-NA-	
-36.15	a) Number of Staircase		Lund our	The substitute of		
	> Upper floors.		Spirit Miles	ACTION OF THE PROPERTY OF THE		
AK.	Basement floor.	Re	quired	02 Nos	MR	
AW.	CA CAMBRIAN CONTROL CO	Required		02 Nos	MR	
	b) Width of Staircase		histopsis	mail all are se		
A.S.	> Upper floors	Required		1.25 mtr & 1.0 mtr	MR	
dille	➤ Basement floor	TOTAL CO.	A STORY		(old case)	
-MA	c) Protection of exits	Required		1.25 mtr & 1.0 mtr	MR (old case)	
	Fire check door	As pe	r clause 7.3	31 in UBBL 2016	(old case)	
HIV	> Pressurization	Required		Provided	MR	
		F.	NA-	-NA-	-NA-	
36.86	d) No. of continuous staircase to terrace	Re	quired	Two Provided	MR	
AZ-	e) Width of corridor		NA-	Southern -NA-	-NA-	
3	1) Door size	Giela	lm	1.20mtr (Final Exit)		
	Compartmentation.	-/-/	- TINISteller	(Zinta Exit)	MR	
$-\lambda_1 P_1 -$	Fire check door.	R	equired	Provided in basement	MR	
-A3-	Sealing of electrical shafts.		-NA-	-NA-		
1.7	Fire rating of shaft door.		-NA-	-NA-	-NA-	
2007	Water curtain Ping demonstration		-NA-	-NA-	-NA-	
-	Fire dampers	-	-NA-	-NA-	-NA-	
4	Smoke Management system.	As per clause 7.31 in UBBL 2016				
7.77	Basement	30	ACPH	Exhaust fan provided	2.00	
1,1	Upper floors		equired			
5	Fire Extinguishers.		STATE OF THE	Exhaust fan provided	MR	
SIV	Total numbers		10 Nos	ar Commence or a control		
	Types		3C / CO2	Provided	MR	
33400	ISI Marking			ABC & CO2	MR	
6	First Aid Hose Reels.	18	I marked	Provided	MR	
100	Total numbers on each floor.		77.	was I Builde	Si Pi	
JK.			One	Provided	MR	
	• Length of hose-reel hose.		30 mtr	Provided		
	Nozzle Diameter			many Street Co.	MR	
					(9.1	
7	Automatic fire detection & alarming system		5 mm	Provided	MR	

	Type of detectors	CoMole		आगृत महोत्स	
	Location of Main Panel	Required	Provided	MR	
	Location of Repeater Panel	-NA-	Provided	MR	
	 Alternate source of power 	Required	-NA-	-NA-	
	Hooter's location	Required	Provided	MR	
8	MOEFA		Provided	MR	
9	Public Address System	Required	Provided	MR	
10	Automatic Sprinkler System	Required	Provided	MR	
	Basement	20, 1995	amuli(legs	IVIK	
	Upper floors.	Required	Provided	MR	
-		-NA-	-NA-	-NA-	
	Sprinkler above false ceiling	-NA-	-NA-	-NA-	
11	Internal Hydrants.			-INA-	
	Size of Riser/Down-comer	Required	100 mm) (D	
NO.	Number of Hydrant per floor	-NA-	-NA-	MR	
	Hose box.	-NA-	-NA-	-NA-	
12	Yard Hydrants.		-11/1	-NA-	
- 1	Total number of hydrants.	-NA-	-NA-		
5 T	Hose box.	-NA-		-NA-	
13	Pumping arrangements.	-NA-	-NA-	-NA-	
	Ground Level		Application of		
		NTA .	tertes have graffic as		
	 Discharge of main pump. Head of main pump. 	-NA-	-NA-	-NA-	
	Number of main pumps.	-NA-	-NA-	-NA-	
	Jockey Pump output.	-NA-	-NA-	-NA-	
	> Jockey Pump output. > Jockey Pump head.	-NA-	-NA-	-NA-	
		-NA-	-NA-	-NA-	
	 Standby Pump output. Standby Pump head. 	-NA-	-NA-	-NA-	
		-NA-	-NA-	-NA-	
TVI	 Auto Starting/Manual Stopping. Pump house access. 	-NA-	-NA-	-NA-	
		-NA-	-NA-	-NA-	
	Terrace Level				
	Discharge of pump.	450 LPM	Provided	MR	
	➤ Head of pump.	-NA-	-NA-	-NA-	
	> Power supply.	Required	Provided	MR	
6.95	➤ Auto starting of pump.	-NA-	-NA-	-NA-	
14	Captive water storage for fire fighting.		WATER CHIEFT	2 12	
and really	Underground tank capacity.	20,000 ltr	Provided	MR	
	> Draw-off connection.	-NA-	-NA-	-NA-	
	➢ Fire Service Inlet.	-NA-	-NA-	-NA-	
	> Access to tank.	-NA-	-NA-	-NA-	
1.15	Overhead tank capacity.	10,000 ltrs	10,000 ltrs	MR	
N SA	T '4 C'	Required	Provided	MR	
15	Exit Signage.	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TO THE PERSON NA			
16	Provision of Lifts.	-NA-	-NA-	-NA-	
	Pressurization of lift shaft.	-NA-	-NA-	-NA-	
	Pressurization of lift lobby.	-NA-	-NA-	-NA-	
	Communication in lift car.	Required	Provided	MR	
No.	Fireman's switch.	-NA-	-NA-	-NA-	
:137	Lift signage.	Required	Provided	MR	
17	Standby Power Supply	Required	Almost Been Marilla		
18	Refuge Area	-NA-	-NA-	-NA-	
200	Total area		-NA-	-NA-	
	• Location	-NA-	Tarana Sala		
19	Fire Control Room.		-NA-	-NA-	
19	Detector system panel.	-NA-	STA II	-NA-	
	• Detector system paner.	-NA-	-NA-	1	

. .

Flow switch panel		आर	त महोत्सव		
Tiow switch panel.	-NA-	-NA-			
PA system panel.	-NA-	-NA-	-NA-		
Battery backup.	***	-NA-	-NA-		
Building floor plan.	-NA-		-NA-		
20 Special Fire Protection System for the	Special Fire Protection System for the Protection of special Risk, if any.				
	or opecial Risk, if any.				

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 379 dated 28/06/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2021/SZ/459 dated 30/09/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

approved, F.T. Letter in protup