

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2024/316

Dated: 01 / 08

FIRE SAFETY CERTIFICATE

Certified that the M/s Gulistan Guest House located at 3861, Khirki Taffazzul Hussain, Jama Masjid, Delhi - 06, comprised of Ground + 04 upper floors: Ground floor - (reception + 01 dormitory with 03 beds), 1st floor - (02 guest rooms), 2nd floor - (02 guest rooms), 3rd floor -(02 guest rooms) & 4th floor - (not in use), for total 06 guest rooms & 01 dormitory was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2021/46 dated 01.02.2021. The building/premises was re-inspected by officer concerned of this department on 22.07.2024 in presence of Mohd. Imran (Owner Son) and found that building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 23.07.2024 stating not to use any floor above third floor for any purpose. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)", ground floor - (01 dormitory with 03 beds), 1st floor - (02 guest rooms), 2nd floor - (02 guest rooms) & 3rd floor - (02 guest rooms) for total 06 guest rooms & 01 dormitory with 3 beds upto 3rd floor only, with effect from01.108.12024. for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and, subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Director Delhi Fire Service ol

Copy to:-

- 1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defense Colony, New Delhi w.r.to ID No. 2024061109213 dated 11.07.2024.
- 3. The Licensee, M/s Gulistan Guest House at 3861, Khirki Taffazzul Hussain, Jama Masjid, Delhi.

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 9. The occupancy of above 3rd floor shall not be allowed as per clause 7.31 in UBBL-2016.

1	Na	mo Prodd	TION REPORT			
		me & address of the building	M/s Gulistan Guest House at 3861, Khirl Taffazzul Hussain, Jama Masjid, Delhi-06.			
2	Building is comprised of		Ground + 04 u	nnor Goo-	Deini-06.	
			Ground floor	pper 1100rs		
			Ground floor - reception + 01 hall (used a dormitory with 03 beds)			
			1" floor - (02 g	ust rooms)		
			2 nd floor (02 g	uest rooms)		
	١,		2 nd floor – (02 guest rooms) 3 rd floor – (02 guest rooms)			
			4th floor (not	in co		
			23.07.2024)	in use as per aff	idavit date	
3	Ty	pe of occupancy		A 1)		
4	Ty	pe of case	Residential (Group A-1) Renewal			
5						
_	Details of previous FSC		F6/DFS/MS/GH/NDZ/2021/46 dated			
6			01.02.2021			
7		e safety direction letter no.	Nil		197	
2	_	te of inspection	22.07.2024			
8		me of the inspecting officers	Sumit Kumar, A			
9		me of the designation of officer m the building side	Mohd. Imran (Owner Son)			
10	Ye	ar of construction	1972			
11	Ap	plicant's letter no.	Online application no. 2024061109213 date			
			11.07.2024			
S.No	Minimum Standards on fire Prevention and fire safety requirements U/R 33		Requirement/ Existing fire	Provided at Site	Remarks MR/	
			safety		NMR	
1	Access To Building:					
	Ro	ad width	NA	03 m	NA	
	Ga	te width	NA	NA	NA	
	Width of internal road		NA	NA	NA	
2	Nu	mber, Width, Type and Arrang	gement of Exits:			
	A	Number of staircases		- 41		
		a Upper floor	01 no.	01 no.	MR	
		b Basement	NA	NA	NA	
	В	Width of staircases				
		a Upper floor	80 cms.	86 to 88 cms.	MR	
		b Basement	NA	NA /	NA	
	C	Protection of exits				
		a Fire check door	NA	NA	NA	
		b Pressurization	NA	NA	NA	
	D	No. of continuous staircases	01 no.	01 no.	MR	
		to terrace	NIA	NIA	NA	
	E	Width of corridor	NA	NA		
	F	Door size	1.0 mtr.	1.0 mtr.	MR	
3	_	mpartmentation:	274	I NIA	NA	
	A	Fire check door	NA	NA	NA NA	
	В	Sealing of electrical shafts	NA	NA	NA NA	
	C	Fire rating of shaft door	NA	NA	NA NA	
	D	Water curtain	NA	NA	NA NA	
	E	Fire dampers	NA	NA	IVA	
4	Sm	oke Management System:	1.2 1 2007	P.1	MR	
	A	Upper floors	12 ACPH	Exhaust fans	NA	
Ì	В	Basements	NA	NA	NA (4)	

5.		tinguisher:	00	00 === '	MR		
> = =	A	Total numbers	08 nos.	08 nos.	N========		
	В	Types	CO ₂ & ABC	Provided	MR		
	C	ISI marking	Required	Provided	MR		
6	First-Aid-Hose Reels:						
	A	Total numbers of each floor	NA	01 no. at 1 st floor	NA		
	В	Length of hose reel hose	NA	30 m	NA		
	C	Nozzle diameter	NA	05 mm	NA		
7	Automatic Fire Detection And Alarming System:						
	A	Type of detectors (CO type)	Required	Provided	MR		
	В	Location of main panel	Required	Provided at ground floor	MR		
	С	Location of repeater panel	NA .	NA	NA		
	D	Alternate source of power	Required	Provided	MR		
•	E	Hooters	Required	Provided	MR		
8	MOEF		NA	NA	NA		
9	x - x.c.ai-c.a-	Address System:	Required	Provided	MR		
10		atic Sprinkler System:	Isu	Late			
	A	Basement	NA	NA	NA		
	В	Upper floor	NA	NA	NA		
	С	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants:						
	A	size of riser/down-comer	NA	NA	NA		
	В	Number of hydrants per floor	NA	NA	NA		
	C	Hose box	NA	NA	NA		
12	Yard Hydrants:						
	A	Total number of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	NA		
13	Pumping Arrangements:						
-,-,-	A Ground level						
	a)	Discharge of main pump	NA	NA	NA		
	b)	Head of main pump	NA	NA NA	_		
	c)	Number of main pumps	NA	NA NA	NA		
	d)	Jockey pump out put	NA	NA NA	NA		
	e)	Jockey pump head	NA	252373	NA		
	f)	Standby pump out put	NA NA	NA NA	NA		
	g)	Standby pump head	NA	NA	NA		
	h)	Auto starting /manual	NA	NA NA	NA		
	i)	stopping		INA .	NA		
	B	Pump house access Terrace level	NA	NA	NA		
	Terrace level						
	b)	Discharge of pump Head of the pump	NA	225 LPM	NA		
	c)	Power supply	NA	40 m	(NA		
	d)	Auto starting C	NA	Provided	NA		
	=/	Auto starting of pump	NA	NA	NA		

W

_	Captive Water Storage For Fire Fighting:						
-	A	Underground tank capacity	NA	NA	NA		
	B	Draw-off connection	NA	NA	NA		
	C	Fire service inlet	NA	NA	NA		
	D.	Access to tank	NA	NA	NA		
	E	Overhead tank capacity	NA	2,500 ltrs. (NA		
15	Exi	t Signage:	Required	Provided	MR		
16	Provision of Lifts:						
	A	Pressurization of lift shaft	NA	NA	NA		
	В	Pressurization of lift lobby	NA	NA	NA		
	C	Communication in lift car	NA	NA	NA		
2.0	D	Firemen's grounding switch	NA	NA	NA		
	E	Lift signage	NA	NA	NA		
17	Sta	indby Power Supply:	NA	Provided	NA		
18	Refuge Area:						
	A	Total area	NA	NA	NA		
	В	Location	NA	NA	NA		
19	Fire Control Room:						
	A	Detector system panel	NA	NA	NA		
	В	Flow switch panel	NA	NA	NA		
	C	Pa system panel	NA	NA	NA		
	D	Battery backup	NA	NA	NA		
	E	Building floor plans	NA	NA	NA		
20		pecial Fire Protection Systems F pecial Risks, If Any:	or Protection of	NA	NA		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Shortcomings communicated vide letter No.F6/DFS/MS/GH/NDZ/2024/250 dated 21.05.2024 has been rectified.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2021/46 dated 01.02.2021 is recommended to be renewed upto 3rd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Sumit Kumar Designation ADO (SPM)

Col Color

23/1/24

Liv Japy

Denoetry May 19

Herson