GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2024/320

Dated: 01/.08/2024

FIRE SAFETY CERTIFICATE

Certified that the M/S Hotel Worth, guest house located at Plot no. 02, Block no. 80-A, Krishna Market, Paharganj, New Delhi comprises of B+ Gr.+ three Upper floors, Ground floor-reception & first to third floor (08 room at each floor) total 24 Guest rooms up to third floor owned/occupied by Hotel Worth, guest house was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2021/131 dated 10/03/21. Now, the premise was inspected by the officer concerned of this department on 20/07/24 in the presence of Manager and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor-reception & first to third floor (08 room at each floor) total 24 Guest rooms up to third floor and valid up to the period of three year from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

DIRECTOR Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, New Delhi: to ensure the occupancy in the building.
- The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2024071310942 dated 13/07/24.
- 3. The Manager, M/S Hotel Worth Plot no. 02, Block no. 80-A, Krishna Market, Paharganj, New Delhi.

Condition for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid for guest house up to third floor only.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned and basement shall be used as per BBL concerned
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

9. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

1. Name & address of the building: M/S Hotel Worth Guest house, Plot no. 02, Block

No. 80-A, Krishna Market, Pahar Ganj, New Delhi. Building is Comprised of basement +Gr.+ Three upper floors of 1st floor to 3rd floor (08 guest rooms at each floor)

total 24 guest rooms.

Basement (other property) & restaurant at ground floor.

2. Type of occupancy:- Residential, Sub Division-A-1

Ground (reception) 1st to 3rd

floor (08 room at each floor, total 24 rooms)

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/GH/NDZ/2021/131 dated

10.03.2021

5. Fire safety directives No.-

N/A 20/07/2024

Date of inspection:-

Sh. Ravinder Singh, ADO (CC)

7. Name of the inspecting officer:-

8. Name & designation of officer

Manager

From the building side:9. Year of construction:-

2020

10. Applicant's letter No:-

10. Applicant's letter No:-		ID No. 2024071310942 dated 13/07/24. old case			
	Minimum Standards on fire Prevention and fire safety U/R 33	UBBL- 2016/NBC part-4 2016	Provided at site		
l.	Access to Building				
	1) Road width	06	15 mtr	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
	Number, Width Type & Ar	rangement of Ex	rite	IV/A	
	A. Number of staircases	general of E			
	1. Upper floors	02 Nos.	02 Nos.	MR	
	2. Basements	N/A	N/A		
	B. Width of staircase		11/2	N/A	
	1. Upper floors	1.5mtr.	1.5 m each	100	
	2. Basements	N/A	N/A	MR C	
	14	1	IVA	N/A(other	
	C. Protection of exits			property)	
	1. Fire check door	Required	Provided		
	2. Pressurization	N/A	N/A	MR	
	D. No. of continuous	02	02	N/A	
	staircase to terrace		02	MR	
	E. Width of corridor	1.5mtr	1 6		
	F. Door size (Room)	1.0 meter	1.5mtr	MR	
	Compartmentation	1.0 meter	1.0 meter	N/A	
	1) Fire check door	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain		N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
	Smoke Management System	N/A	N/A	N/A	
	1) Basements			IVA	
	2) Upper floors	N/A	N/A	N/A	
		12 a/c per hour	provided	MR	
-	71	/	- 6		
_	Fire Extinguishers		The state of the s		
	1) Total numbers	12 Nos.			
	1	12 1405.	14 Nos.	MR	

	NIA				
		ABC & CO2	ABC & CO2	MR	
		Required	Provided	MR	
• Pa	First-Aid Hose Reel		(
		01	01	MR	
		30 mtr.	30 mtr. /	MR	
		05 mm	05 mm	MR	
1	Automatic Fire Detection & Alarming System				
		Required	Provided	MR	
	2) Location of main panel	Ground floor	Provided	MR	
		N/A	N/A	N/A	
	4) Alternate source of power	Required	Provided	MR	
	5) Hooter's Location	Ground floor	Provided	MR	
3.	MOEFA	N/A	N/A	N/A	
).	Public Address System	Required	Provided		
10.	Automatic Sprinkler System		2.011000	MR	
	1) Basement	N/A	N/A	MD	
	2) Upper floors	N/A	N/A	MR	
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling	-	I WALL	N/A	
11.	Internal Hydrants				
	1) Size of riser/down-comer	N/A	N/A	N//	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor		N/A	N/A	
	3) Hose box	N/A	N/A	NIA	
12.	Yard Hydrants	- 44.4	IVA	N/A	
	1) Total number of hydrants	N/A	N/A	I NU	
	2) Hose box	N/A		N/A	
13.	Pumping Arrangement	I	N/A	N/A	
	1) Ground level	N/A	NI/A		
	a) Discharge of main	N/A	N/A	N/A	
	pump	IV/A	N/A	N/A	
	b) Head of main pump	N/A	NI/A		
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual	N/A N/A	N/A	N/A	
	stopping	10/4	N/A	N/A	
1	2) Terrace level				
	a) Discharge of pump	450 LPM	450 X D) C	1	
	b) Head of pump	30 mtr.	450 LPM	MR	
1	c) Power supply	Required	30 mtr.	MR	
	d) Auto starting of pump	Required	Provided	MR	
14		150	Provided	MR	
14.	Captive Water Storage for F	1			
V	1) Under ground tank	N/A	N/A	N/A	
	capacity				
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
1	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank cap.	5000 ltr.	5,000 ltr.	MR	
				1	
15.	Exit Signage.				
~~,	DAIL DIGHAGE.	Required	Provided	MR	



16.	Provision of Lifts.	_		
	 a) Pressurization of lift shaft 	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided /	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any: fire extinguishers are provided near electric panel			MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Further, there is a restaurant at ground floor having separate entry and exit and FSC has already been issued.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2021/131 dated 10/03/21 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the Inspecting Officer

Name: Raynder Singh

Designation: ADO (CC)