



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No.F.6/DFS/MS/Residential/2024/SZ/5/2

Dated: 14/0 8 /2024

FIRE SAFETY CERTIFICATE

Certified that the New Boys Hostel-A, Near Dhobi Ghat (Satpura Hostel), IITD Campus, Hauz Khas, New Delhi-110016 comprised of Basement, Ground & Three Upper Floors was issued FSC by this department vide letter no. F6/DFS/MS/Residential/SZ/2018/1686 dated 18/07/2018. The premise was reinspected by the officer concerned of this department on 05/08/2024 in the presence of Mr. Ashok Kumar and found that the said Residential building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and the building block is fit for occupancy class "Group A Residential building" with effect from _/4/02_/2024 for a period of five years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on 14.08.20.24....at New Delhi by.

(ATUL GARG)
DIRECTOR
IRE SERVICE

Copy to:-

1. New Boys Hostel-A, Near Dhobi Ghat (Satpura Hostel), IITD Campus, Hauz Khas, New Delhi-110016.

2. The Executive Engineer (Bldg.), MCD, Jal Vihar, Lajpat Nagar, Delhi-110024.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



INSPECTION REPORT

1. Name& address of the building : New Boys Hostel-A, Near Dhobi Ghat (Satpura Hostel), IITD Campus, Hauz

Class-A "Residential"

2. Type of Occupancy Basement+ Ground+ Three Upper Floors

3. Comprised of Renewal

4. Type of Case F6/DFS/MS/Residential/SZ/2018/1686 dated 18/07/2018

5. Details of Previous NOC 6. Fire Safety directives letter No : F6/DFS/MS/BP/2002/1453dated 06/09/2002

7. Date of inspection

: DO (South) & ADO (BCP) Name of Inspecting Officer
 Name and designation of officers
 From the building side : N

: Mr. Ashok Kumar

11. App		truction : 2005 etter No. : outdoo um Standards on fire prev	ention and	728 dated 23/05/2018 BBL/NBC	Provided at site	Remarks MR/NMR	
S. No.	fire saf	ety U/R 33	Eagraded?	Requirement	SHOW IN SHOW IN	MIK/NMIR	
	Access	to building			6m	MR	
1.	Road width		6m -NA-	-NA-	-NA-		
	•	Gate width		-NA-	-NA-	-NA-	
	•	Width of internal road			Company to the second		
2	Number, Width, Type & Arrangement of Exits						
2.	a Num	a. Number of staircases			GF to 3 rd F: 8 Nos	MR	
	•	Upper Floors		Required	GF to 1st F: 1 Nos	IVIIC	
	-					MR	
4		Basements		Required	4 Nos	IVIK	
	h Wid	th of staircases		dvn	of organic actions as		
	0. 1120	AV-		- squart	GF to 3 rd F: 1.27m,		
	-	-A.M-		tos	1.27m, 1.25m, 1.24m,	727.284	
		Upper Floor	4.71-	1.25m	1.23m, 1.24m, 1.23m,	MR(old case)	
		- AM-		t jug lu	1.25111		
		100		fend	GF to 1 st F: 1.15 Nos		
	-	47.		1.25m	1.16m, 1.25m, 1.23m,	MR(old case)	
		Basements		2200	1.24m		
	c. Prote	ction of exits					
	•	Fire check door		Required in Basement	Provided	MR	
MR		Pressurization		-NA-	-NA-	-NA-	
	d.	No. of continuous staircase	s to terrace	Required	1 Nos	MR(old case)	
		Width of Corridor		1m head	Provided	MR	
	e.	Door Size		1m	1m (final exit)	MR	
3.		rtmentation		AMANT PRE	(1111 (1111 (1111)		
			Tylis/S	Required in Basement	Provided	MR	
,H)	le e	Fire check door		President and the state of the	-NA-	-NA-	
		Sealing of electrical shafts Fire Rating of shaft door		-NA-	-NA-	-NA-	
707		Water Curtain		-NA-	- NTA		
311		Fire Dampers		-NA-	-NA-wy -	-NA-	
JIM		3090-01010111111111111111111111111111111	Riggiff	-NA-	-NA-	-NA-	
4.	Smoke Management System						
		Basements	2 %	30 a/c per hour	Exhaust Fan Provided	MR	
2/1	•	Upper floors	167X	12 a/c per hour	Natural Ventilation	MR	
5.	Fire Ex	tinguishers	777	1917	OF BERTHAMAN 2 W		
7.5		Total numbers	775	Required	30 No's	MR	
WY.		Types	4.45	ABC/W. CO ₂ /CO ₂	15/15/- No's	MR	
10	3	IS marking	A 11	ISI	Yes	MR	
	First-A	id Hose Reels		131	165	At	
			Doguid	Haras Plant AND) (D		
-42-	- 1	Total numbers on each floo	Jr A. A.	Required	Upper Floors: 4 Nos Basement: 2 Nos	MR	
Jus.		Length of hose reel hose Nozzle diameter	1.05	Required	30m	MR	
	_	MOZZIE GIMINETEL		Required	5mm	MR	

			7/-	_\
		6/19	आज़ादी का अमृत मह	त्सव
	• Tyme of L			-NA
mili .	• Type of detectors	-NA-	-NA-	
terj -	Location of Main Panel	-NA-	-NA-	-NA
	Location of Repeater Panel	-NA-	-NA-	-NA
	Alternate source of power	-NA-	-NA-	-NA
	Hooters' Location	-NA-	-NA-	-NA
	MOEFA	N. H. H. J.C.D.	Provided	-NA
	Public Address System	-NA-	Provided	-NA
0.		-NA-	Tiovides	1 14
·	Automatic Sprinkler System	Required in Basement	Provided	MR
	Basement		-NA-	-NA
	Upper Floors Sprinkless have files willing	-NA-	-NA-	-NA
	Sprinkler above false ceiling	-NA-	-NA-	an'n
1.	Internal Hydrants	A Carlotte and to a	100mm	MR
	Size of riser/down-comer	Required	Upper Floors: 4 Nos	MR
137,713		Required	Upper Floors. 4 103	-
	Number of hydrants per floor		Basement: 2 Nos	MR
		Required	Upper Floors: 4 Nos	
	Hose Box		Basement: 2 Nos	
2.	Yard Hydrants	i b	2) (0)	-NA-
	Total number of hydrants	-NA-	2 Nos	-NA-
	Hose Box	-NA-	2 Nos	-1
13.	Pumping Arrangements		ments and the a	_
	Ground Level		274	-NA-
	Discharge of main Pump	-NA-	-NA-	-NA-
	> Head of Main pump	-NA-	-NA-	-NA-
	Number of main pumps	-NA-	-NA-	
	> Jockey Pump out put	-NA-	-NA-	-NA-
	> Jockey pump head	-NA-	10 -NA-	-NA-
	> Standby Pump out put	-NA-	-NA-	-NA-
	> Standby Pump Head	-NA-	-NA-	-NA-
	➤ Auto Starting/Manual Stopping	-NA-	-NA-	-NA-
	> Pump House Access	-NA-	-NA-	-NA-
1			Kinen terminas mera	
	Terrace level	900 LPM	2 Nos of 900 LPM	MR
	Discharge of pumpHead of the pump	35m	40m	MR
	Dower Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
	Captive Water Storage for fire fighting			
14.	> Underground tank capacity	-NA-	-NA-	-NA-
	> Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
1 3	> Access to tank	Required	Provided	MR
. · ·	Overhead Tank capacity	Required	20,000 Lts	MR
	Exit Signage.	Required	Provided	MR
15.	Provision of Lifts.		MEET TO MANAGEMENT AND COME.	27.1
16.	Pressurization of Lift Shaft	-NA-	-NA-	-NA-
	 Pressurization of Lift lobby 	-NA-	-NA-	-NA-
	Communication In lift Car	-NA-	-NA-	-NA-
	Fireman's Grounding Switch	-NA-	-NA-	-NA-
	Lift Signage	-NA-	52,927.11	-NA-
17.	Standby power supply	-NA-	-NA-	-NA-
18.	Refuge Area.	N/A	NA	VT.
10.	> Total Area	-NA-	-NA-	-NA-
1 7	> Location	-NA-	-NA-	-NA-
19.	Fire Control Room	374	rest controlling to a	1200
	Detector System Panel	-NA-	-NA-	-NA-
1 112	Flow Switch Panel	-NA-	-NA-	-NA-



<u> </u>	PA System Panel	-NA-	-NA-	-NA-
	Battery backup	-NA-	-NA-	-NA-
	Building Floor Plans	-NA-	-NA-	-NA-
0.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Residential/SZ/2018/1686 dated 18/07/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

letter in putup tor