GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/Educational/2024/SZ/42

Dated: 14/ 08/ 2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Institute of SAARC Studies Inter Disciplinary Research Centre, Academic Building No 10, at South Asian University Complex, Maidan Garhi, New Delhi 110068 comprised of Basement, Ground plus 07 Upper Floor owner/occupied by South Asian University have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 04/08/2024 on in the presence of Mr. Vinit & Mr. Vikas (Project) and that the premise is fit for occupancy class (Educational occupancy) with effect from 14/02/2024 for a period of Three years in accordance/ with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 201/

Issued on ______/4 o R / 2024 at New Delhi by

Copy to: -

1. The Executive Engineer (Bldg) HQ, MCD, 9th Floor, Civic Centre, Minto Road, New Delhi 110002.

2. The Shapoorji Pallonji & Company Pvt Ltd, located at 7th floor Kanchenjunga Building, 18- Barakhamba Road, New Delhi 110001.

Conditions for the validity of Fire Safety Certificate:-

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

4. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

5. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-

2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

01-6



- 1	INSPECTI	ON REPORT	1/0. N. T. T.		
1	Name & Address of the Building	M/s Institute of SAARC Studies Inter Disciplinary Research Centre, Academic Building No 10, at South Asian University Complex, Maidan Garhi, New Delhi			
2	Type of Occupancy	Educational occup		New Delli	
3	Building Comprised of	Basement, Ground plus 07 Upper floors New Case Nil			
4	Type of Case				
5	Details of Previous NOC				
6	Hire Safety Directives Letter No	F6/DFS/MS/BP/2016/157 Dated 05/07/2016			
7	Date of Inspection	04-08-2024			
8	Name of the Inspecting Officers	DO South & ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Vinit & Mr. Vikas (Project)			
10	Year of construction	2023	Told in a triple of their		
11	Applicant letter No.	SPCPL/SAU-PKG-III/DFS/2024/0996 dated 08/07/2024			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	NBC /UBBL requirements	Provided at Site	Remarks MR/NMR	
14	Access to Building.		codige Vs. swill		
	Road width	06 mtr	Provided	MR	
	Gate width	06 mtr	Provided	MR	
	Width of internal road	06 mtr	Provided	MR	
2.	Number, width, type & arrangement of exits.	-jerang	HERD STEWARTS IN	MIK	
471	a) Number of Staircase	veriousit ta	s Tro eximise A	_	
	▶ Upper floors.	04 Nos	Provided	MR	
	▶ Basement floor.	04 Nos	Provided	MR	
	b) Width of Staircase	011103	Tiovided	MIK	
SM	> Upper floors	1.50 mtr	Provided	MR	
	▶ Basement floor	1.50 mtr	Provided		
ZW.	c) Protection of exits	, so mu	Tiovided	MR	
	➤ Fire check door	Required	Provided	1 10	
886	▶ Pressurization	Required		MR	
MIN NER	d) No. of continuous staircase to terrace	-	Provided	MR	
	e) Width of corridor	Required 1.50 m	Provided	MR	
	f) Door size		Provided	MR	
3.	Compartmentation.	1.2 m	Provided	MR	
t N	Fire check door.				
in.		Required	Provided	MR	
	Sealing of electrical shafts.	Required	Provided	MR	
	Fire rating of shaft door. Water curtain	Required	Provided	MR	
		-NA-	-NA-	-NA-	
4.	• Fire dampers.	-NA-	-NA-	-NA-	
	Smoke Management system.			-11/1	
	Basement	12 ACPH	Provided	MR	
l/	Upper floors	12 ACPH	Provided	120	
5.	Fire Extinguishers.		1 TOVIDED	MR	
	Total numbers	Required	CON 1 T		
	Types	ABC / CO2	60 No's Provided	MR	
1/4	ISI Marking		ABC & W.CO2	MR	
6.	First Aid Hose Reels.	ISI marked	Provided	MR	
-	Total numbers on each floor.	60.11	neier Power Stupply	25 34	
Z-	Length of hose-reel hose.	02 Nos	Provided	MR	
	Nozzle Diameter	30m	Provided	MR	
7.	Automatic fire detection & alarming system	5mm	Provided		
	Type of detects		1 TOVIDEL	MR	
	Type of detectors	-NA-	-NA-	-NA-	
	4		A STATE OF THE PARTY OF THE PAR	-IVA-	

N/51

7/	
आज़ादी	
अमृत	महोत्सव

-11-47	Location of Main Panel Location - SP	-NA-	-NA-	-N/
-	Location of Repeater Panel	-NA-	-NA-	
	Allemate source of nower	-NA-	-NA-	-N/
-	Hooter's location	-NA-	-NA-	-N/
	MOEFA			-NA
9.	Public Address System	Required	Provided	M
10.	Automatic Sprinkler System	Required	Provided	MI
	Basement		LUKELLE YOUR	4
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling Internal III.	Required	Provided	MR
11.	Internal Hydrants.	-NA-	-NA-	-NA
	Size of Riser/Down-comer	100	A Alterative Allegan	V ₁ " 1 11
	Number of Hydrant per floor	100 mm	Provided	MR
En a	Hose box.	02 Nos	Provided	MR
12.	Yard Hydrants.	02 Nos	Provided	MR
144		4-940 A44 44	Emalibridgho restur	
	Total number of hydrants. Hose box.	04 No's	Provided	MR
13.	Pumping arrangements.	04 No's	Provided	MR
RIM	Ground Level		A TRAINER A	.,,,,,
Rive	Discharge of main pump.		1829 st 1 4	
	Head of main pump.	2850 LPM	Provided	MR
	Number of main pumps.	70m	Provided	MR
Hay	Jockey Pump output.	02 No	Provided	MR
	Jockey Pump head.	180 LPM	Provided	MR
	Standby Pump output	70m	Provided	MR
	Standby Pump head	2850 LPM	Provided	MR
	Auto Starting / Manual Stopping	70m Required	Provided	MR
	Pump house access.	Required	Provided	MR
	Terrace Level	Modulied	Provided	MR
	Discharge of pump.	900 LPM	n. de	
907	➢ Head of pump.	40 mtr	Provided	MR
30.7	➤ Power supply.	Required	Provided Provided	MR
14.	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for fire fighting.		Common UG Tank	MR
	 Underground tank capacity 	2,00,000 ltr &	PROFESSION CONTRACTOR	
	 Draw-off connection. Fire Service Inlet. 	3,00,000 ltrs	Provided	MR
2015	> Access to tank.	Required	Provided	MR
	Overhead tank capacity.	Required	Provided	MR
	tank capacity.	Required	Provided	MR
15.	Exit Signage.	25,000 ltr	Provided	MR
16.	Provision of Lifts.	Required	Provided	MR
	Pressurization of lift shaft.	Required	District Control	
	 Pressurization of lift lobby. 	Required	Provided	MR
1994	 Communication in lift car. 	Required	Provided Provided	MR MR
Hay.	Fireman's switch.	-NA-	-NA-	-NA-
MIN	• Lift signage.	-NA-	-NA-	-NA-
17.		Required	Provided	-NA-
18.		70011 10 11	THE TOYING	IVIK
117	Total area	-NA-	-NA-	-NA-
100	• Location	-NA-	-NA-	-NA-
19.		A DESTRUCTION OF THE PARTY OF T	Wilself Tell	RETEV
	 Detector system panel. 	Required	Provided	



Flow switch panel. PA system panel.	Required		
 PA system panel. 		Provided	MR
	Required	Provided	MR
 Battery backup. 	Required	Provided	MR
Building floor plan.	Required		MR
ecial Fire Protection System for the otection of special Risk, if any.	Required	Provided	MR
arther, the party has complied all that the cated by this department vide letter of expering in view of the substantially satisfies.	he observation / (ven no 71 dated 19/ sfactory compliance	Shortcoming already 04/2024.	issued &
	Building floor plan. ecial Fire Protection System for the otection of special Risk, if any. e fire protection system provided in at the time of inspection. arther, the party has complied all trated by this department vide letter of expense in view of the substantially satisfaction.	Building floor plan. Required Required	Building floor plan. Required Provided Provided Required Provided Provided Provided Provided Provided Provided Provided Provided Provided Provided

Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010 Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: \$h. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

opported, F.T. letter in protup your signature of