

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/ 808

Dated: 19 / 08/2024

FIRE SAFETY CERTIFICATE

Certified that the Teaching Tree School located at 109, Ashram Road, Budh Pur, Delhi110036, comprised of Ground & first floor only owned/occupied by the Teaching Tree School
have complied with the fire prevention and safety requirements in accordance with rule 33 of
Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on
03.08.2024 in the presence of Mr. Darshan Anand Bhardwaj (Owner) and observed that all
the fire safety arrangements as provided in the premises found in good working condition. The
premises have complied with requirements of circular issued by Director of Education vide letter
no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class 'Group B
Educational' with effect from ...19.1.0.8.120.2.9... for a period of three years, subject to
compliance of the conditions mentioned below:

Issued on ... 19 10. 8 20 24 ... at New Delhi

Atul Garg) Director 2:-011-23414000

Copy to: -

The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

2. The Manager, Teaching Tree School at 109, Ashram Road, Budh Pur, Delhi-110036.

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : Teaching Tree School at 109, Ashram Road, Budh Pur, Delhi-110036.

2. Composition of building : Ground & first floor only

3. Type of Occupancy : Educational

4. Type of Case : New 5. Details of previous NOC : Nil Fire Safety directives letter No : Nil

7. Date of inspection : 03.08.2024 Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Sh. Darshan Anand Bhardwaj (Owner)

10. Year of Construction : 2022

	Minimum Standards on fire prevention and fire safety U/R 33	Director of education circular dated 01.03.2011 Requirements	Provided at site	Remarks MR/NMR			
	Access to building						
	Road width	06m	06m	MR			
	Gate width	Directly accessible	Directly accessible	MR			
	Width of internal road	NA	NA	NA			
1	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	01	02	MR			
	Basements	NA	NA	NA			
	b. Width of staircases						
	Upper Floors	1.50m or less and 75cm	1.50m each	MR			
	Basements	NA	NA	NA			
	c. Protection of exits						
	Fire check door	NA '	NA	NA			
*	Pressurization	NA	NA	NA			
	d. No. of continuous staircases to terrace	NA	NA	NA			
	e. Width of Corridor	NA	NA	NA.			
	f. Door Size	01m	1.10m double door	MR			
	Compartmentation.						
	Fire check door	NA	NA	NA			
	Sealing of electrical shafts	NA	NA	NA.			
	Fire Rating of shaft door	NA	NA	NA			
	• Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
4	Smoke Management System.						
	Basements	NA	NA	NA			
	• Upper floors	NA	NA	NA			
	Fire Extinguishers						
	Total numbers	04nos	09nos	MR			
	Types	ABC/CO2	ABC—09	MR			
	ISI marking	ISI Marked	Yes	MR			
		I		1			



	Total numbers on each floor	N/2 NA	NA NA			
	Length of hose reel hose			1,		
	Nozzle diameter	NA	NA	N		
7		NA	NA	NA		
-	The detection and alamining system.					
	Location of Main Panel	NA NA	NA NA	NA NA		
	Location of Repeater Panel	NA NA	05/10/2947	NA NA		
	Alternate source of power	-0.000	NA -	24,6234		
	Hooters' Location	NA	NA	NA		
	and development and the state of the state o	NA	NA	NA		
8	MOEFA	NA	NA	NA		
9	Public Address System.	NA	NA	NA		
10	Automatic Sprinkler System.					
1	Basement	NA	NA NA	NA		
	Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants					
	Size of riser/down-comer	NA	NA	NA		
	Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
2	Yard Hydrants.	2				
-	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
, -	Control States of Section 2010	350	.32.5	1		
3 P	Pumping Arrangements. • Ground Level					
	Discharge of main Pump	27/1	N/A	N/A		
	0 100 00 00 00 00 00 00 00 00 00 00 00 0	N/A	N/A			
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	3 9 _ 4 _ 6 6		N/A	N/A		
	> Standby Pump Head	N/A N/A	N/A	N/A		
	> Auto Starting/ Manual stopping	N/A	N/A	N/A		
	> Pump House Access	4.9/4.5				
	Terrace level		NA	NA		
	➤ Discharge of pump	NA	NA NA	NA		
	> Head of the pump	NA		NA		
	> Power Supply	NA	NA NA	NA NA		
-	➤ Auto Starting of pump	NA	NA	1		
-	Captive Water Storage for fire fighting.					
Capt		NA	NA	NA NA		
	Underground tank capacity	NA	NA	NA NA		
)	Draw-off connection	NA	NA	NA		
)	Fire service inlet	NA NA	NA	NA		
>	Access to tank	Sec. 2	NA	NA		
	Overhead Tank capacity	NA	AP Sec	NA		
		NA	NA	1		
	ignage.		N/A	N/A		
Provis	ion of Lifts. Pressurization of Lift Shaft	N/A	IN/A			

16

_	Pressurization of Lift lobby	N/A	N/A	N/A		
	 Communication In lift Car Fireman's Grounding Switch 	N/A	N/A	N/A N/A		
	Lift Signage	N/A	N/A			
		N/A	N/A	N/A		
17	Standby power supply	NA	NA	NA		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2011, it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer

Name :-C.L. Meena

Designation:- ADO/RN

19/8/101

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8

2 10/8