

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/2024/ 792

Dated: 16/08/2024

## FIRE SAFETY CERTIFICATE

Certified that the Shree Uday Public School located at A-24, Bhagat Singh Park, Siraspur, Delhi-110042. comprised of Ground & First Floor only owned/ occupied by Shree Uday Public School was issued Fire Safety Certificated by this department vide letter F6/DFS/MS/School/WZ/2020/352 dated 16.09.2019. The premises was inspected by the officer concerned of this department on 03.08.2024 in presence of Sh. Pulkit Rana (Owner) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational" with effect from ...... 6. . 0.8. 2.9. for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 16. 08 2024.... at New Delhi by.

Ph:-021-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Managing Director, Shree Uday Public School located at A-24, Bhagat Singh Park, Siraspur, Delhi-110042.

## Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3 All the staff members must know the correct method of operation of firefighting system.

4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

any.

6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

## INSPECTION REPORT

1. Name & address of the building : Shree Uday Public School at A-24, Bhagat Singh Park, Siraspur,

Delhi-110042.

2. Composition of building : Ground & first floor only

3. Type of Occupancy : Educational
4. Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/School/WZ/2020/352 dated 16.09.2020

6. Fire Safety directives letter No : NBC Part-IV
7. Date of inspection : 03.08.2024

8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Sh. Pulkit Rana (Owner)

10. Year of Construction : 2009-2018

11. Applicant's letter No. : Letter No- Nil dated 15.07.2024

11. Applicant's letter No. Remarks Provided at site Requirement as per Minimum Standards on fire prevention MR/NMR Rule 35 (6) and fire safety U/R 33 Access to building MR 06m 06m Road width MR 4.80m 4.50m Gate width NA NA Width of internal road NA Number, Width, Type & Arrangement of Exits 2 a. Number of staircases MR 02 02 Upper Floors NA NA NA Basements b. Width of staircases MR 1.65m each 1.50m each NA NA Upper Floors NA Basements c. Protection of exits NA NA NA Fire check door NA NA NA Pressurization NA NA d. No. of continuous staircases to terrace NA NA NA NA e. Width of Corridor MR 1.07m 01m f. Door Size Compartmentation. NA NA NA Fire check door NA NA NA Sealing of electrical shafts NA NA NA Fire Rating of shaft door NA NA Water Curtain NA NA Fire Dampers NA NA Smoke Management System. 4 NA NA NA Basements MR Natural Ventilation Required Upper floors Fire Extinguishers 5 MR 08nos 06nos Total numbers ABC-08 MR ABC/CO2 Types MR Yes ISI Marked ISI marking

G

6	First-Aid Hose Reels.					
	Total numbers on each floor	NA	NA NA	N		
	Length of hose reel hose		45,000			
	Nozzle diameter	NA	NA	NA NA		
7	Automatic fire detection and alarming syst	NA NA	NA	NA		
	Type of detectors	NA NA	NA NA	1 11		
	Location of Main Panel	NA	NA NA	NA NA		
	Location of Repeater Panel	NA	NA NA	752317		
	Alternate source of power			NA		
	Hooters' Location	NA	NA	NA		
3	MOREA	NA	NA	NA		
	MOEFA  Diship Address Suntan	NA	. NA	NA		
0	Public Address System.	NĄ.	NA	NA		
U	Automatic Sprinkler System.			-		
	Basement	NA	NA	NA		
	Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
1	Internal Hydrants	-11				
	Size of riser/down-comer	NA	NA NA	NA		
	Number of hydrants per floor	NA	NA	NA NA		
	Hose Box	NA	NA	NA NA		
2	Yard Hydrants.					
	Total number of hydrants	/				
	Hose Box	NA	NA	NA		
	58(92,805)	NA	NA	NA		
3	Pumping Arrangements.					
	Ground Level			_		
	Discharge of main Pump	N/A	N/A	T 27/4		
	➤ Head of Main pump			N/A		
	➤ Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	➤ Standby Pump out put	N/A	N/A	N/A		
	➤ Standby Pump Head	N/A				
	➤ Auto Starting/ Manual	N/A	N/A N/A	N/A N/A		
	stopping > Pump House Access	N/A	N/A			
	Pump House Access     N/A N/A N/A      Terrace level					
	STATE OF THE STATE					
	Discharge of pump	NA NA	NA NA	NA		
	➤ Head of the pump	NA	NA	NA		
	➤ Power Supply	NA	NA NA	NA		
	➤ Auto Starting of pump	NA	NA	NA		
	Captive Water Storage for fire fighting.					
	Underground tank capacity	NA	NA NA	ŊA		
	➤ Draw-off connection	NA	NA NA	ŇA		
	> Fire service inlet	NA	NA	NA		
	> Access to tank	NA	NA NA	NA		
	Overhead Tank capacity	NA	NA	NA		
	Exit Signage.	Required	VAVA:	MR		
5			Provided			

11 6



			N/A	N/A	N/A
	•	Pressurization of Lift Shaft		N/A	N/A
	<ul> <li>Pressurization</li> </ul>	Pressurization of Lift lobby	by N/A	N/A	
		Communication In lift Car	N/A	N/A	N/A
		Car Country of Page 1 and Car Anna Car	N/A	27/4	N/A
	•	Fireman's Grounding Switch	N/A	N/A	
	Lift Signage	27/4	N/A	N/A	
			N/A	NA	NA
7	Standb	y power supply	NA	107	
8	Refuge Area.			N/A	N/A
U	>	Total Area	N/A	EAST TO SECURE	N/A
	>	Location	N/A	N/A	197-
19	III III III	ntrol Room	<u> </u>	4	
.,	N/A			N/A	N/A
		Detector System Panel		N/A	N/A
		Flow Switch Panel	N/A		N/A
		n. c	N/A	N/A	7
		ESTATION OF THE STATE OF THE ST	350	N/A	N/A
		Ratter hacklin	27/4	Lair	
	y.	5-100 Table 100	N/A	Vent	N/A
	9.	Batter backup  Building Floor Plans	N/A N/A	N/A	N/A
20		1012140000 K.Th		Vent	N/A N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/School/WZ/2020/352 dated 26.09.2019.

Signature of the Inspecting Officer
Name:-C.L. Meena
Designation:- ADO/RN

DO (NW)

My LED (NOT)

STR

CED Mingle

A DO MAN

ADO MAN

cont - - P.T.O.