

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No.F.6/DFS/MS/EH/2024/SZ/130

Dated. 0.7. / 0.5. / 2024

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s BO-Tai located at 6/4, Second Floor, Kalka Das Marg, Near Qutab Minar, Mehrauli, New Delhi comprised of Ground & Two upper floor owned/occupied by Unit of Massive Restaurant Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/SZ/2021/129 dated 13/07/2021. The restaurant premise was re-inspected by the officer concerned of this department on 30/04/2024 in the presence of Mr. Zorawar Kalra and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 07/05/2024 at New Delhi by

DELHI FIRE SERVICE 1 Vh

1. The Addl. Commissioner of Police, Lic/Branch, 1st Floor, P. S Defence Colony Delhi Copy to: -110049. (Ref MHA Portal ID 2024041204863 dated 16/04/2024)

## Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the

3. All the staff members must know the correct method of operation of fire fighting

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of 2.8 of

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

~	۱۱	,
1)	N	ь
v	,,	-

/		N118	7/-	
	INSPECTION	ON REPORT	आज़ादी	न
1	Name & Address of the Building	M/s BO-Tai, (Un located at 6/4, Se Qutab Minar, Mel	rant Pvt Ltd) s Marg, Near	
2	Type of Occupancy	Group-D Assemb		
3	Building Comprised of	Ground + Two up	per floor	
4	Type of Case	Renewal	1,15	
5	Details of Previous NOC	F 6/DFS/MS/EH/S	SZ/2021/129 dated 13	/07/2021
6	Fire Safety Directives Letter No	Approval of FPW		
200		30/04/2024	Facilities 4	
7	Date of Inspection	DO (South) & AD	O (BCP)	
8	Name of the Inspecting Officers	Mr. Zorawar Kalra		N 1.4
9	Name & Designation of Officers	56-2E	WORLD IN COLUMN SEA	
10	from the building side	2018 Restaurant	is running at 2 <sup>nd</sup> floo	r of the bldg.
10	Year of construction	MHA Portal ID 20	24041204863 dated	16/04/2024
11	Applicant letter No.	10/2	Provided at Site	Remarks
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Directive at N/3 & circular 2005	what shift a	MR/NMR
1	Access to Building.		6m	MR
•	Road width		N/A	N/A
-	Gate width	N/A	N/A	N/A
100	Width of internal road	N/A	an to healt *	
2	Number, width, type & arrangement of ex	its.	BELL MEDICAL ST	
4	a) Number of Staircase	The second secon	02 Nos	MR
A391	> Upper floors.	02 Nos	NA NA	N/A
Alst	> Basement floor.	N/A	pg pononia.	
ZV S	b) Width of Staircase		1.56 m & 1.01 m	MR (old case
A134	> Upper floors	1.56 & 1.1 m	1.56 m & 1.61 m	N/A
X7	Basement floor	N/A	LIDE GENIA	-
ASK	c) Protection of exits		N/A	
		N/A	N/A N/A	N/A
SUA.	> Pressurization	N/A	N/A	N/A
102	d) No. of continuous staircase to terrace	N/A	N/A	N/A
1697	e) Width of corridor	N/A	1.2 m 2 m	Old case
937	f) Door size	02 exit (02 & 1 m)	1.2 H 2 H	eD Id
3	Compartmentation.		N/A	N/A
11-11	Fire check door.	N/A	N/A	N/A
4/191	<ul> <li>Sealing of electrical shafts.</li> </ul>	N/A		N/A
AIM	<ul> <li>Fire rating of shaft door.</li> </ul>	N/A	N/A N/A	N/A
N. Par	Water curtain	N/A	According to the second	N/A
1111	• Fire dampers.	N/A	N/A	N/A
4	Smoke Management system.		with the collection	
		30 ACPH	N/A	N/A
W		12 ACPH	Provided	MR
	• Upper floors  Fire Extinguishers.	0-15424-5(-334)		
5		06 Nos	07 Nos	MR
	Total numbers     Types	ABC/CO <sub>2</sub>	ABC- & CO <sub>2</sub>	MR
du	• Types		Provided	MR
	• 131 Marking	ISI marked	Flovided	IVIIX
6	First Aid Hose Reels.	000	Provided	MR
1	Total numbers on each floor.	One	Provided	MR
	Length of hose-reel hose.	30m		
	Nozzle Diameter	5mm	Provided	MR
7	Automatic fire detection & alarming syste	***************************************	something to be	41 11
	- TC1	37/4	NT/A	NT/A
	<ul> <li>Type of detectors</li> <li>Location of Main Panel</li> </ul>	N/A N/A	N/A N/A	N/A N/A

	N	117	आज़ादी । अमृत	होत्सव
-	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Ilooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System		1.10.5	
	Basement	N/A	N/A	N/A
	Ground floor.	Required	Provided	M/R
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	Size of Riser/Down-comer	Required	100 mm	MR
	Number of Hydrant per floor     Hose box.	Required	One	MR
		Required	One	MR
12	Yard Hydrants.	merchald all years	PRIL M. HOSE	1 12
7	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.		Aller Lands or	
7	Ground Level		all and the	
	Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	> Standby Pump output.	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	<ul> <li>Auto Starting/Manual Stopping.</li> <li>Pump house access.</li> </ul>	N/A	N/A	N/A
	Fump house access.	N/A	N/A	N/A
	Terrace Level	10/11	to MANAGED A	1.071
	Discharge of pump.	450 & 225 LPM	Provided	MR
	Head of pump.	40 m	Provided	MR
	Power supply.	HEAT OF THE PERSON NAMED IN	Provided	MR
	> Auto starting of pump.	Required	21 17 7 11 11 11 11 11 11 11 11	0.
to off		Required	Provided	MR
14	Captive water storage for fire fighting.		مودا لارجي وموالي	
110	<ul> <li>Underground tank capacity.</li> </ul>	N/A	N/A	N/A
	> Draw-off connection.	N/A	N/A	N/A
	> Fire Service Inlet.	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	5,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		The second secon	
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
		N/A	N/A	N/A
	Lift signage.  Standby Power Supply	Required	Provided	MR
17	Standby Power Supply	Required	Tovided	IVIIC
18	Refuge Area		و خوا الند اللومان	74
	Total area	N/A	N/A	N/A
	• Location	NIA	N/A	N/A
		N/A	N/A	IN/A
19	Fire Control Room.	of the day of	B Continue	nJ r
	Detector system panel.	N/A	N/A	N/A

And .	Flow switch panel.	N 18	आज़ात अमृ	री <sub>का</sub> त महोत्सव
	PA system panel.	N/A		
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any.	N74.	N/A	N/A
	The fire protection system provided in a	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/SZ/2021/129 dated 13/07/2021, renewal under rule 37 of the Delhi Fire Service

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: Do (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HQ)

f.t. letta in