

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/260

Dated...l.4./08./2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s China Garden Takashi Terrace Bar and Café located at GF, FF & Second floor only, at M-73, M-Block Market, Greater Kailash-II, New Delhi 110048 in the building comprised of Basement, Ground plus Three Upper Floors owner/occupied by Unit of Four Seasons Cuisine India Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/SZ/2021/118 dated 24/06/2021. The restaurant premise was re-inspected by the officer concerned of this department on 03/08/2024 in the presence of Mr. Harish Kumar (Manager) of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant running at GF, FF & SF only) and Validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 14 / 08 /2024 at New Delhi by

(ATUL GARG) DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Joint Commissioner of Police, Lic/Branch, 1st Floor, PS Defence Colony, New Delhi 110049 (MHA Portal ID. 2024072611615 dated 26/07/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

5. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

1		INSPECTIO	N REPO	RT	आजादी	RT _	
		& Address of the Building	M/s China Garden Takashi Terrace Bar and C (A Unit of Four Seasons Cuisine India Pvt Ltd) 73, M-Block Market, Greater Kailash-II, N Delhi 110048			Pvt Ltd) M-	
2	Туре	of Occupancy	Group-D Assembly Building. (Ground & 1 st Floor Rest. 2 nd floor Kitchen Blocked one side & 3 rd floor Closed)				
3	Build	ing Comprised of		t, Ground	+ Three upper floors		
4	Type	of Case	Renewal				
5	Detai	ls of Previous NOC	F.6/DFS/MS/EH/SZ/2021/118 dated 24/06/2021				
6	Fire S	Safety Directives Letter No	Nil 22 4998 20 (b. of 20%2)				
7	Date	of Inspection	03/08/2024				
8	Name	e of the Inspecting Officers	DO (South) & ADO (BCP)				
9		e & Designation of Officers the building side	Mr. Harish Kumar (Manager)				
10		of construction	2006-07 Restt. at ground & 1 st floor only MHA Portal ID. 2024072611615 dated 26/07/2024			26/07/2024	
11	Appl	icant letter No.	MHA Por	rtal ID. 2	024072611615 dated		
S. No.	- 5	mum standards on Fire Prevention Fire Safety U/R 33	Old NOC Provided at Site requirement		Remarks MR/NMR		
1_	Acce	ess to Building.		- (- / - / - / - / - / - / - / - / - /	09 mtr Provided	MR	
		Road width	Requ		Directly accessible	N/A	
	1	Gate width	N/A		N/A	N/A	
		Width of internal road	N/.	A	1,1/1		
2		aber, width, type & arrangement of ex	its.	n Ariem I	part book 4		
200	a)	Number of Staircase		irad	Two nos	MR	
	-	Upper floors.	Requ		Two nos	N/A	
	> Basement floor.		Required Two nos 197A				
		Width of Staircase	Requ	ired	1.25 & 1.10 mtr	MR (old case	
		Upper floors	Requ		1.25 & 1.10 mtr	MR (old cas	
		Basement floor	Codeway .		the same of the sa		
	-	Protection of exits > Fire check door	N/	'A	N/A	N/A	
		> Pressurization	N/	'A	N/A	N/A	
	d)	No. of continuous staircase to terrace	Requ	uired	One	MR	
		Width of corridor	N.	/A	1.50 m	N/A	
		Door size	Requ	uired	1.50 m	MR (old ca	
3	-/	partmentation.		armed 30	CITATION CADA - R		
		Fire check door.	or skeep to the sale	/A	N/A	N/A	
		Sealing of electrical shafts.	100	/A	N/A	N/A	
		• Fire rating of shaft door.		/A	N/A	N/A	
		• Water curtain		/A	N/A	N/A	
	1	• Fire dampers.	N	/A	N/A	N/A	
4	Smo	ke Management system.		disedi	o west Earthy 10 11		
/NO		Basement	30 A	CPH	N/A	N/A	
		Upper floors	12 A		Provided	MR	
	Fire	Extinguishers.	2		GARAGO INC.		
		Total numbers	- 06	Neces Lies	20 Nos	MR	
5	Types		A DOUGO		ABC-16 & CO ₂		
5		The second secon		C/CO₂	04	- MR	
3		ISI Marking	ISI marked		Provided	MR	
21.7		ISI Marking	ISI n	narked			
6	Firs	t Aid Hose Reels.			digger up 1 win	and the state of	
A1.0	Firs	t Aid Hose Reels. Total numbers on each floor.	One	at each	Provided		
A1.0	Firs	t Aid Hose Reels.	One 3		digger up 1 win	MR MR MR	



A	attenutic fire detection & starming system.			1
+	Type of detectors		Smoke & Heat	MR
- 1		Required	Ground floor	N/A
- 1	Location of Main Panel	N/A	N/A	N/A
- 1	Location of Repeater Panel	N/A	Each floor	MR
- 1	Alternate source of power	Required	Provided	MR
	Hooter's location	Required	Provided	MR
10.	MOEFA	Required	N/A	N/A
9	Public Address System	N/A	NA.	-
10	Automatic Sprinkler System		Provided	MR
	Basement	Required	Provided	MR
- 1	Ground floor & above floor	Required	N/A	N/A
- 1	Sprinkler above false ceiling	N/A	TOTAL STREET	0
11	Internal Hydrants.		Provided	MR
	Size of Riser/Down-comer	100mm	Provided	MR
	Number of Hydrant per floor	01 No	Provided	MR
	Hose box.	01 No	Provided	
12	Yard Hydrants.		N/A	N/A
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	NA.	I NA
13	Pumping arrangements.			
	Ground Level		NUA	I N/A
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	
	Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	 Standby Pump output. Standby Pump head. 	N/A	N/A	N/A
	> Anto Starting/Manual Stopping.	N/A	N/A	N/A
	> Pump house access.	N/A	N/A	N/A
		N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.	900 LPM	Provided	MR
	> Head of pump.	40 m	Provided	MR
	> Power supply.	Required	Provided	MR
	Auto starting of pump.	NA	Provided	NA
14	Captive water storage for fire fighting.		11.12	1
	Underground tank capacity.	N/A	NA	N/A
	Draw-off connection.	N/A	N/A	N/A
	> Fire Service Inlet.	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
	 Overhead tank capacity. 	5,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	1		- Sux
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	Required	Provided	MR
	Fireman's switch.	Required	Provided	MR
	Lift signage.	Required		
17	Standby Power Supply	Required	3.55	
18	Refuge Area	nuque di	riovased	MR
-		7755		
	Total area	N/A	N/A	N/A
	Location	NA	N/A	N/A





.0	Fire Control Room.			
19	Detector system panel.	N/A	N/A	1 300
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A		N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the	NA	N/A	N/A
20	Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 303 dated 24/07/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/SZ/2021/118 dated 24/06/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)