GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/NDZ/2024/ Gn 347

Dated: 16/08/2024

FIRE SAFETY CERTIFICATE

Certified that the M/S Kuber International located at XV-4700-4701, Shora Kothi Main Bazar, Pahar Ganj, New Delhi comprises of stilt +Ground + 03 Upper floors, stilt -parking, Ground to 3rd floor (05 guest rooms at each floor) total 20 Guest rooms, was earlier granted FSC by this department vide letter No.F6/DFS/MS/EH/NDZ/2021/463 dated 04.10.2021. Now, the premise was inspected by the officers concerned of this department on 06/08/2024 in the presence of Manager and found that the said guest house building has complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 stilt- parking, Ground- to 3rd floor (5 guest rooms at each floor) Total - 20 guest rooms and valid up to the period of three year from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed

Issued ... 16. 08 2024 at New Delhi by.

Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, New Delhi: to ensure the occupancy in the building and
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2024071711143 dated 19/07/24.
- 3. The Manager, M/S Kuber International located at XV-4700-4701, Shora Kothi Pahar

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the

The trained fire fighting staff should be available round the clock.

- The compliance with regards to electrical installation, structural stability, set back area, occupancy and any
- This fire safety certificate may not be treated in any case fc. regularization of unauthorized construction, if any. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of 9. Stilt floor shall be used strictly for parking only.

10. Any flammable material for interior decoration is prohibited.

			etad at YV		
Name & address of the building	4700-4701, Ganj, New	4700-4701, Shora Kothi, Main bazar, Pahar Ganj, New Delhi, Stilt +Ground and Three			
Type of occupancy: -	Residential ground floo	Residential Group A-1, stilt -parking, ground floor to 3 rd floor 05 guest rooms at each floor, Total -20 room.			
Type of case: -	Renewal	Renewal			
Details of previous FSC: -		No.F6/DFS/MS/EH/NDZ/2021/463 dated			
Fire safety directives No					
			*		
	r: - Sh. Ravinde	Sh. Ravinder Singh (ADO/CC) Sh. Rajinder Atwal (DO /CD)			
Name & designation of office From the building side: -	<u>Manager</u>	Manager			
Year of construction: -	2021		and the state of		
Applicant's letter No: -	ID No. 2024	4071711143 dated	19/07/24.		
33	2016/ /NBC part-4		MR/NMR		
Charles Transmission A.	2 3 - 12	-17			
	N/A	1.5 mtr	N/A (PSS)		
Taran Harman Continue	N/A	N/A	N/A		
	N/A	N/A	N/A		
Number, Width Type & Arran	gement of Exits		IVA		
A. Number of staircases					
		02 Nos.	MR		
	The state of the s	N/A	N/A		
1900 C.	The state of the s	N/A	N/A		
		1.50 mtr.	MR		
The state of the s	N/A	N/A	N/A		
1. Fire check door	NI/A				
2. Pressurization			N/A		
D. No. of continuous			N/A		
staircase to terrace		Provided	MR		
	1.50m	1.50m			
Compartmentation	01 mtr.		MR		
			MR		
2) Sealing of electrical shafts	N/A	N/A	7 (5)		
	1 3 7 7 7	1 - 44 - 4	NIA		
3) Fire rating of shaft door PSS- Pedestrian Shippi	N/A ·	N/A	N/A N/A		
	Type of occupancy: - Type of case: - Details of previous FSC: - Fire safety directives No Date of inspection: - Name of the inspecting officer Name & designation of officer From the building side: - Year of construction: - Applicant's letter No: - Minimum Standards on fire Prevention and fire safety U/R 33 Access to Building 1) Road width 2) Gate width 3) Width of internal road Number, Width Type & Arran A. Number of staircases 1. Upper floors 2. Basements B. Width of staircase 1. Upper floors 2. Basements C. Protection of exits 1. Fire check door 2. Pressurization D. No. of continuous staircase to terrace E. Width of corridor F. Door size(room) Compartmentation 1) Fire check door	Name & address of the building M/S Kuber 4700-4701, Ganj, New upper floor Type of occupancy: - Residential ground floor each floor, Type of case: - Renewal Details of previous FSC: - No.F6/DFS 04.10.2021 Fire safety directives No N/A Date of inspection: - 06.08.2024 Name of the inspecting officer: - Sh. Ravindon Sh. Rajinder Name & designation of officer From the building side: - 2021 Applicant's letter No: - ID No. 2024 Minimum Standards on fire Prevention and fire safety U/R 33 Minimum Standards on fire Prevention and fire safety U/R 33 Minimum Standards on fire Prevention and fire safety U/R 33 Minimum Standards on fire Prevention and fire safety U/R 33 Minimum Standards on fire Prevention and fire safety U/R 34 Access to Building 1) Road width N/A N/A Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 02 Nos. 2. Basements N/A B. Width of staircase N/A 1. Upper floors 1.50mtr 2. Pressurization N/A D. No. of continuous staircase to terrace 1.50mtr P. Door size (room) 01 mtr. Compartmentation 1) Fire check door 1.50m Compartmentation 1) Fire check door 1.50m	A700-4701, Shora Kothi, Manan, New Delhi, Stilt +Groupper floor. Type of occupancy: - Residential Group A-1, stilt ground floor to 3rd floor 05 geach floor, Total -20 room. Type of case: - Renewal		

- 5

		\% N/A	N/A	N/A	1200
	4) Water curtain	N/A	N/A	N/A	THE RESERVE AND PARTY.
	5) Fire Danipers	N/A			
4.	Smoke Management System	N/A	N/A	N/A	
	1) Basements	12 ACPH	Mechanical	MR	
	2) Upper floors		(Exhaust fan)	+	78
5.	Fire Extinguishers	10 Nos.	10 Nos.	MR	
	1) Total numbers	ABC & CO2	ABC & CO2	MR	1 46
	2) Types	Required	Provided	MR	
	3) ISI marking	Regulied	110,100		
6.	First-Aid Hose Reel	01	01	MR	
	1) Total number at each floor	30 mtr.	30 mtr.	ME	1
	2) Length of hose reel hose	05 mm	05 mm	MF	3
	3) Nozzle diameter	fortists and the same	VV		
7.	Automatic Fire Detection & Ala	Paguired	Provided	MI	3
	1) Type of detectors CO type	Required Stilt floor	Provided	MI	
	2) Location of main panel		N/A	N/	
	3) Location of repeater panel	N/A Required	Provided	M	
	4) Alternate source of power	Required At each floor	Provided	M	7111
	5) Hooter's Location	Participate and the	Provided	/ N/	
8.	MOEFA	N/A		N/	
9.	Public Address System	N/A	N/A	114/	
10.	Automatic Sprinkler System	2011	N/A	N	/A
	1) Basement	N/A	Provided		/A
	2) Upper floors	N/A	The second of th		/A
17	3) Sprinkler above false ceiling	N/A	N/A	- 1.	
11.	Internal Hydrants		N/A	N	I/A
1-1	1) Size of riser/down-comer	N/A	1975 FOR 1840 B		N/A
	2) Number of hydrants per floor	N/A	N/A		N/A
	3) Hose box	N/A	N/A	- 11	W.A.
12.	Yard Hydrants	Take .	LATIA	-	N/A
	1) Total number of hydrants	N/A	N/A		N/A
	2) Hose box	N/A	N/A	-4	NA
13.	Pumping Arrangement				> */A
	1) Ground level	N/A	N/A		N/A
	a) Discharge of main	N/A	N/A		N/A
	b) Head of main pump	N/A	N/A		N/A
	c) Number of main pump	N/A	N/A		N/A
	d) Jockey pump out put	N/A	N/A		N/A
		N/A	N/A	2.3	N/A
		N/A	N/A		N/A
	f) Stand by pump output	N/A	N/A		N/A
	g) Stand by pump head				N/A
	h) Auto starting/Manual	N/A	N/A		IN/A
	stopping			/	
	2) Terrace level				100
	 a) Discharge of pump 	450 LPM	450LPM	/	MR
	b) Head of pump	30 mtr.	30 mtr.	(MR
	c) Power supply	Required	Provided		MR
	d) Auto starting of pump		Provided		MR

L	Under ground tank capacity	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	Required	Provided	MR	
	d) Over head tank capacity	5,000 ltr	5,000 ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
10.		N/A	N/A	N/A	
14	b) Pressurization of lift	N/A	N/A	N/A	
	lobby c) Communication in lift car	Required	Provided	MR	
300		Required	Provided	MR	
10	d) Fireman's switch	Required	Provided	MR	
_	e) Lift signage	Required	Provided	MR	
17.	Stand by Power Supply		N/A	N/A	
18.	Refuge Area	N/A		N/A	
Fi -	Total area location	N/A	N/A	N/A	
105			N/A	N/A	
19.	Fire Control Room	N/A	1,210	N/A	
	a) Detector system panel	N/A	N/A		
	* / /	27/4	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	Y 12 12 12 12 12 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15	N/A	
	d) Battery backup	N/A	N/A	Harasan Hara	
		37/4	N/A	N/A	
	e) Building floor plan	N/A		N/A	
20.	Special Fire Protection System for Protection of special Risk, if any: ABC & CO ² The fire protection systems provided in the building we				

The fire protection systems provided in the building were randomly tested,

checked and found functional at the time of inspection. In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter no. No.F6/DFS/MS/EH/NDZ/2021/463 dated 04.10.2021, under rule 35(6) of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the inspecting officer

Signature of the Inspecting Officer

Name: - Rajinder Atwal

Designation: - DO (CD)

Name : Raving

Designation: ADO (CC)