

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/2024/257

Dated: 08/08/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Samrat Restaurant located at Shop no. 74A, Ground Floor, Outram Lane, Kingsway Camp, Delhi-110009, in the building comprised of ground & first floor only owned/ occupied by Smt. Neelam Samrat was issued fire safety certificate vide letter no. F6/DFS/MS/2021/EH/217 dated 08.09.2021. The premises was inspected by the officer concerned of Fire Service on 01.08.2024 in the presence of Smt. Veena Hora and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rules 33 of the Delhi Fire Service Rules, 2010 and building premises is fit for occupancy class "Group D Assembly (Restaurant)" for ground floor only with effect from for a period of up to 31.03.2024 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 8 | 08 | 20 29 at New Delhi by

Pb-011-23414000

Copy to:-

1. M/s Samrat Restaurant located at Shop no. 74A, Ground Floor, Outram Lane, Kingsway

Conditions for the validity of Fire Safety Certificate:

1. This Fire Safety Certificate is valid for restaurant on ground floor for assembly occupancy only. In case of any violation, this FSC will be treated as null & void. 2. All the means of escape/entry/exit shall be kept free from any obstruction.

3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system. 5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months

INSPECTION REPORT 1. Name & address of the building

: M/s Samrat Restaurant at Shop no. 74A, GF, Outram Lane, Kingsway Camp,

Delhi- 110009,

2. Type of Occupancy

: Assembly/ Restaurant

3. Type of Case

: Renewal

4. Composition of building

: Ground & first floor but restaurant running at ground floor only, first

Floor - tin shed vacant

5. Details of previous NOC

: F6/DFS/MS/2021/EH/217 dated 08.09.2021

6. Fire Safety directives letter No

: Circular No. F.6/DFS/EH/MS/2005/718 dated 04.11.2005

7. Date of inspection

: 01.08.2024

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Smt. Neelam Samrat (Owner)

10. Year of Construction/conversion : 1966 (Old Building)

11. Applicant's letter No

	Minimum Standards on fire prevention and fire safety U/R 33	Circular Dated 04.11.2005 Requirements	Provided at site	Remarks MR/NMR		
	Access to building					
	Road width	06m	06m	MR		
	Gate width	NA	NA NA	NA		
	Width of internal road	NA	NA NA	NA		
	Number, Width, Type & Arrangement of Exits (Restaurant at Ground Floor only)					
	a. Number of staircases					
	Upper Floors	NA	NA	NA		
	Basements	NA	NA NA	NA		
	b. Width of staircases		LI VIII			
	Upper Floors	NA	NA	NA		
	Basements	NA	NA NA	NA		
	c. Protection of exits					
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
	d. No. of continuous staircases to terrace	NA	NA	NA		
	e. Width of Corridor	NA	NA	NA		
	f. Door Size	1.50m each	2.0m each & 1.50m each	MR		
0	Compartmentation.					
	Fire check door	NA	NA -	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
4	Smoke Management System.					
	Basements	NA	NA	NA		
	Upper floors	Required	Natural Ventilation	MR		
5	Fire Extinguishers					
	Total numbers	05nos	06nos			
	• Types	ABC/Co2	ABC-4 /Co2-02	MR		
	ISI marking	Yes	Yes	MR		
_		do 1/2		MR		

	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	 Length of hose reel hose 	30m	Provided	MR		
	Nozzle diameter	5mm	Provided	MR		
		220-200-200				
	Automatic fire detection and alarming system.					
	Type of detectors	NA	Provided	NA NA		
	Location of Main Panel	NA	NA NA	NA NA		
	 Location of Repeater Panel Alternate source of power 	NA NA NA	NA NA NA	NA NA		
•	Hooters' Location	Required	Provided	MR		
8 9	MOEFA Public Address System.	NA NA	NA	NA		
10	Automatic Sprinkler System.					
	-	NA	NA	NA		
	Basement	NA	Provided	NA		
	Upper Floor (Ground floor)	NA NA	NA	NA		
	Sprinkler above false ceiling .	14/3				
11	Internal Hydrants	NA NA	Provided	NA		
	Size of riser/down-comer	NA NA	Provided	NA		
	Number of hydrants per floor Hose Box	NA NA	Provided	NA		
12	Yard Hydrants.					
12	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
13	Pumping Arrangements. • Ground Level					
	Ground Level Discharge of main Pump	N/A	N/A	N/A		
	> Head of Main pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A	N/A	N/A		
ш,	> Jockey rump head	N/A N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		
	> Standby Pump Head	N/A	N/A	N/A		
	> Auto Starting/ Manual stopping	N/A	N/A	N/A		
		N/A		N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level Displaces of nume	2001701	T			
1	➢ Discharge of pump	225 LPM	450 LPM	MR		
	➤ Head of the pump	40m	Provided	MR		
	➤ Power Supply	Required	Provided	MR		
	➤ Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	. NA	NA	NIA		
	▶ Draw-off connection	NA	NA NA	NA		
	➤ Fire service inlet	NA	NA NA	NA NA		
	> Access to tank	NA -	NA NA	NA NA		
	Overhead Tank capacity	5,000 LTR	Provided	3330047		
	Exit Signage.	Š.		MR		
15 16	Provision of Lifts.	Required	Provided			

7				N/A	
1	Pressurization of Lift Shaft	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car Fireman's Grounding Switch	NA	NA -	NA	
1		NA	NA	NA	
		NA	NA	NA	
	Lift Signage	N/A	N/A	N/A	
	Standby power supply				
	Refuge Area > Total Area > Location	N/A	N/A	N/A	
		N/A	N/A	N/A	
,	Pin Control Poom				
•		N/A	N/A	N/A	
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel		N/A	N/A	
	Batter backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	DEMINES IN	NA	
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA		

The fire protection systems provided in the building were tested/ checked and found in

Keeping in view of the substantial compliance of the minimum standards on fire prevention working condition at the time of inspection. and fire safety required under the rules. It is recommended to renew Fire Safety vide this department letter of even no. F6/DFS/MS/2021/EH/217 dated 08.09.2021 Certificate under rule 37(3) of Delhi Fire Service Rules 2010.

Signature of the Inspecting Name :- C.L. Meena Designation:- ADO/RN