## VERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



No F 6 / DFS / MS / 2024 /EH/WZ/ 274

## Dated: 27/08/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s The Mohans (A Unit of Mittal Hotels Pvt. Ltd.) located at (First Floor), Plot No. 3 & 4, Central Market, Ashok Vihar, Phase-II, Delhi-110052 in a building comprised of Basement, Ground plus Two upper floors was issued FSC by this department vide letter No F6/DFS/MS/EH/WZ/2021/285 dated 11.10.2021. The premise was re-inspected by the officer concerned of this department on 14.08.2024 in the presence of Sh. R.K. Jha (Manager) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "Assembly (Restaurant)" Group D (for First floor only) with effect from ... 27. 08. 2024 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 27.108.1.2024... at New Delhi, by

Delki Fire Service

Copy to: -

- 1. M/s The Mohans (A Unit of Mittal Hotels Pvt. Ltd.) located at (First Floor), Plot No. 3 & 4, Central Market, Ashok Vihar, Phase-II, Delhi-110052.
- MHA Portal, ID No. 2024070210246.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA portal (https://www.delehlhlic.gov.in) along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in
- Basement shall be used as per building bye laws.

## INSPECTION REPORT 1. Name & address of the building: M/s Mohans (A Unit of Mittal Hotels Pvt. Ltd.) located at Plot No. 3& 4, First Floor, Central Market, Ashok Vihar, Delhi-110052. Assembly (Restaurant) at First Floor.

Basement, Ground floor plus two upper floors. Type of Occupancy **Building Comprised of** 3. Renewal

F6/DFS/MS/EH/WZ/2021/285 Dated 11/10/2021 Type of Case 4. 5. Details of Previous NOC NBC/ UBBL

6. Fire Safety directives letter No 14/08/2024 7. Date of inspection R.K.Sinha, ADO (BW)

8. Name of Inspecting Officer 9. Name and designation of officers

Sh. R.K. Jha From the building side

1985 as per MHA Portal

MHA Application ID No. 2024070210246 dated 23/07/2024 10. Year of Construction

S. No.	1. Applicant's letter No. :  Minimum Standards on fire prevention and fire safety U/R 33	As per Requirement letter dated 11/10/2021/ Clause No. 35(6) of DFS Rules 2010		MR/NMR					
1.	Access to building	6 m	Provided	MR					
	Road width	4.5 m	Directly Accessible	MR NA					
	Gate width	NA NA	NA	NA					
	Width of internal road	White the second		W. Carlotte					
2.	Number, Width, Type & Arrangement of Exits								
	Number of staircases	02	02	MR					
	Upper Floors	NA	Provided	NA					
	Basements	INA	IVA						
	Width of staircases	Oll Con	1.30 m & 1.15 m	MR(old case)					
	Upper Floor	Old Case	NA	NA					
	Basements	NA	NA	NA					
	Protection of exits	NA NA	NR	NR					
	Fire check door	NR	NA NA	NA					
	Pressurization	NA	IVA						
	No. of continuous staircases to	01	Provided	MR					
	terrace	NA	NA	NA NA					
	Width of Corridor	2 m & 1 m	Hall-1 = $2 \times 1.5$ m, $2 \times 1.1$	m MR(old case)					
	Door Size		Hall -2 = 2 × 1.8 m Small Room- 0.90 m						
_	Compartmentation NA NA								
3.	100 Park 187	NA	NA						
	Fire check door	NA	NA	NA					
	Sealing of electrical shafts	NA NA	NA	NA					
	Fire Rating of shaft door	NA NA	NA	NA					
	Water Curtain		NA	NA					
	Fire Dampers								
4.	Smoke Management System								
565	Basements	NA		MR					
	3.000 MANAGE - 1.00 C M	Required	Provided	IVIX					
	Upper floors								
5.	Fire Extinguishers	08 Nos.	- 10 Nos.	MR					
	Total numbers		D. Had	MR					
	Types	ABC/Co2 Typ	Provided	MR					
	IS marking	Required	11041000						
6.	Tint Aid Hose Reels		Provided	MR					
	Total numbers on each floor	01	Provided	MR					
	Length of hose reel hose	30 m		MR					
	Margle diameter	5 mm	Provided	IVIK					
7.	detection and alarming system								
		NA	Provided						
	Type of detectors	NA	GF	NA					
	Location of Main Panel		NA	NA					
	Location of Repeater Panel	NA NA	Provided	NA					
	Alternate source of power	NA NA	Near Exit	NA					
	Hooters' Location	NA	IVOII DAIL	The state of the s					

• 1	,	3	v
N		,	

	MANN	Required	Provided	MR				
	MOEFA	NA	NA	NA •				
0.	Public Address System NA NA Automatic Sprinkler System							
	Personal	NA	NA	NA				
	Basement Linear Floor	Required	Provided	MR				
	Upper Floor	Required	Provided	MR				
1.	Sprinkler above false ceiling	Required						
1.	Internal Hydrants							
	Size of riser/down-comer	100 mm	Provided	MR				
	Number of hydrants per floor	02	Provided	MR				
12.	Hose Box Yard Hydrants	02	Provided	MR				
	Total number of hydrants	NA NA	NA NA	NA NA				
••	Hose Box	NA	NA	NA				
13.	Pumping Arrangements							
	Ground Level	P						
	Discharge of main Pump	NA	NA	NA				
	Head of Main pump	NA	NA	NA				
	Number of main pumps	NA	NA	NA				
	Jockey Pump out put	NA	180 lpm on terrace	NA				
	Jockey pump head	NA	60 m	NA				
	Standby Pump out put	NA	NA	NA				
	Standby Pump Head	NA	NA	NA				
	Auto Starting/Manual Stopping	NA	NA	NA				
	Pump House Access	NA	NA	NA				
	Terrace level							
		0001		1				
	Discharge of pump	900 lpm	Provided	MR				
	Head of the pump	40 m	Provided	MR				
	Power Supply	Required	Provided	MR .				
2	Auto Starting of pump	Required	Provided	MR				
14.								
	Underground tank capacity	NA NA	NA	NA				
	Draw-off connection	NA	NA	NA				
	Fire service inlet	ÑΑ	NA	NA				
	Access to tank	NA	NA	NA				
	Overhead Tank capacity	10,000 ltrs	Provided	MR				
15.	Exit Signage.	Required	Provided	MR				
16.	Provision of Lifts.							
	Pressurization of Lift Shaft	NA	NA I	NA				
	Pressurization of Lift lobby	NA NA	= 3,8691,527	VI CONTRACTOR				
	Communication In lift Car	NA NA	NA NA	NA NA				
	Fireman's Grounding Switch	NA NA		NA				
	Lift Signage	10-70-12	NA	NA				
17.	Standby power supply	NA	NA	NA				
		Required	Provided	MR				
18.	Refuge Area.							
	Total Area	NIA	37.					
	Location	NA NA	NA NA	NA				
	Fire Control Room	I IVA	NA	NA				
19.								
19.	Detector System Panel	374						
19.	Detector System Panel Flow Switch Panel	NA NA	NA NA	NA				

Note: Basement floor is not owned / occupier by the M/s. The Mohan Restaurant & have separate entry/exit, hence fire safety arrangement in basement floor is not checked.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter number F6/DFS/MS/EH/2024/WZ/247 dated 18/06/2024.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DFS/MS/EH/WZ/2021/285 dated 11/10/2021 for first floor only under Rule 37 of the Delhi Fire Service Rules, 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

RAJIV KUMAR SINHA

ADO Rawara

Pycfo (pr)

-

CFO May 200

Dinecter

0 Handes

FO. 850