

### GOVERNMENT OF NATIONAL C HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/SZ/2024/

### FIRE SAFETY CERTIFICATE

Certified that the M/s Modern Perfect Public School located at L-35, Khasra No. 44/19, Gali No. 3-4, Shani Bazar Road, Sangam Vihar, New Delhi-80, comprised of Basement (Library + Science lab) + Ground floor only was granted Fire Safety Certificate by this department vide letter no.- F6/DFS/MS/School/2021/SZ/273 dated 31.03.2021. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 14.08.2024 in the presence of Mr. Surendra Kumar (Owner) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. 3298 to 3398 dated 01.03.2011 issued by the Directorate of Education and the building/premises [Basement (Library + Science lab) + Ground floor only] is fit for occupancy of Group B "Educational Building" with effect from 37.08 2024. renewed for a period of three years, subject to conditions printed below,

Issued on. 27.08 2024...at New Delhi by

Delhi Fire Service

### Copy to:-

- 1. The Dy. Director of Education, GNCT of New Delhi DISTT. South Sector-3, R.K. Puram, New Delhi-22.
- 2. The Principal, M/s Modern Perfect Public School located at L-35, Khasra No. 44/19, Gali No. 3-4, Shani Bazar Road, Sangam Vihar, New Delhi-80.

# Conditions for the validity of Fire Safety Certificate

- 1. Basement shall be used as per NBC/UBBL-2016 & circular no. DE.23(399)/Sch.Br./2024/572 dated 31.07.2024 issued by the Directorate of Education.
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 8. The owner occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

N/16

1	Nar	ne and address of the building:	ECTION REPORT		. 1 . 7 2/
		address of the building:	M/s Modern Perfe	ect Public School lo	cated at L-3:
			Khasra No. 44/19,	Gali No. 3-4, Shani	Bazar Koad
2	Bui	Iding is some	Sangam Vihar, Ne	w Delhi-80.	
3	Tyr	lding is comprised of	Basement (Library	+ Science lab) + Gro	und floor onl
4	T	oe of occupancy	Group B - Educatio	nal Building (School)	
20	Typ	oe of case:	Renewal		
5	Det	ails of previous FSC:	F6/DFS/MS/School	/2021/SZ/273 dated	31.03.2021
6	Fire	safety directives no.:	F6/Estate/CC/Fire S	Safety/2011/3298 to 3	398 dated
			01.03.2011		
7	Dat	e of inspection:	14.08.2021		w L
8	Nar	ne of the inspecting officer:	ADO Rajesh Kuma	r Shukla (M. Road)	
9	Nar	ne and designation of the officer	Mr. Surendra Kuma	r (Owner)	
	froi	n the building side:			
10	Yea	ar of construction:	2014		
11		erence letter no.:	Email dated 29.07.2	024	
S,No	Minimum Standards on fire		Requirements as Provide at site		Remarks
٠,, ١٠	300000000000000000000000000000000000000	evention and fire safety	per DOE circular		MR/NMR
		uirements U/R 33	dated 01.03.2011		
1		cess to Building	- reg - re		Lim
	A	Road width	Accessible	Accessible	MR
	-	Gate width	NA	NA	NA
	B	Width of internal roads	NA -	NA	NA
	C				
2	Nu	mber, Width, Type & Arrangem	ent of Exits		
	A	No. of staircase:	NA NA	NA	NA
		a) Upper floor		2 nos.	MR
		b) Basements	2 nos.	100 Telephone (100 Te	
	В	Width of the staircase:	NA	NA	NA
		a) Upper floor	NA 1 staircase of 1.5	1.14 m & 0.85 m	MR
		b) Basements	mtrs or if main		l s
		AP I	staircase width is <		
		206	1.5 mtrs an	MI, L.	
		AM	additional staircase		
			of 0.75 mtrrs width is	manus miles	
		1000	required.		
	C	Protection of exits	July Lawsen	L STA	NA
	-	a) Fire check door	NA	NA	NA
		b) Pressurization	NA	NA	MR
	D	No. of continuous staircase to	1 no.	2 nos.	
	v	terrace:	and the same	Provided	MR
	F	Width of the corridor	1.50 m	1.0 m (for class	MR
	E	Door size	1.0 m (for class	room)	
K	E		room)	room)	
3	Co	mpartmentation:		NA	NA
3	A	Fire check doors	NA	NA NA	NA
	B	Sealing of electrical shafts	NA	NA NA	NA
	C	Fire rating of shaft doors	NA	NA NA	NA
	D	Water curtain	NA	NA NA	NA
	E	Fire dampers	NA	INA	. 4.0.5
	2	oke Management System:	77	III. II	NA
4	-	Upper floors	NA	NA	
	A	Basements	Required	Provided	MR
	В			thous winds	
5	Fir	e Extinguishers	05 nos.	12 nos.	MR
	A	Total numbers	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR
	В	Types	Required	Provided	MR
	C	ISI marking	Required		NCS -

## N/17

6	1	First Aid Hose reel					
	A		NA	2 nos.	NA		
	B	Length of hose reel	NA	30 m	NA		
	C		NA	5 mm	NA		
7	Automatic Fire Detection and Alarm System (ADAS)						
	A		NA	NA	NA		
	B	Location of main panel	NA	NA	NA		
	C	Location of repeater panel	NA	NA	NA		
	D	Alternate power source	NA	NA	NA		
	E	Hooter's location	NA	NA	NA		
8	M	IOEFA	NA	NA	NA		
9	P	ublic Address System	NA	NA	NA		
10	1000 TOO I WINDOW SHEET THE CONTROL OF						
22540	A	Basement (Area more than 200 m²)	Required	Provided	MR		
	В	Upper floor	NA	NA	NA		
	C	Sprinklers above false ceiling	NA	NA	NA		
11	In	ternal Hydrants		911			
	A	Size of the riser/down comer	NA	NA	NA		
	В	No. of hydrants per floor	NA .	NA	NA		
	C	Hose box	NA	NA	NA		
12	Y	ard Hydrants					
	A	Total no. of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	NA		
13	Pumping Arrangements						
	A	Ground Level					
		a) Discharge of main pump	NA	NA	NA		
	_	b) Head of main pump	NA	NA	NA		
		c) Number of main pump	NA	NA	NA		
		d) Discharge of jockey pump	NA	NA	NA		
		e) Head of jockey pump	NA	NA	NA		
		f) Discharge of standby pump	NA	NA	NA		
		g) Head of standby pump	NA	NA	NA		
		h) Auto starting/ manual stopping	NA	NA	NA		
	B Terrace Level						
		a) Discharge of terrace pump	450 LPM	Provided	MR		
		b) Head of terrace pump	40 m	Provided	MR		
		c) Alternate power supply	Required	Provided	MR		
		d) Auto starting of pump	Required	Provided	MR		
14	Ca	ptive Water Storage for Fire Fighting	- AND TO THE STATE OF THE STATE	an weighter all the			
549)	A	Underground tank capacity	NA	NA	NA		
	В	Draw off connection	NA	NA	NA		
	C	Fire service inlet	NA	NA	NA		
	E	Access to tank	NA	NA	NA		
	D	Overhead tank capacity	5,000 ltrs	Provided	MR		
15	2000	it Signage	Required	Provided	MR		
16	Provision of lift						
-5	A	Pressurization of lift shaft	NA	NA	NA		
1	В	Pressurization of lift lobby	NA	NA NA	NA		
	C	Communication in lift car	NA	NA NA	NA NA		
1	D	Fireman switch	NA				
	-	Lift signage	The Mark	NA	NA		
1	E	Lift Signage	NA	NA	NA		

M/s Modern Perfect Public School located at L-35, Khasra No. 44/19, Gali No. 3-4, Shani Bazar Road, Sangam Vihar, New Delhi-80.



M/s Modern Perfect Public School located at L-35, Khasra No. 44/19, Gali No. 3-4, Shani Bazar Road, Sangam

18	Refuge Area				
	A	location	NA	NA	NA
	B	Total area	NA NA	NA NA	NA NA
19	Fire Control Room				
	A	Fire detection system panel	NA	NA	NA
	B	Flow switch panel	NA NA	NA NA	NA
	C	P A system panel	NA	NA	NA
	D	Battery backup	NA	NA	NA
V)	E	Building floor plan	NA	NA	NA
20	20 Special Fire Protection for special risk if any				NA

### LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided But Not Functional (PNF).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education circular no. vide issued FSC dated 01.03.2011, the 3398 F6/DFS/MS/School/2021/SZ/273 dated 31.03.2021 is recommended to be renewed.

Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (M. Road)

and My 8 on Pls 8 pks
Odso of Boy M. rad.