

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6/DFS/MS/School/NDZ/2024/8,70

Dated: 27 / 08/2024

FIRE SAFETY CERTIFICATE

Certified that Prakash Deep Saraswati Vidya Mandir located at D - 20, Panchal Vihar, Shiv Vihar, Delhi - 110094, comprised of ground plus one upper floor, owned / occupied by Prakash Deep Saraswati Vidya Mandir, was issued Fire Safety Certificate vide letter No F6/DFS/MS/School/2019/NDZ/1672 dated 22/08/2019. The school buildings have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by the Director of Education and re-inspected by the officer concerned of this department on 12/08/2024 in presence of Mr. Vinod Kumar Sharma (Manager) of the school and the school building is fit for occupancy class "Educational Building" (Group - B) with effect from 27/08/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 subject to conditions printed bellow Issued on 27/08/2024 at New Delhi by.

DIRECTOR DELHI FIRE SERVICE

Copy to: -

- 1. The Dy. Director of Education, B Block, YamunaVihar, Delhi 110053.
- 2. The Principal, Prakash Deep Saraswati Vidya Mandir located at D-20, Panchal Vihar, Shiv Vihar, Delhi 110094.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

NIOP

				< 178 E.S. 178	TION REPOR	<u>e</u> T			
				address of the building	Prakash Deep Saraswati Vidya Mandir located at D - 20, Panchal Vihar, Shiv Vihar, Delhi -110094				
1		Building is comprised of			-	one upper floor only			
3		Type of occupancy			Educational Building				
1		Тур	e of	case	Renewal				
5		Details of previous FSC F6/DFS/MS/School/2019/NDZ/1672 dated 22/08/2019.			2 dated				
6		- 6		ety directives letter no.	 F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011. 12/08/2024 				
7		Date	e of	inspection					
8		Nan	ne (of the inspecting officers	Yashwant Singh Meena ADO (L.N)				
9	•		Name of the designation of officer Mr.Vinod Kumar Sharma (Manager) from the building side)			
10									
11		App	olic	ant's letter no.	Outdoor Diar	y No. 4842 dated 02/0			
S.	No	pre		nimum standard of fire ntion and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR		
1		Access to Building:			o residence in in				
	1	A	Re	oad width	6.0 mtrs.	6.0 mtrs.	MR		
		B Gate width		ate width	N/A	N/A	N/A		
		C	W	idth of internal road	N/A	N/A	N/A		
2	1	Nu	mb	er, Width, Type and Arran	gement of Exits	:			
		A		umber of staircases					
			а	Upper floor	01 no.	02 nos.	MR		
			b	Basement	N/A	N/A	N/A		
	1	В	W	lidth of staircases	*	į.			
			a	TT	1.50	0.77 mtr. 0.65 mtr.			
				Upper floor	1.50 meters.	0.77 ma. 0.05 ma.	MR		
			b	Basement Depth 1007	N/A	N/A	MR N/A		
		C	P	Basement rotection of exits	N/A	N/A	N/A		
		C	P	Basement rotection of exits Fire check door	N/A N/A	N/A N/A	N/A N/A		
		C D	P a b	Basement rotection of exits	N/A	N/A	N/A		
			Pa a b N	Basement rotection of exits Fire check door Pressurization o. of continuous staircases	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A		
		D	Pa b N to	Basement rotection of exits Fire check door Pressurization o. of continuous staircases terrace	N/A N/A N/A 01 no.	N/A N/A N/A 01 no.	N/A N/A N/A MR		
[3	3	D E F	Pa b N to W	Basement rotection of exits Fire check door Pressurization o. of continuous staircases terrace Vidth of corridor	N/A N/A N/A 01 no. 1.50 mtrs.	N/A N/A N/A 01 no. 1.50 mtrs.	N/A N/A N/A MR MR		
3	3	D E F	Pra a b Note to W	Basement rotection of exits Fire check door Pressurization fo. of continuous staircases terrace Vidth of corridor Poor size	N/A N/A N/A 01 no. 1.50 mtrs.	N/A N/A N/A 01 no. 1.50 mtrs.	N/A N/A N/A MR MR		
73	3	D E F	P: a b N to W D D mp	Basement rotection of exits Fire check door Pressurization o. of continuous staircases of terrace Vidth of corridor Poor size Partmentation:	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr.	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr.	N/A N/A N/A MR MR		
3	3	D E F Co	Pa b N to W D D mp	Basement rotection of exits Fire check door Pressurization To. of continuous staircases of terrace Tidth of corridor Toor size The check door The check door	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr.	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr.	N/A N/A N/A N/A MR MR MR		
3	3	D E F Co	b N to W D mp	Basement rotection of exits Fire check door Pressurization o. of continuous staircases o terrace Vidth of corridor oor size cartmentation: ire check door ealing of electrical shafts ire rating of shaft door Vater curtain	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr.	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A	N/A N/A N/A MR MR MR NA N/A		
3	3	D E F C A B C	b N to W D mp	Basement rotection of exits Fire check door Pressurization To. of continuous staircases of terrace Tidth of corridor Toor size The check door Time check door	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A N/A	N/A N/A N/A MR MR MR NA N/A N/A		
	3	D E F C A B C D E	Paab N to W D D mp	Basement rotection of exits Fire check door Pressurization o. of continuous staircases o terrace Vidth of corridor oor size cartmentation: ire check door ealing of electrical shafts ire rating of shaft door Vater curtain	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A N/A N/A	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A N/A N/A N/A	N/A N/A N/A MR MR MR NA N/A N/A N/A		
		D E F C A B C D E	Paab Note Note Note Note Note Note Note Note	Basement rotection of exits Fire check door Pressurization To. of continuous staircases of terrace Tidth of corridor Toor size The check door	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A N/A N/A	N/A N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A N/A N/A N/A	N/A N/A N/A MR MR MR NA N/A N/A N/A		

W

NOT

Prakash Deep Saraswati Vidya Mandir located at D-20, Panchal Vihar, Shiv Vihar, Delhi-110094

5.		Extinguisher:		r - 17.			
	A	Total numbers	04 nos.	06 nos.	MR		
-	B	Types	ÇO₂& ABC	CO₂& ABC	MR		
	Ç	ISI marking	ISI Marked	Provided	MR		
6	First-Aid-Hose Reel:						
	A	Total numbers of each floor	N/A	N/A	N/A		
	В	Length of hose reel hose	N/A	N/A	N/A		
	C	Nozzle diameter	N/A	N/A	N/A		
7	Automatic Fire Detection and Alarming System:						
	A	Type of detectors	N/A	N/A	N/A		
-	В	Location of main panel	N/A	N/A	N/A		
	C	Location of repeater panel	N/A	N/A	N/A		
	D	Alternate source of power	N/A	N/A	N/A		
	E	Hooters	N/A	N/A	N/A		
8	MC	DEFA:	N/A	N/A	N/A		
9	Pul	blic Address System:	N/A	N/A	N/A		
10		tomatic Sprinkler System:		IVA	IV/A		
	A	Basement	N/A	N/A	N/A		
	В	Upper floor	N/A	N/A			
	C	Sprinkler above false ceiling	N/A		N/A		
11		ernal Hydrants:	IVA	N/A	N/A		
	A Size of riser/down-comer		N/A	27/4	141		
	B	Number of hydrants per floor	N/A N/A	N/A	N/A		
	C	Hose box		N/A	N/A		
12	IVA N/A						
14	A	Total number of hydrants	NI/A				
	B	Hose box	N/A	N/A	N/A		
13			N/A	N/A	N/A		
1	Pumping Arrangements: Ground level						
Ţ	A		27/4		200200		
	B	Discharge of main pump Head of main pump	N/A	N/A	N/A		
	C		N/A	N/A	N/A		
	D	Number of main pumps	N/A	N/A	N/A		
	E	Jockey pump out put	N/A	N/A	N/A		
	F	Jockey pump head Standby pump out put	N/A N/A	N/A	N/A		
-	G		V42 / 2072 / 224	N/A	N/A		
	H	Standby pump head Auto starting /manual	N/A N/A	N/A	N/A		
	11	stopping	IN/A	N/A	N/A		
	I Pump house access		N/A	N/A	N/A		
2	Terrace Level						
	A	Discharge of pump	N/A	N/A	N/A		
	В	Head of the pump	N/A	N/A	N/A		
	C	Power supply	N/A	N/A	N/A		
	D	Auto starting of pump	N/A	N/A	N/A		

W



Prakash Deep Saraswati Vidya Mandir located at D-20, Panchal Vihar, Shiv Vihar, Delhi-110094

4	Cap	tive Water Storage for Fire Fighting:	N/A	N/A	N/A		
	A	Underground tank capacity	N/A	N/A	N/A		
1	В	Draw-off connection	N/A	N/A	N/A		
Ī	C	Fire service inlet	N/A	N/A	N/A		
Ī	D	Access to tank	N/A	N/A	N/A		
	E	Overhead tank capacity	N/A	N/A	N/A		
15	Exi	t Signage:	14/71				
16	47.10		1 N/A	N/A	N/A		
	A	Pressurization of lift shaft	N/A	N/A	N/A		
	B	Pressurization of lift lobby	N/A	N/A	N/A		
	C	Communication in lift car	N/A	N/A	N/A		
	D	Firemen's grounding switch	N/A	N/A	N/A		
- 4	E	Lift signage	N/A	N/A	N/A		
17			N/A	NA			
18		fuge Area:		27/4	N/A		
10	-	Total area	N/A	N/A	N/A		
	A B	Location	N/A	N/A	IVA		
10	Ti Control Pooms						
19	-		N/A	N/A	N/A		
	A	Detector system panel	N/A	N/A	N/A		
	B	Flow switch panel	N/A	N/A	N/A		
	C	PA system panel	N/A	N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
	E	Building floor plans	N/A	N/A	N/A		
20	Sp	ecial Fire Protection systems for otection of special Risks, if any:	1 18				

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2019/NDZ/1672 dated 22/08/2019 under the Circular no. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 is recommended to be renewed.

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation ADO (Laxmi Nagar)

DY. CFO/NDZ

C.F.O.

16'81)200

molto