Io. F6/DFS/MS/School/NDZ/2024/ 85)

Dated: 02/09/2024

## FIRE SAFETY CERTIFICATE

Certified that Government Girls Senior Secondary School No. 02 located at Tukhmir Pur, Delhi - 110094, comprised of ground plus one upper floor, (Old Building 4 Blocks A, B, C & D only) owned / occupied by Government Girls Senior Secondary School No. 02, was issued Fire Safety Certificate vide letter No F6/DFS/MS/School/NDZ/2021/611 dated 13/08/2021. The school building was re-inspected by the officer concerned of this department on 27/08/2024 in presence of Mrs. Sushila Singh (Vive - Principal) and observed that all the fire prevention and fire safety requirements in accordance with Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education and that the building is fit for occupancy class "Educational Building" (Group - B) for ground plus one upper floor, old block (except new block) with effect from 02/09/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 02 09 2024 at New Delhi by.

DIRECTOR DELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, B-Block, Anand Vihar, Delhi - 110091.

2. The Principal, Government Girls Senior Secondary School No. 02 located at Tukhmir Pur, Delhi - 110094.

## Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

N/20

_			= = =	1/20				
			INSPE	CTION REPOR	<u>T</u>			
1	Na	me	& address of the building	Government Girls Senior Secondary School N				
2	Bu	ildi	ng is comprised of	Ground plus o	Tukhmir Pur, Delhi - ne upper floor (04 I			
3	Tv	ne (	of occupancy	C, A & D Interconnected)				
4	Tv	ne d	of case	Educational Building				
5	_	1		Renewal				
			s of previous FSC	F6/DFS/MS/S 13/08/2021.	F6/DFS/MS/School/NDZ/2021/611 dated 13/08/2021.			
6	Fire safety directives letter no. F16/Estate/CC/Fire Safety/2011/3298 to 3 dated 01/03/2011.			98 to 3398				
7	Da	Date of inspection 27/08/2024.						
8	Na	me	of the inspecting officers	Yashwant Singh Meena ADO (L.N)				
9	Na	me	of the designation of officer he building side	Mrs. Sushila Singh (Vive - Principal)				
10			of construction	Block C - 2010	), B – 2011, A & D -	2013		
11	Ar	plie	cant's letter no.	Email dated 07	/08/2024.			
S.No		M	inimum standard of fire ntion and fire safety U/R 33	Circular Requirement	Provided at site	Remarks MR/NMR		
1	Ac	ces	s to Building:					
	A		oad width	6.0 mtrs.	6.0 mtrs.	M/R		
	d			4.50 mtrs.	5.0 mtrs.	M/R		
- 1	B	1	ate width	N/A	N/A	N/A		
	C	100	Vidth of internal road		IVA	1,7.1		
2	_	_	per, Width, Type and Arrang	gement of Exits:				
	A	N	lumber of staircases		04	1 M/D		
		a	Upper floor Basement	03 nos. N/A	04 nos. N/A	M/R N/A		
		b		IVA	IVA	.4.4.4.		
	В	a	Vidth of staircases Upper floor	1.50 mtrs.	1.5 mtr, 1.50 mtrs, 1.43 mtrs. & 1.30 mtr.	M/R		
		b	Basement	N/A	N/A	N/A		
	C	P	rotection of exits	27/4	N/4	27/4		
		a	Fire check door	N/A	N/A	N/A		
	D	N	Pressurization o. of continuous staircases terrace	N/A 01 no.	N/A 01 no.	N/A M/R		
	E		Vidth of corridor	1.5 mtrs.	2.10 mtrs.	M/R		
- 1	F	F Door size		1.0 mtr.	tr. 1.0 mtr.			
3	Co	mp	artmentation:					
	A	F	ire check door	NA	NA	NA		
	В	S	ealing of electrical shafts	N/A	N/A	N/A		
	C		ire rating of shaft door	N/A	N/A	N/A		
	D	- 22	/ater curtain	N/A	N/A	N/A		
25	E		re dampers	N/A	N/A	N/A		
4	Sn		e Management System:					
	A		asement	N/A	N/A	N/A		
	В	U	pper floor	N/A	N/A	N/A		

W

N	L
- 17	

T	Fire	Extinguisher:			
+		Total numbers	14 nos.	14 nos.	M/R
-	_		CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	M/R
1		Types	ISI Marked	Provided	M/R
		ISI marking	151 Marked		
	Firs	t-Aid-Hose Reel:	NI/A	N/A	N/A
	A	Total numbers of each floor	N/A N/A	N/A	N/A
	В	Length of hose reel hose	27-	N/A	N/A
	C Nozzle diameter		N/A	IVA	
1	Aut	tomatic Fire Detection and Alarm	ing System:	N/A	N/A
	A Type of detectors		N/A		N/A
	В	Location of main panel	N/A	N/A	N/A
	C	Location of repeater panel	N/A	N/A	0.0000000000000000000000000000000000000
	D	Alternate source of power	N/A	N/A	N/A
	E	Hooters	N/A	N/A	N/A
8		DEFA:	N/A	N/A	N/A
9		blic Address System:	N/A	N/A	M/R
10		tomatic Sprinkler System:			
10	A	Basement	N/A	N/A	N/A
	B	Upper floor	N/A	N/A	N/A
		Sprinkler above false ceiling	N/A	N/A	N/A
- 00 0	C	<b>A</b>	25 W T. T.		
11	_	ternal Hydrants:	N/A	N/A	N/A
	A	Size of riser/down-comer	N/A	N/A	N/A
	В	Control of the Contro	N/A	N/A	N/A
	C	Commence of the second of the	1971	5,847	
12	2 Y	ard Hydrants:	N/A	N/A	N/A
	A	2-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		N/A	N/A
	В		· N/A	IVA	1,1/2
1	3 P	umping Arrangements:			
1		Ground level	27/4	NT/A	N/A
	A		N/A	N/A	N/A
	В		N/A	N/A	N/A
	C		N/A	N/A	N/A
	I	Jockey pump out put	N/A	N/A	
	F	Jockey pump head	N/A	N/A	N/A
	F		N/A	N/A	
	(	Standby pump head	N/A	N/A	N/A
	_	Auto starting /manual stopping	N/A	N/A	5.00
	1	Pump house access	N/A	N/A	N/A
	1000	Terrace Level		7711	NT/A
F		A Discharge of pump	N/A	N/A	N/A
		B Head of the pump	N/A	N/A N/A	N/A
- 1	-	C Power supply	N/A N/A	N/A N/A	N/A
	1.5	Auto starting of pump			

-	1,000	tive Water Storage for Fire Fighting:	N/A	N/A	N/A
8	A	Underground tank capacity	N/A	N/A	N/A
	В	Draw-off connection	N/A	N/A	N/A
	C	Fire service inlet	N/A	N/A	N/A
- [	D	Access to tank	N/A	N/A	N/A
Ī	E	Overhead tank capacity	N/A N/A	N/A	N/A
5	Exi	Signage:	N/A		
16	Pro	vision of Lifts:	N/A	N/A	N/A
	A	Pressurization of lift shaft		N/A	N/A
ĺ	В	Pressurization of lift lobby	N/A	N/A	N/A
	C	Communication in lift car	N/A	N/A	N/A
	D	Firemen's grounding switch	N/A	N/A	N/A
	E	Lift signage	N/A	N/A	N/A
17	Sta	indby Power Supply:	N/A	*M	
18		fuge Area:	N/A	N/A	
	A	Total area	N/A	N/A	N/A
	B	Location	N/A	10.12	
19	-	re Control Room:	I NI/A	N/A	N/A
	A	Detector system panel	N/A N/A	N/A	N/A
	B		N/A	N/A	N/A
	C	PA system panel	N/A	N/A	N/A
	D	Battery backup	N/A	N/A	N/A
	E	Building floor plans	N/A	N/A	N/A
20		pecial Fire Protection systems for rotection of special Risks, if any:	1772		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards on fire preventior and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/NDZ/2021/611 dated 13/08/2021 under the Circular no F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 is recommended to be renewed.

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation ADO (L.N)

DY. CFO/NDZ

20 81 20M

Director

Aprylin

1.70