

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6 DFS/MS/School/2024/SZ/ 358

Dated: 04/09 / 2024

FIRE SAFETY CERTIFICATE

Issued on <u>04/69</u>2024 at New Delhi by

ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi -54.

2. M/s Kundan Singh Public School at F-150/4, Chattarpur Extension, New Delhi-74.

Conditions for the validity of Fire Safety Certificate:-

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. This certificate cannot be treated as regularization of unauthorized construction, if any.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



•	Name & Address of the Building	TION REPORT				
1		M/s Kundan Singh Public School at F-150/4, Chhattarpur Extension, New Delhi 110074.				
2	Type of Occupancy	Educational, Group-B				
3	Building Comprised of	Ground floor only				
	Type of Case Details of Previous NOC	Renewal				
6	Fire Safety Directives Letter No	F6/DFS/MS/School/2024/SZ/255 dated 24/02/2014				
		DOE Circular dated 01/03/2011				
7	Date of Inspection	29/08/2024				
9	Name of the Inspecting Officers	Sh. Rajesh Kumar				
	Name & Designation of Officers from the building side	Mr. Surender Singh				
10	Year of construction	2014				
11 S. No	Applicant letter No.	Outdoor diary no 5176 dated 12/08/2024				
BENTEN SACE	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL/NBC requirements	Provided at Site	Remarks MR/NMR		
1	Access to Building.		of the made resource as			
	Road width	Required	Provided	MR		
	Gate width	Required	Provided	MR		
	Width of internal road	-NA-	-NA-	-NA-		
2	Number, width, type & arrangement of exits.		State Market State			
	a) Number of Staircase		1 Albert F			
	Upper floors.	-NA-	-NA-	-NA-		
	▶ Basement floor.	-NA-	-NA-	-NA-		
	b) Width of Staircase	TVA		-14/4-		
	> Upper floors	NTA	ATA-	374		
	➤ Basement floor	-NA-	-NA-	-NA-		
	c) Protection of exits	-NA-	-NA-	-NA-		
	Fire check door	.74GeGP 4	ecist perifer insert in a			
	> Pressurization	-NA-	-NA-	-NA-		
	(A)	-NA-	-NA-	-NA-		
	d) No. of continuous staircase to terrace	-NA-	-NA-	-NA-		
	e) Width of corridor	-NA-	-NA-	-NA-		
Total Control	f) Door size	1.0 mtr	Provided	MR		
3	Compartmentation.					
11	Fire check door.	-NA-				
	Sealing of electrical shafts.	-NA-	-NA- -NA-	-NA-		
	Fire rating of shaft door.	-NA-	-NA-	-NA-		
	Water curtain	-NA-		-NA-		
	Fire dampers.	-NA-	-NA-	-NA-		
4.	Smoke Management system.	-INAP	-NA-	-NA-		
P	Basement	NIA	- millional s			
	Upper floors	-NA-	-NA-	-NA-		
5.	Fire Extinguishers.	-INA-	-NA-	-NA-		
	Total numbers	Dami'				
	Types	Required	02 Nos	MR		
	ISI Marking	ABC type	ABC Type	MR		
6.	First Aid Hose Reels.	ISI mark	Provided	MR		
gj.	Total numbers on each floor.		م کسال الدک			
		-NA-	-NA-	-NA-		
	Length of hose-reel hose.	-NA-	-NA-	-NA-		
	Nozzle Diameter	-NA-	-NA-			
7 -	Automatic fire detection & alarming system.			-NA-		
	Type of detectors	-NA-	NA TOTAL	717		
	Location of Main Panel	-NA-	-NA-	-NA-		
	Location of Repeater Panel	-NA-	-NA-	-NA-		
	Alternate source of power		-NA-	-NA-		
	Ilooter's location	-NA-	-NA-	-NA-		
8.	MOEFA	-NA-	-ΝΛ-	-NA-		
9.	Public Address System	-NA-	-NA-			
10.	Automatic Sprinkler System	-NA-	-NA-	-NA		
	AUTOMATIC SDITINGER System			-NA		

N/ 10

			-NA-	-NA-
	The state of the s	-NA-	-NA-	-NA-
	Basement	-NA-	-NA-	-NA-
	Linner floors	-NA-	-117	
JV.	Sprinkler above false ceiling		314	-NA-
-	Internal Hydrants.	-NA-	-NA-	-NA-
11.	Size of Riser/Down-comer	-NA-	-NA-	-NA-
	Number of Hydrant per floor	-NA-	-NA-	
	Hose box.	-NA-		-NA-
	Yard Hydrants.	774	-NA-	
12.	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-		
			THE WELL PUR TO	
13.	Pumping arrangements. • Ground Level	ad a nettern	-NA-	-NA-
	 Ground Level Discharge of main pump. 	-NA-	-NA-	-NA-
	to the common terms	-NA-		-NA-
	Carain mumme	-NA-	-NA-	-NA-
	The state of the s	-NA-	-NA-	-NA-
	Jockey Pump output.Jockey Pump head.	-NA-	-NA-	-NA-
	> Standby Pump output.	-NA-	-NA-	-NA-
	> Standby Pump head.	-NA-	-NA-	-NA-
	> Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	> Pump house access.	-NA-	-NA-	-IVA-
			Mariles of Greature	374
	Terrace Level Discharge of pump	-NA-	-NA-	-NA-
	> Head of pump.	-NA-	-NA-	-NA-
	> Power supply.	-NA-	-NA-	-NA-
	> Auto starting of pump.	-NA-	-NA-	-NA-
1.4	Captive water storage for fire fighting.		go il trembhal 🐣	
14.	Underground tank capacity.	NA	-NA-	-NA-
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	-NA-	-NA-	-NA-
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		4312 1050	-NA-
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	
	Lift signage.	-NA-	-NA-	-NA-
17.	Standby Power Supply	-NA-	-NA-	-NA-
18.	Refuge Area		Large Area of the Life A . (0)	NIA
	Total area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
19.	Fire Control Room.		, leastly by a	
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA- "
	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

la lagua



The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/School/2024/SZ/255 dated 24/02/2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (South)

Any pli approved, F.t. Fetter in pr your synature Pl