



No F 6 / DFS / MS / 2024 /School/WZ/ 860

04/09/2024 Dated

FIRE SAFETY CERTIFICATE

Certified that the M.C. Primary Boys School located at Holambi Khurd, Delhi-110082 comprised of Ground and First floor was issued FSC by this department vide letter No F6 /DFS/MS/2021/School/WZ/665 dated 27.08.2021. The premises was re-inspected by the officer concerned of this department on 23.08.2024 in the presence of Smt. Savita (In-charge), and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from 1.109.12024. for a period of three years, subject to compliance of the conditions mentioned below: Issued on ... 04 109 224. at New Delhi by

011-23414000

Copy to:-

1. The Director, Education, Government of NCT of Delhi. Old Sect. Delhi-110054

The Principal, M.C. Primary Boys School, Holambi Khurd, Delhi-110082.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the

occupant, in a safe manner, in the event of emergency.

9. Electric meter and electrical panel under the staircase must be removed within a period of three months from the date if issuance of the Fire Safety Certificate. Failing to do so the Fire Safety Certificate will be null and void.

INSPECTION REPORT

Name & address of the building : MC Primary Boys School, Holambi Khurd, Delhi- 110082.

Type of Occupancy Educational

Building Comprised of Ground plus First floor

Type of Case Renewal

5. Details of Previous NOC F6/DFS/MS/2021/School/WZ/665 dated 27/08/2021 6. Fire Safety directives letter No DOE circular No. 3298-3398 dated 01/03/2011

7. Date of inspection 23/08/2024

8. Name of Inspecting Officer R.K.Sinha, ADO (BW)

9. Name and designation of officers

From the building side : Smt. Savita (In-charge)

0.	the section of the se	t's letter No. : Standards on fire n and fire safety U/R 33	DOE Requirement	Provided at site	Remarks MR/NMR			
	Access to							
	• Ro	ad width	6 m	Provided	MR			
		te width	4.5 m	Directly Accessible	MR			
		dth of internal road	NA	NA NA	NA			
R	Number, Width, Type & Arrangement of Exits							
0	a. Number	of staircases		The second manufactured to				
	• U	pper Floors	02	02	MR			
	• B	asements	NA	NA	NA			
	b. Width o	f staircases	70	The prompt of the				
	• U	pper Floor	1.50 m each	Provided	MR			
		sements	NA NA	NA	NA			
	c. Protecti	on of exits						
	• Fi	re check door	NA	NA	NA			
		essurization	NA	NA	NA			
		continuous staircases to	NA NA	NA pgala amil	NA			
	e. Width o	f Corridor	NA	NA	NA			
F	f. Door S	ize	1 m	Provided	MR			
	Compartmentation							
	• Fir	check door	NA NA	NA	NA			
	• Sea	ling of electrical shafts	NA	NA	NA			
1		Rating of shaft door	NA	NA NA	NA			
-		ter Curtain	NA NA	NA NA	NA			
		Dampers	NA	NA	NA			
1	Smoke Management System							
-		ements	NA NA	NA I	NA			
1		per floors	Required	Naturally Ventilated	MR			
1			A COTTEN	M. A. S.	- 100			
+	Fire Exting	100 March 100 CO. 100						
F		al numbers	04	05	MR			
L	 Typ 		ABC/CO2 Type	Provided	MR			
-		narking	Required	Provided	MR			
1 2	First-Aid H		A 40					
-		al numbers on each floor	NA	NA	NA			
1		gth of hose reel hose	NA	NA	NA			
	Noz	zle diameter	NA	NA	NA			
1	Automatic fire detection and alarming system							
		e of detectors	NA	NA	NA			
		tion of Main Panel	NA	NA				
	19 HE 20 CONTROL OF THE PARTY O	tion of Repeater Panel	NA	NA	NA			
	• Alte	rnate source of power	NA	NA NA	NA			
	. 11-	ers' Location	NA	IIA	NA			
	Hoq	CIS LOCATION	jh h	NA	NA			

		p-14		<u> </u>		
	LMOREA	NA	NA	NA		
9.	MOEFA Public Address System	NA	NA	NA		
10.	Automatic Sprinkler System					
	Basement	NA	NA -	NA		
	Ground Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11.	Internal Hydrants	Late the	July 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
	Size of riser/down-comer	NA	NA	NA .		
	Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
12.	Yard Hydrants					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA NA		
13.	Pumping Arrangements					
	Ground Level					
	➤ Discharge of main Pump	NA	NA	NA		
	➤ Head of Main pump	NA	NA	NA		
	> Number of main pumps	NA	NA	NA		
	➢ Jockey Pump out put	NA	NA	NA		
	> Jockey pump head	NA	NA	NA		
	Standby Pump out put	NA	NA	NA		
-	Standby Pump Head Auto Starting/Manual	NA	NA	NA		
	➤ Auto Starting/Manual Stopping	NA	NA	NA		
	➤ Pump House Access	NA	NA	NA		
	Terrace level	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
	Discharge of pump	NA	NA	NIA		
	➤ Head of the pump	NA	NA NA	NA NA		
	> Power Supply	NA	NA	- NA		
	> Auto Starting of pump	NA NA	NA NA			
1.	Captive Water Storage for fire fighting	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		NA N		
	Underground tank capacity	NA	NA	N/A		
	Draw-off connection	NA NA	NA NA			
	> Fire service inlet	NA	NA NA	J. 1111 (1997)		
	> Access to tank	NA NA	NA NA			
	Overhead Tank capacity	NA NA	NA NA	18.5 TA 1 TA 18.00.00		
5.	Exit Signage.	Required	Provided	MR		
5.	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA.	- 47		
-		A Charles of the Control of the Cont	NA			
	Pressurization of Lift lobby Communication In 119 Communication	NA /	NA			
	Communication In lift Car	NA	NA			
-	Fireman's Grounding Switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
•	Standby power supply	NA	NA	NA		
	Refuge Area.					
	> Total Area	NIA I				
-	> Location	NA NA	NA NA	NA		
		IVA	NA	NA		

Detector System Panel	NA	NA	T
Flow Switch Panel	NA	NA NA	NA
PA System Panel		NA NA	NA
	NA	NA	NA
Battery backup	NA	NA	NA
Building Floor Plans	NA		
	177.000.00	NA	NA
Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: Electric meter and electrical panel found installed under the staircase which have to be removed to a safer place.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under DOE circular no. 3298-3398 dated 01/03/2011, it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DF\$/MS/2021/School/WZ/665 dated 27/08/2021.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

OFO, 323-NIO

4 cho (w) 1/287

30/8 sou

8m, FT

Anythin mutp f

for son ple

3/9/27

Inetor Of SM John