

C-58

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/EH/2024/SZ/29/ No.

Dated. 09/09/2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & Style of M/s Social Ambience Mall Situated at Shop No T- 306, 3rd Floor, Ambience Mall, Plot No 2, Nelson Mandela Marg, New Delhi 110070, Comprised of 03 Basements, Ground Plus Three Upper Floors owner/occupied by Impresario Entertainment & Hospitality Pvt. Ltd was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/SZ/2021/209 Dated 02/09/2021. The restaurant premise was re-inspected by the officer concerned of this department on 02/09/2024 in the presence of Mr. Omparkash found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant at 3rd Floor only and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued on 09/09/2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Joint C.P (Lic) 1st Floor, PS Defence Colony, New Delhi 110049. Ref. MHA Portal ID 2024081212570 dated 12/08/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system. 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first www.dfs.delhigovt.nic.in 2010. The form is


5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to



1

10	INSPECTION REPORT					
1	Name & Address of the Building	M/s Social Ambience Mall (A Unit of Impresario Entertainment & Hospitality Pvt. Ltd.) Shop No T-306, 3 rd Floor, Ambience Mall, Plot No 2, Nelson Mandela Marg, New Delhi 110070.				
	Type of Occupancy			ling "Group-D" Restauran		
2	Building Comprised of	Three tier Basement, Ground + 03 upper floors			loors	
3		Renewal			FIL 108	
4	Type of Case Details of Previous NOC	F.6/DFS/MS/EH/SZ/2021/209 Dated 02/09/2021				
5	Fire Safety Directives Letter No	Nil myses themen's viriable.				
6	Fire Safety Directives Botton	02/09/2024				
7	Date of Inspection Name of the Inspecting Officers	Sh. DO (South) & ADO (BCP)				
9	Name & Designation of Officers from the building side	Mr. Omparkash				
10	Year of construction	2010 Restaurant running at 3 rd Floor in Ambiance Mall building.				
11	Applicant letter No.	100000000000000000000000000000000000000		2024081212570 dated 12		
S. No.	Minimum standards on Fire Prevention	D	/BBL rement	Provided at Site	Remarks MR/NMR	
1	and Fire Safety U/R 33 Access to Building. FSC No.F.6/DFS/MS/M	all/2023/	SZ/35 Da	ted 25/01/2023 of Ambienc	e Maii	
	Road width	9m 5m		Provided*	MR	
	Gate width Width of internal road			Provided* Provided*	MR MR	
	In the second (2011)	Favite		water water to be a fire		
2	Number, width, type and arrangements of	D.	ovided &	Maintained by Ambian	ice Mall	
	a. Number of Staircase	02 Nos 02 Nos		17 Nos	MR	
	Upper floors Basement floor			17 Nos	MR	
		Provided &		Maintained by Ambiar	ice Mall	
	b. Width of Staircase	1.50 mtr each N/A		Provided	MR	
	Upper floors			As above	N/A	
	Basement floor			Maintained by Ambian	ice Mall	
	c. Protection of exits	Required		As above	MR	
	Fire check door		/A	As above	N/A	
	Pressurization	1 1 2	uired	As above	MR	
	d. No. of continuous staircase to terrace	J	/A	N/A	N/A	
7	e. Width of corridor f. Door size	2 exits (2 m & 1 m)		2 m & 1 m	MR	
				ovided & Maintained by Ambiance Mall		
3	Compartmentation.		uired	As above	MR	
	Fire check door.		/A	As above	N/A	
	Sealing of electrical shalls.		/A	N/A	N/A	
	Fire rating of shaft door.		/A	N/A	N/A	
	Water curtain			N/A	N/A	
	• Fire dampers.	N/A		Maintained by Ambier	ce Mall	
4.	Smoke Management system.	NI/A		As above	N/A	
	BasementUpper floors		uired	Exhaust fans provided	MR	
5.	Fire Extinguishers.		, 1	gabboom on a stately	MR	
	Total numbers	05	Nos	06 Nos.		
	• Types			ABC-04, W.CO ₂ -02	MR	
	ISI Marking	ISI marked		Provided	MR	
6.	First Aid Hose Reels.	Pr	ovided &	& Maintained by Ambience Mall		
	Total numbers on each floor.			One in Restaurant	MR	
	a I could offer a sell.	Hose Reel		30m	MR	
	Nozzle Diameter			5mm	MR	







Fire Control Room.	Provided & Maintained by Ambience Mall		
Detector System Panel. Flow Switch Panel.	N/A	As above	N/A
PA system Panel.	N/A	As above	N/A
	N/A	As above	N/A
Building floor plan	N/A	As above	N/A
	N/A	As above	N/A
Special Fire Protection System for the Protection of special Risk, if any:	N/A	As above	N/A
	Detector System Panel. Flow Switch Panel. PA system Panel. Battery backup Building floor plan Special Fire Protection System for the	Detector System Panel. Flow Switch Panel. PA system Panel. Battery backup Building floor plan Special Fire Protection System for the	Detector System Panel. Flow Switch Panel. PA system Panel. Battery backup Building floor plan N/A As above N/A As above

Note: Fire Safety arrangement provided & Maintained by Ambience Mall

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/SZ/2021/209 Dated 02/09/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ)

Dinester My

My souded