

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

ग्राजादी मा अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2024/ 895

Dated: 11/09/2024

FIRE SAFETY CERTIFICATE

Certified that C.R. Dass Govt. Sarvodaya Kanya Vidyalaya located at New Seelampur, Delhi110053, comprised of ground plus one upper floor owned / occupied by C.R. Dass Govt. Sarvodaya
Kanya Vidyalaya, was issued Fire Safety Certificate vide letter No F6/DFS/MS/School/2021/NDZ/809
dated 01/10/2021. The school building has complied with the fire prevention and fire safety requirements
in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011
issued by Director of Education and re-inspected by the officer concerned of this department on 02/09/2024
in the presence of Mrs. Bhavna Gupta (Principal) & Mr. P. K Sharma (Estate Manager) of the school and
that the school building is fit for occupancy class Group B "Educational Building" with effect from

11/09/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or
sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire
Service Rules, 2010 subject to conditions printed bellow.

Issued on 11 09 2024 at New Delhi by.

DIRECTOR

CDELHI FIRE SERVICE

Copy to: -

- 1. The Commissioner, MCD, Headquarters, 419, Udyog Sadan, Patparganj Industrial Area, Delhi 110092.
- 2. The Joint Director of Education, (Land & Estate), Director of Education, Lucknow Road, Delhi 110054.
- 3. The Principal, C.R. Dass Govt. Sarvodaya Kanya Vidyalaya located at New Seelapur, Delhi 110053.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

4)19

					TION REPORT					
		Name & address of the building C.R. Dass Govt. Sarvodaya Kanya Vidyala								
2	Building is comprised of				located at New Seelapur, Delhi - 110053.					
,		Type of occupancy			THE RESERVE THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	Ground plus one upper floor				
1		Type of case				Educational Building				
5					500/050/5/WE500	Renewal				
,		Details of previous FSC			F6/DFS/MS/School/2021/NDZ/809 dated					
5		Fire safety directives letter no.			01/10/2021 F16/Estate/CC/Fire Safety/2011/3298 to 3398					
,					dated 01/03/2011.					
7		Date of inspection 03/09/2024								
8		-			100 (1 N)					
9		Name of the inspecting officers Name of the designation of officer			Mrs. Bhavna Gupta (Principal) &					
,		from the building side			Mr. P. K Sharma (Estate Manager)					
10		Year of construction			1997					
11				ant's letter no.	Outdoor Diary No. 56123 dated 23/08/2024					
	No		M	inimum standard of fire ntion and fire safety U/R 33	Requirement Circular	Requirement Provided at site				
1	_	Ac	ces	s to Building:						
		A		oad width	6.0 mtrs.	8.0 mtrs.	MR			
	-			ate width	4.50 mtrs.	5.60 mtrs.	MR			
		B	1000	idth of internal road	N/A	N/A	N/A			
		C	0.55%	Participation of the Company of the	G-1251-0-1					
2				er, Width, Type and Arrang	gement of Exits.					
		A	N	umber of staircases		05 nos.	MR			
			a	Upper floor	04 no. N/A	N/A	N/A			
1			b	Basement	NA	13/21	*****			
		В		idth of staircases	1.5 mtrs./0.75	Provided	MR			
			a	Upper floor	mtr add.	Tiovided	, , , ,			
			b	Basement	N/A	N/A	N/A			
		C	Pr	otection of exits						
			а	Fire check door	N/A	N/A	N/A			
١			b	Pressurization	N/A	N/A	N/A			
3		D		o. of continuous staircases	01 no	01 no	MR			
		E		terrace lidth of corridor	1.5 mtrs.	2.10 mtrs. & 1.50 mtrs.	MR			
		F	Do	oor size	1.0 meter.	1.0 meter.	MR			
		Compartmentation:								
		A		re check door	NA	NA	NA			
	1	В	10,100	aling of electrical shafts	N/A	N/A	N/A			
	}	C	212-5	re rating of shaft door	N/A	N/A	N/A			
	1	5		ater curtain	N/A	N/A	N/A			
		E		re dampers	N/A	N/A	N/A			
		200		Management System:	2.0/2.8		ANT			
1				sement	N/A	N/4	N1/4			
		A				N/A	N/A			
1		B	U	pper floor	N/A	N/A	N/A			

5.	Fi	re Extinguisher:	19 nos.	MR				
	A	Total numbers	19 nos. CO ₂ & ABC	CO ₂ & ABC	M			
	B	Types	D-55-039-477-7	Provided	MI			
	C ISI marking		ISI Marked	Horizon	V2.5541			
6	Fi	rst-Aid-Hose Reel:	7 - 1970	N/A	N/A			
	A	Total numbers of each floor	N/A	N/A N/A	N/A			
	В	Length of hose reel hose	N/A		N/A			
	C	Nozzle diameter	N/A	N/A	INF			
7	Automatic Fire Detection and Alarming System:							
1	A	Type of detectors	N/A	N/A	N/A			
	В	Location of main panel	N/A	N/A	N/A			
	C	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooter's Location	N/A	N/A	N/A			
8	MOEFA:		N/A	N/A	N/A			
•	Pu	blic Address System:	N/A	Provided /	MF			
10	Au	tomatic Sprinkler System:	200 200 200					
	A	Basement	N/A	N/A	N/A			
	В	Upper floor	N/A	N/A	N/A			
	C	Sprinkler above false ceiling	N/A	N/A	N/A			
1	1071							
	A	Size of riser/down-comer	N/A	N/A	N/A			
	В	Number of hydrants per floor	N/A	N/A	N/A			
	C	Hose box	N/A	N/A	N/A			
2	Ya	Yard Hydrants:						
	A	Total number of hydrants	N/A	N/A	N/A			
ı	В	Hose box	N/A	N/A	N/A			
3	Pur	nping Arrangements:		IVA	IVA			
+	Ground level							
+	A	Discharge of main pump	N/A	N/A	N/A			
ŀ	В	Head of main pump	N/A	N/A	N/A			
H	c	Number of main pumps	N/A	N/A	N/A			
H	D	Jockey pump out put	N/A	N/A	N/A			
-	E	Jockey pump head	N/A	N/A	2.74.50			
-	F	Standby pump out put	N/A	N/A N/A	N/A N/A			
\vdash	G	Standby pump head	N/A	N/A				
-	H	Auto starting /manual	N/A N/A	N/A N/A	N/A N/A			
1		stopping	14/15	IV/A	IVA			
h		Pump house access	N/A	N/A	N/A			
7	Гerr	race Level			- 17 4 4			
-	4	Discharge of pump	N/A	N/A	N/A			
_	3	Head of the pump	N/A	N/A	N/A			
_		Power supply	N/A	N/A	N/A			
\vdash	5	Auto starting of pump	N/A	N/A	N/A			

(1)

A	U	nderground tank capacity	N/A	N/A	N/A		
B	D	raw-off connection	N/A	N/A	N/A		
C	F	ire service inlet	N/A	N/A	N/A		
a	1	Access to tank	N/A	N/A	N/A		
T	_	Overhead tank capacity	N/A	N/A	N/A		
5 1			N/A	N/A	N/A		
6							
16	A	Pressurization of lift shaft	N/A	N/A	N/A		
	В	Pressurization of lift lobby	N/A	N/A	N/A		
	C	Communication in lift car	N/A	N/A	N/A		
	D	Firemen's grounding switch	N/A	N/A	N/A		
	E	Lift signage	N/A	N/A	N/A		
17	Sta	ndby Power Supply:	N/A	N/A	N/A		
18	Refuge Area:						
	A	Total area	N/A	N/A	N/A		
	В	Location	N/A	N/A	N/A		
19	Fire Control Room:						
	A	Detector system panel	N/A	N/A	N/A		
	B	Flow switch panel	N/A	N/A	N/A		
	C	PA system panel	N/A	N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
	E	Building floor plans	N/A	N/A	N/A		
20	O Special Fire Protection systems for protection of special Risks, if any:		N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2021/NDZ/809 dated 01/10/2021 under the Circular no. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 is recommended to be renewed.

No file is pending with me before disposal of this case.

4/9/2024 Signature of the Inspecting Officer Yashwant Singh Meena Name ADO (Laxmi Nagar) Designation