



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

गणादी न अमृत महोत्सव

No. F6/DFS/MS/GH/SZ/2024/367

Dated: 06 09 2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Varun Guest House located at 31, Nangli Razapur East Nizamuddin, New Delhi-13, comprised of Basement + Ground + 03 upper floors: Basement - found closed, (Ground floor- reception + 01 office + 1 store, 1st floor - 03 guest rooms, 2nd floor- 03 guest rooms, 3rd floor - 03 guest rooms, was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/GH/2021/SZ/19 dated 11.01.2021. The building/premises was re-inspected by Assistant Divisional Officer (M. Road) from this department on 03.09.2024 in presence of Mr. Rahul Pandey (Manager) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Residential Sub Division-A-1" for total 09 Guest rooms (Ground floor- reception + 01 office + 1 store, 1st floor - 03 guest rooms, 2nd floor- 03 guest rooms) and valid upto 31.03.2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on ...O.6 09 2024 at New Delhi by

Director

Delhi Fire Service

11 12/9/24 M

Reference: MHA Portal Online application no. 2024081712819.

Conditions for the validity of Fire Safety Certificate

 All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

Т				CTI	ON REPORT				
		ame & address of the building M/s Varun Guest House located at 31, Nang Razapur East Nizamuddin, New Delhi-13.							
2	Building is comprised of			Ba Ba Gi 1st 2nd	Basement + Ground + 04 upper floors Basement- (found closed, Affidavit submitted) Ground floor- reception + 01 office + 1 store 1 st floor - 03 guest rooms 2 nd floor- 03 guest rooms				
3	Type of occupancy			3 rd floor - 03 guest rooms Residential Group A-1					
4	Type of case		11.00	Renewal					
5	Details of Previous FSC			(45)(54)	F6/DFS/MS/GH/2021/SZ/19 dated 11.01.2021				
6	AT THE PERSON AS		0000		TODATO GUITA TE				
7	Fire Safety directive letter no.			1000	Nil				
8	Date of inspection				03.09.2024 Rajesh Kumar Shukla ADO (M. Road)				
9		Name of the inspecting officers					,		
y	Name of the designation of officer from the building side				Mr. Rahul Pandey (Manager)				
10		3.77	nstruction		1991 & 2022				
11	Appli	cant	's letter no.		MHA online application no. 2024081712819				
S.I o	Pre	nimu vent uire			equirement as er Rule 35 (6)	Provided at Site	Remarks MR/NMR		
1	Acc	Access to building					45 (Caus)		
	A	Ro	oad width		Required	6.0 mtrs	MR		
	В		ate width		NA	NA	NA		
	C	1000	idth of internal road		NA	NA	NA		
2			r, Width, Type and Arrang	geme	nt of Exits		×		
-	A	ı	lumber of staircases						
		a	Upper floor	_	Required	1 no.	MR		
			Basement		NA	NA	NA		
	В	a	Width of staircases Upper floor		1.0 mtrs	1.0 mtrs to 1.20 mtrs	MR		
		b	Basement		NA	NA NA	NA		
	C		otection of exits			YT -	1.000		
			Fire check door		NA	NA	NA		
		_	Pressurization		NA	NA	NA		
	D	terrace		to	Required	01 no.	MR		
	E	1 PARKE TARGESTANIS			NA	NA	NA		
_	F		oor size		1.0 mtrs	1.05 mtrs (final exit)	MR		
3			rtmentation						
	A				NA	NA	NA		
	1 2	8 Silving			NA	NA	NA		
	D	Fire rating of shaft door Water curtain			NA	NA	NA		
		E Fire dampers			NA	NA	NA		
4	Smoke Management System.				NA	NA	NA		
	A		sement		NA				
ů.					NA	NA	NA		
	B	Up	per floor		NA	NA	TAV		

5.	Fire Extinguisher							
	A Total numbers			08 nos.	08 nos.	MR		
	В	_	pes '	, Anticatorio	CO ₂ & ABC	MR		
	C	-	marking	CO ₂ & ABC	ISI marked	MR		
•	10000	17.11-14		Required	151 marked			
6			Aid-Hose Reels			MR		
	A Total numbers of each floor			01 no.	01 no.	MR		
	B		ngth of hose reel hose	30 mtrs.	30 mtrs.	1.50		
	C	No	zzle diameter	5 mm	5 mm	MR		
7	Automatic Fire Detection And Alarming System (required as per clause 7.31.viii,							
	UBBL 2016).							
	A Type of detectors			CO detectors	Provided	MR		
	В	L	ocation of main panel	At ground floor	Provided	MR		
	C	L	ocation of repeater panel	NA	NA	NA NA		
	D	A	lternate source of power	NA	NA	NA MR		
VIII.	E	Hooters		Audible in entire building	Provided			
8	M	OEI	⁷ A	Required	Provided	MR		
9	Pu	blic	Address System.	NA	NA	NA		
10	_		natic Sprinkler System.		M N			
n fami	A		sement (Area less than 200 m	2) NA	NA	NA		
	В			NA	NA	NA		
	C	Library And Parket States and		NA	NA	NA		
11	Internal Hydrants							
**	A size of riser/down-comer			NA	NA	NA		
	B			NA NA	NA	NA		
	C			NA	NA	NA		
12	Yard Hydrants.							
	A Total number of hydrants			NA	NA	NA		
	В		se box	NA	NA	NA		
13	Pumping Arrangements.							
	A		round Level					
	-	a	Discharge of main Pump	NA	NA	NA		
		ь	Head of Main Pump	NA	NA	NA		
		c	Number of main pumps	NA	NA	NA		
		d	Jockey pump out put	NA	NA	NA		
	-	e	Jockey pump head	NA	NA	NA		
		f	Standby pump out put	NA	NA	NA		
		g	Standby pump Head	NA	NA	NA		
		h	Auto Starting /Manual stopping	NA	NA	NA		
	-	i	Pump house access	NA	NA	NA		
	В		rrace Level	1400	7977			
	4	a	Discharge of pump	450 LPM	450 LPM	MR		
		b	Head of the Pump	40 mtrs.	40 mtrs.	MR		
		d	Power supply Auto starting of pump	Required	Provided	MR		
		1000	Auto starting of pump uest House located at 31, Nangli Razap	Required	Provided	MR		

14	M/s Varun Guest House located at 31, Nangli Razapur East Nizamuddin, New Delhi-13. Captive Water Storage for Fire Fighting.							
	A Underground tank capacity	NA NA	NA	NA				
	B Draw-off connection	NA	NA	NA				
	C Fire service inlet	NA	NA	NA				
	D Access to tank	NA	NA	NA				
	E Overhead tank capacity	5,000 ltrs	5,000 ltrs	MR				
15	Exit Signage.	Required	Provided	MR				
16	Provision of Lifts.							
	A Pressurization of lift shaft	NA	NA	NA				
	B Pressurization of lift lobby	NA	NA	NA				
	C Communication in lift car	NA	NA	NA				
	D Firemen's grounding switch	NA	NA	NA				
	E Lift signage	NA	NA	NA				
17	Standby Power Supply	Required	Provided	MR				
18	Refuge Area.							
177.00	A Total area	NA	NA	NA				
	B Location	NA	NA	NA				
19	Fire Control Room							
	A Detector system panel	NA	NA NA	NA				
	B Flow switch panel	NA	NA	NA NA				
	C PA system panel	NA	NA NA	NA NA				
	D Battery backup	NA	NA NA	NA NA				
	E Building floor plans	NA	NA	NA NA				

LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

NA

Note:- All the internal walls of rooms on terrace have been demolished and construction on terrace has been rendered unusable/Inhabitable (Photos placed on C/65 to C/67 on file). An affidavit for not using any floor above 3rd floor for guest house has been submitted by the owner (Affidavit placed at C/68 & 69 on file.).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

If agreed to the note above & in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/2021/SZ/19 dated 11.01.2021 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

> Signature of the Inspecting Officer Rajesh Kumar Shukla Name ADO (M. Road) Designation

NA

NA

Building floor plans

20

Special Fire Protection Systems For

Protection Of Special Risks, If Any: