

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/NDZ/2024/ 557

Dated: 12/09/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s V3S Mall located at Plot No. 12, District Centre, Laxmi Nagar, Delhi - 110092, comprised of two basements, ground plus four upper floors owned/occupied by M/s V3S Infratech Limited was issued FSC vide letter no. F6/DFS/MS/NDZ/2021/461 dated 23.09.2021. The Mercantile building (mixed occupancy) was re-inspected by the officers concerned of this department on dated 28/08/2024 in presence of Mr. Vineet Kant Parashar (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Multiplex / Mercantile Building" two basements, ground plus four upper floors with effect from 12/09/2024 for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule 2010, printed below.

Issued on 1209 2024 at New Delhi by.

(ATUL GARG)
DIRECTOR
© CDELHI FIRE SERVICE

#### Copy to:-

- 1. The Dy. Director (Bldg.), C & I, DDA, C-1, 2<sup>nd</sup> floor, Vikas Sadan, New Delhi.
- 2. The Manager, V3S Infratech Limited, Plot No. 10, District Centre, Laxmi Nagar, Delhi 110092.

## Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. Presently, Basement is being used for Parking. Services & Estate Office.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

			200	TION REPORT			
1	Name & address of the building		V3S Mall located at Plot No. 12, District Centre Laxmi Nagar, Delhi - 110092.				
2		Building is comprised of		Two Basement, Ground plus four upper floors.			
3	Type of occupancy		Multiplex/Mercantile				
4	Type of case		Renewal				
5	Details of previous FSC		F6/DFS/MS/NDZ/2021/461 dated 23.09.2021				
6	Fire safety directives letter no.		F6/MS/DFS/BP/2019/56 dated 08/02/2019				
7	Date of inspection		28.08.2024				
8	Name of the inspecting officers		Sumesh Kumar Dua, DCFO/NDZ & Yashwan				
9	Name of the designation of officer from the building side		Singh Meena ADO (Laxmi Nagar)  Mr. Vineet Kant Parashar (Manager)				
10	Year of construction			2006 & 2020 - 2	)1		
11	Ap	plicant's letter no.					
S.No		Minimum standard of fir evention and fire safety U	re TR 33	Requirement as per Directive	o. 5333 dated 16/08/2 Provided at site	Rei	marks /NMR
i	7.0	cess to Building:					
	A	Road width		11 mtrs.	45 mtrs.	Γ.	
	B	Gate width		4.50 mtrs	06 mtrs.		MR
2	770-4-51	Width of internal road		07	06 mtrs.		MR
31	A	mber, Width, Type and A	rrange	ement of Exits:	o mus.		MR
	A	Number of staircases	JAM I	-			
	-	a Upper floor b Basement		15 nos.	18 nos.	-	) (D
	В	b Basement Width of staircases		13 nos.	15 nos. + 02 ramp		MR
	-				- 02 Talli	-	MR
		- FF-11 11001		meters & 1.25 meters.	1.25 mtrs, 1.50 mtrs, mtrs & 2.50 mtrs	2.0	MR
	C		1.2	5 meters & 1.5 meters.	1.25 mtrs. & 1.5 m	- 1	MR
	C	Protection of exits					
7.1		a Fire check door		Required	Provided		(4(74)2)
	D	b Pressurization		Required	Provided		MR
		No. of continuous staircases to terrace		04 nos.	04 nos.		MR
	E	Width of corridor			OT 1105.		MR
	F	Door size		02 meters.	2.10 meters.		MR
			2.	0 mtrs & 1.50	2.0 mtrs & 1.50 m	trs	MR
3	Co	mpartmentation:		mtr.			14116
	A Fire check door						
	В	Sealing of electrical shafts		Required	Provided		MR
	C	Fire rating of shaft door	S	Required	Provided		MR
	D	Water curtain		02 hrs	Provided		MR
	E			Required	Provided	_	MR
	- 110 danipeis		Required	Provided		- Co-Antibotio	
	Smoke Management System:				LIOVIGED		MR
	A	D					
	A	Basement		30 a/c per hrs	Description		1
	A B	Basement Upper floor		30 a/c per hrs 12 a/c per hrs	Provided Provided		MR

W

# 

5.	_	re Extinguisher:							
	A	Total numbers	130 nos.	140 nos.	MR				
	В	Types	CO₂ & ABC	CO₂ & ABC	MR				
	C	ISI marking	ISI Marked	ISI Marked	MR				
6	First-Aid-Hose Reel:								
	A	Total numbers of each floor	12 nos.	12 nos.	MR				
	В	Length of hose reel hose	30 meters.	30 meters.	MR				
	C	Nozzle diameter	05 mm	05 mm	MR				
7	Automatic Fire Detection and Alarming System:								
	A	Type of detectors	Smoke/Heat	Provided	MR				
	В	Location of main panel	Control room	Provided	MR				
	C	Location of repeater panel	Security room	Provided	MR				
	D	Alternate source of power	Batter & DG Set	Provided	MR				
	E	Hooters location	Staircase	Provided	MR				
8	M	OEFA:	Required	Provided	MR				
9	Pu	blic Address System:	Required	Provided	MR				
10	_	tomatic Sprinkler System:	real Track part part	LE LINES					
	A	Basement	Required	Provided	MR				
	В	Upper floor (P.S. Only)	Required	Provided	MR				
	C	Sprinkler above false ceiling	Required	Provided	MR				
11	315	ternal Hydrants:	1						
**	A	Size of riser/down-comer	150 mm	150 mm	MR				
	B	Number of hydrants per	12 nos.	12 nos.	MR				
		floor	2-7- (M25-2-N	22.000					
	C	Hose box	12 nos.	12 nos.	MR				
12	Ya	rd Hydrants:			Hi				
	A	Total number of hydrants	11 nos.	11 nos.	MR				
	В	Hose box	11 nos.	11 nos.	MR				
13	Pu	mping Arrangements:							
1	Ground level								
	A	Discharge of main pump	2250 LPM	2250 LPM	MR				
	В	Head of main pump	70 M	70 M	MR				
	C	Number of main pumps	02 nos.	02 nos. /	MR				
	D	Jockey pump out put	180 LPM	180 LPM	MR				
	E	Jockey pump head	70 M	70 M	MR				
ř	F	Standby pump out put	2250 LPM	2250 LPM	MR				
	G	Standby pump head	70 M	70 M	MR				
	Н	Auto starting /manual	Required	Provided	MR				
		stopping	5.00/ <b>4</b> 007500		#2등하기				
	I	Pump house access	Required	Provided	MR				
2	Terrace Level								
	A	Discharge of pump	N/A	N/A	N/A				
	В	Head of the pump	N/A	N/A	N/A				
	C	Power supply	N/A	N/A	N/A				
- 1	D	Auto starting of pump	N/A	N/A	N/A				

V3S East Centre Mall located at Plot No.12, District Centre, Lxmi Nagar, Delhi-110092.

CI	Underground tank capacity			
B	Draw-off connection	2,00,000 Liters	3,00,000 Liters	N/A
C	Fire service inlet	Required	Provided	0.000.101
D	Access to tank	Required		MR
I		Required	Provided	MR
5	Exit Signage:	50,000 liters	Provided	MR
6	Provision of Lifts:	Required	50,000 liters.	MR
	A Pressurization of lift shaft	- quired	Provided	MR
1	D   Ficasultation of ite	Required		
_	Communication: 11-	Required	Provided	MD
12	D   I ilelien S grounding	Required	Provided	MR
		Required	Provided	MR
7	Standby Power Supply:	Required	Provided	MR
18	Refuge Area:	Required	Provided	MR
1	A Total area	- coquired	Provided	MR
_	B Location	No.	TOVIDED	MR
19	Fire Control Room;	N/A	NVA	
**	A Detector system	N/A	N/A	N/A
	- I TOW SWITCH DOWN I	D	N/A	
	C   I'A System now i	Required	D	N/A
	D Dattery backup	Required	Provided	MR
••	E   Billidina C	Required	Provided	MR
20		Required	Provided	MR
**	Special Fire Protection systems for protection of special Piels	r Required	Provided	MR
_	protection of special Risks, if any:	1 Collinson c	Provided	MR
		Pane	ela   Tovided in	MR
	The Fire protection systems		all HT & LT Panels	MIK

Fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of above deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The NOC / FSC was issued vide letter no. F6/DFS/MS/NDZ/2021/461 dated 23.09.2021 renewal under rule 35 of the Delhi Fire

Signature of the Inspecting Officer Name: Yashwant Singh Meena Designation: ADO/Laxmi Nagar

Signature of the Inspecting Officer

Name: Sumesh Kumar Dua Designation: Dy.CFO/NDZ

CHOHO

tup for Sign. Pleasy