C-25



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-1 10001

No. F.6/DFS/MS/EH/2024/SZ/ 56 2

Dated: 13 /0 9 /2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of TACO BELL located at E-153, Ground Floor, Kalkaji Delhi 110019 in the building comprised of 03 tiers Basement, Ground plus Seven Upper floors owned/occupied by Unit of Burman Hospitality Pvt Ltd was issued FSC by this department vide letter F6/DFS/MS/EH/2021/SZ/383 dated 29/12/2021. The restaurant premise was reinspected by the officers concerned of this department on 04/09/2024 in the presence of Ms. Sheetal and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class- D "Assembly Building" and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13/09/2024 at New Delhi by

DIRECTOR DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police, Lic/Branch 1st Floor PS Defence Colony, New Delhi 110049 (Ref. MHA Portal ID 2024082112964 dated 21/08/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

- All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTION REPORT				
1	Name & Address of the Building	TACO PELL	Unit of Burman He	महोत्सव Sonitality P	
2		Ltd.) at Shop No	E-153, Kalkaji Delhi	110019	
3	Type of Occupancy	Group-D Assemb	oly Building.		
4	Building Comprised of	Basement, Ground Plus two upper floor (Restaurant running at ground floor only)			
5	Type of Case	Renewal	J: 1400	n P	
6	Details of Previous NOC	F6/DFS/MS/EH/2021/SZ/383 dated 29/12/2021			
7	Fire Safety Directives Letter No		C Part-IV		
	Date of Inspection	04/09/2024	magneth s		
8	Name of the Inspecting Officers	DO (South) & AI	OO (BCP)		
9	Name & Designation of Officers from the building side	Ms. Sheetal			
10	Year of construction	1985		_	
11	Applicant letter No.	1985 MHA Portal ID 2024082112964 dated 21/08/2024			
S. No.	Martin Company of the		and south a	1	
	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL/NBC Requirement	Provided at Site	Remark MR/NM	
1	Access to Building.	ं विश्ववाद्यायः	r polarinickopi. A		
708	Road width	Required	9m	MR	
	Gate width	N/A	Accessible from road	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of ex	its.	in the board of		
7.12	a) Number of Staircase	A4110411.13	F Number of up		
	➤ Upper floors.		N/A	N/A	
	Basement floor.		Other property	N/A	
AW	b) Width of Staircase		F Standoy Pur		
25/197	> Upper floors	N/A	N/A	N/A	
	➤ Basement floor	N/A	N/A	N/A	
	c) Protection of exits		Part part		
	➤ Fire check door	N/A	N/A	N/A	
	> Pressurization	N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	Required	One	MR	
50.7	e) Width of corridor	N/A	N/A	N/A	
	1) Door size	1.50 mtr x 2	1.50 mtr each	MR	
3	Compartmentation.	जुक्ती जुक्ती वर्गी (क)	Targette Table of The		
11	Fire check door.	N/A	N/A	N/A	
AW	Sealing of electrical shafts.	N/A	N/A	N/A	
AW.	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	• Fire dampers.	N/A	N/A	N/A	
4	Smoke Management system.		1071	IVA	
- 02#0		20 1 000-	avisino of Lifts.		
2.1	Basement	30 ACPH	N/A	N/A	
AM	• Upper floors	12 ACPH	N/A	N/A	
5	Fire Extinguishers.		 Communication 		
AU	Total numbers	06 Nos	06 Nos	MR	
J. David	Types	ABC/CO ₂	ABC & CO ₂	MR	
ACK	ISI Marking	ISI marked	Provided	MR	
6	First Aid Hose Reels.		27 F. 22 C	77 21	
11/1	Total numbers on each floor.	One	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	
7	Automatic fire detection & alarming syste	m. feater	- Department -		
- 1 - 1	Type of detectors	N/A	Provided	N/A	
	Location of Main Panel	N/A	Provided	N/A	





	A Lossian of D		_{सिक्र} अमृत	नहोत्सव
	Location of Repeater Panel Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	N/A	N/A	N/A
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System	N/A	NA	N/A
-	Basement	v ³ =mo l	American Par	
	Ground floor.	NA	Other property	NA
	Sprinkler above false ceiling	NA arrow	Provided	NA
11	Internal Hydrants.	N/A	N/A	N/A
	Size of Riser/Down-comer		de regeranta de	IVA
		100 mm	Provided	MR
	Number of Hydrant per floor Hose box.	One	Provided	MR
12	Yard Hydrants.	One	Provided	MR
100	C. I. Surreton reversity		F BY A SEA OF THE SEA	IVIK
	Total number of hydrants.	N/A	N/A	N/A
13	Hose box. Pumping and a second	N/A	N/A	N/A
Net .	Pumping arrangements.		Annual Control of	IN/A
110	Ground Level	Leave to	BIDGI M. T. W.	-
	Discharge of main pump.	N/A	N/A	N/A
	ricad of main pump.	N/A	N/A	N/A
	 Number of main pumps. Jockey Pump output. 	N/A	N/A	5000000
	> Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping.	N/A	N/A	N/A
	> Pump house access.	N/A	ALL THE PROPERTY ST	N/A
A LOS	Terrace Level	21/21	N/A	N/A
	Discharge of pump.	450 LPM	on Fine Joseph door	
MIK	➤ Head of pump.	450 LPM	Provided	MR
	➤ Power supply.	THE PERSON NAMED IN COLUMN	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	Required	Provided	MR
n da i	Underground tank capacity.	N//	muitalizantanana	
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	N/A	N/A	N/A
15	Exit Signage.	20,000 Ltrs	20,000 ltr	MR
16	Provision of Lifts.	Required	Provided	MR
Ψ				
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
17	Lift signage. Standby Power Servel	N/A	N/A	N/A
18	Standby Power Supply	N/A	N/A	N/A
10	Refuge Area	7	Jack Steel Have Regis.	7
	Total area	N/A	N/A	N/A
n A	• Location	N/A	N/A	N/A
19	Fire Control Room.		IVA	N/F
	Detector system panel.	N/A		-
	Flow switch panel.	TO THE REAL PROPERTY.	N/A	N/A
			TO STATE OF THE REST	



20	Battery backup. Building floor plan. Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A randomly checked	N/A
		N/A	N/A	NI/A
		N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
		NT/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found

Keeping in view of the deemed compliance of the minimum standard on fire prevention functional at the time of inspection. and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2021/SZ/383 dated 29/12/2021, renewal under rule 37 of the Delhi Fire Service

Accordingly, DFA is put up for approval and signature please. rules, 2010 is recommended.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

As approved, F.T. Letter in pritup for your signature BI.

uploaded