



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-1 10001

No.F.6 DFS/MS/School/2024/SZ/920

Dated: 20/09/2024

FIRE SAFETY CERTIFICATE

Certified that the Andhra Education Society Dr. K Ramesh Babu Memorial Sr. Sec. School located at Sector VII, Pushp Vihar, New Delhi 1100017 comprised of Basement (vacant), Ground plus Two upper floors only owned/occupied by Andhra Education Society issued was Safety Certificate by this department vide letter No. F6/MS/DFS/2003/2036 dated 12/12/2003. The said premises was re-inspected by officer concerned of this department on 17/09/2024 in presence of Mr. Ashwathi KE (HOS) of the school and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational Building Group -B" with effect from 20/09 / 2024 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on 20/09 2024 at New Delhi by

(ACUL GARG) DIRECTOR DELHI FIRE SERVICE

Copy to: -

 The Principal, Andhra Education Society Dr. K Ramesh Babu Memorial Sr. Sec. School located at Sector VII, Pushp Vihar, New Delhi 1100017.

2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi -54.

Conditions for the validity of Fire Safety Certificate:-

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



		ON REPORT	cation Society Dr K Par	nesh Dah	
ľ	Name & Address of the Building	M/s Andhra Education Society, Dr. K Ramesh Babu Memorial Sr. Sec. School, Sector -VII, Pushp Vihar New Delhi 110017 Educational, Group-B (School)			
2	Tyme of Occupancy				
3	Type of Occupancy	Basement, Ground plus two upper floor			
	Building Comprised of				
4	Type of Case Details of Previous NOC	F6/MS/DFS/2003/2036 dated 12/12/2003			
5		Nil			
6	Fire Safety Directives Letter No	17-09-2024			
7	Date of Inspection	DO (South)			
9	Name of the Inspecting Officers Name & Designation of Officers from the building side	Mr. Ashwathi KE (HOS)			
10	Year of construction	1997 COLG Dated 04/09/2024			
10		Outdoor diary no 6016 Dated 04/09/2024			
11 S. No	Applicant letter No. Minimum standards on Fire Prevention and Fire Safety U/R 33	As per old NOC Requirement	Provided at Site	MR/NMF	
			19 14 15 15 15 15 15 15 15 15 15 15 15 15 15	MR	
1	Access to Building.	6 mtr	Provided	Old case	
	Road width	4.5 mtr	Provided	-NA-	
	Gate width	-NA-	-NA-	-14/4-	
1 8 -	Width of internal road		or extend	-	
2	Number, width, type & arrangement of exits.			MR	
	a) Number of Staircase	04 Nos each	Provided		
	 Upper floors. Basement floor. 	01Nos	Provided	MR	
	b) Width of Staircase	1.50 mtr & 1.25 mtr	2 x 1.22 mtr & 2 x 1.50 mt	r MR	
1 V	> Upper floors > Basement floor	1.50 mtr	1.50 mtr	MR	
	Carles Carles		-NA-	-NA-	
	> Fire check door	-NA-	-NA-	-NA-	
51.00 I	> Pressurization	-NA-	II THINKS AND LESS	MR	
	d) No. of continuous staircase to terrace	02 No	Provided	-NA-	
		-NA-	or asknot-NA-own silign	14762	
	e) Width of corridor	1 m to aqui	Provided *	MR	
37)4	n Door size	0.03 3	grapi, Passa AL 6	274	
3	Compartmentation.	-NA-	-NA-	-NA-	
HII"	Fire check doof.	-NA-	-NA-	-NA-	
	Sealing of electrical shafts.	-NA-	-NA-	-NA-	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
215	Water curtain	-NA-	-NA-	-NA-	
-	Fire dampers.	THE PLANT	paragona many v		
4.	Smoke Management system.	NTA: (Cled)	-NA-	-NA-	
# V	Basement	-NA-	-NA-	-NA-	
T.	Upper floors	-NA-	dental alabert a		
	Fire Extinguishers.		Provided	MR	
5.	Total numbers	Required		MR	
W 10		ABC	ABC Type	MR	
Pille	Types Yel Madring	ISI mark	Provided	MIL	
	ISI Marking People	1	E38. III 1 P	MR	
6.	First Aid Hose Reels.	01 at each	Provided	MR	
	Total numbers on each floor.	Required	Provided		
	Length of hose-reel hose.	Required	Provided	MR	
	Nozzle Diameter Automatic fire detection & alarming system.				
			-NA-	-NA-	



	Location of Main Panel	-NA-		
o la	Location of Repeater Panel	-NA-	-NA-	-NA-
7.14	Alternate source of power		-NA-	-NA-
	Hooter's location	-NA-	-NA-	-NA-
8.	MOEFA	-NA-	-NA-	-NA-
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	-NA-	-NA-	-NA-
	Basement			-NA-
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.	-NA-	-NA-	-NA-
	Size of Riser/Down-comer	(2)	Photos -	IVA
	Number of Hadran	100mm	Provided	MR
	Number of Hydrant per floor Hose box.	Required	Provided	MR
12.	Yard Hydrants.	Required	Provided	MR
chile)				MIN
With	Total number of hydrants. Hose box.	-NA-	-NA-	-NA-
13.		-NA-	-NA-	-NA-
	Pumping arrangements. • Ground Level			TALL
	Discharge of			
	 Discharge of main pump. Head of main pump. 	-NA-	-NA-	-NA-
11.95	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	> Jockey Pump head.	-NA-	-NA-	-NA-
Heg.	Standby Pump output	-NA-	-NA-	-NA-
	Standby Pump head	-NA-	-NA-	-NA-
	Auto Starting / Manual Stopping	-NA-	-NA-	-NA-
	> Pump house access.	-NA-	-NA-	-NA-
	Terrace Level	-NA-	-NA-	-NA-
	Discharge of pump.	450 LPM		
	➤ Head of pump.	30m	Provided	MR
	➤ Power supply.	Required	Provided	MR
XIE.	Auto starting of pump.	Required	Provided Provided	MR
14.	Captive water storage for fire fighting.	7	Flovided	MR
	 Underground tank capacity. 	50,000 ltrs	Provided	100
	Draw-off connection.	Required	Provided	MR MR
	 Fire Service Inlet. Access to tank. 	Required	Provided	MR
	Overhead tank capacity.	Required	Provided	MR
15.	Exit Signage.	12,500 ltrs	Provided	MR
16.		Required	Provided	MR
	Pressurization of lift shaft.		TEXTORIA IVA	
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
21	Lift cianage	-NA-	-NA-	-NA-
17.		-NA-	-NA-	-NA-
18.	Refuge Area	-NA-	-NA-	-NA-
	Total area	NIA T		14
vige	Location	-NA-	-NA-	-NA-
19.		-NA-	man, dr. -NA-	-NA-
		40, 41 log	a la	
	Detector system panel.	-NA-		

-NA-	NA	I -NA-
-NA-		-NA-
-NA-	-NA-	-NA-
-NA-	-NA-	-NA-
-NA-	-NA-	-NA-
	-NA-	-NANA- -NANA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 213 dated 02/05/2024 & Basement is vacant. (photo enclosed)

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/MS/DFS/2003/2036 dated 2/12/2003, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Manoj Kumar Sharma Design: DO (South)

CFO (HQ)